

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: Smp 14020 Yr Regn: 04 16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Vezel c.c. 1496Colour: M. Brown A/C: Insured / Std / NI / NASp. Reading: 84189 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU1 1110593Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 215/60R16R: Dun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 6 mmL/Bal. 9 mm L/Bal. 6 mmD.O.A. 26/4/22 D.O.I. 5/5/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

10/6/21 By 8445d Cdn

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SMP 1402D
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

Estimate No: ES2290435
Date: 04 May 2022
Policy No: 5111879269-02
Veh Reg No: SMP1402D
Make/Model: HONDA VEZEL
1.5X CVT ABS

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 26/04/2022
TP Veh Reg No: SLV106X

NOT Authorised
11 Rmp @ 4450/-
Resurvey After Paint
5 days

Chassis No: RU11110593
Engine No: L15B4030596
Reg. Date: 04/04/2016

Estimate Repair Cost to Vehicle No :SMP1402D

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 FRONT BUMPER	801.70	1 PC	801.70	✓
2 FRONT BUMPER LOWER SIDE CHROME garnish	381.00	1 PC	381.00	✓
3 FRONT BUMPER REINFORCEMENT BRACKET	321.00	1 PC	321.00	✓
4 FRONT BUMPER SIDE RETAINER LH	17.00	1 PC	17.00	✓
5 FRONT BUMPER CLIP	3.80	6 PCS	22.80	✓
6 FRONT GRILLE BASE	301.60	1 PC	301.60	✓
7 HEADLAMP LH	1,999.30	1 PC	1,999.30	✓
8 FRONT GRILLE TOP MOULDING	75.00	2 PCS	150.00	✓
9 FRONT GRILLE TOP GARNISH	65.00	1 PC	65.00	x
10 FRONT GRILLE LOGO	24.10	1 PC	24.10	✓
11 FRONT GRILLE CLIP	3.80	6 PCS	22.80	✓
12 BONNET	854.60	1 PC	854.60	✓
13 BONNET INNER RUBBER	24.00	1 PC	24.00	x
14 FRT LH FENDER ARP GARNISH	153.00	1 PC	153.00	✓
15 AIR-CON CONDENSER	568.10	1 PC	568.10	x
			5,706.00	
		Less 20%	1,141.20	4,564.80
Labour				
16 TO REMOVE AND REFIX FRT BUMPER ASSY, GRILLE, HEADLAMPS, BONNET & ATTACHMENT; KNOCK AND REPAIR FRT SUPPORT PANEL, FRT LH FENDER AND RE-ALIGN TO SAME	700.00	1 LA	700.00	500
17 TO PUTTY AND RESPRAY ON FRT BUMPER, REINFORCEMENT, BONNET, FRT SUPPORT PANEL, FRT LH FENDER	800.00	1 LA	800.00	720
18 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	x
			1,600.00	1,600.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total S\$ 6,164.80
Add GST @ 7% 431.54
Total Amount Payable S\$ 6,596.34

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

Suppl

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department


Estimate No: ES2290435 /YISHUN
Date: 06 May 2022
Policy No: 5111879269-02
Veh Reg No: SMP1402D
Make/Model: HONDA ONDA VEZEL
1.5X CVT ABS
Chassis No: RU11110593
Engine No: L15B4030596
Reg. Date: 04/04/2016

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 26/04/2022
TP Veh Reg No: SLV106X

Estimate Repair Cost to Vehicle No :SMP1402D

Description	U/Price	Quantity	List Price <u>S\$</u>	Amount <u>S\$</u>
Supplementary 1				
List Price				
1 FRONT GRILLE OUTER COVER	301.20	1 PC	CM 301.20	—
2 BONNET LOCK BRACKET	38.70	1 PC	CM 38.70	—
3 HEADLAMP LOWER BRACKET	39.00	2 PC	CM 78.00	—
			417.90	
	Less 20%		83.58	334.32
	Total			S\$ 334.32
	GST Amount			S\$ 23.40
	Total Amount Payable			S\$ 357.72

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE