

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

29-Apr-22

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6841 P

1 pc	Front bumper X		\$	531.00
1 pc	Front bumper emblem X	NN	\$	44.00
1 pc	Front bumper o/s side retainer X	NN	\$	16.00
1 pc	Front n/s fender X Repair	NN	\$	384.00
1 pc	Front n/s fender inner shield X	NN	\$	120.00
1 pc	Front n/s door X Repair Buc	NN	\$	761.00
2 pcs	Front n/s door hinges @ \$34.00 X	NN	\$	68.00
1 pc	Rear n/s door X Repair	NN	\$	791.00
2 pcs	Rear n/s door hinges @ \$34.00 X	NN	\$	68.00
1 pc	n/s rocker panel garnish X Repair	NN	\$	286.00
1 pc	Front n/s wheel cover @ \$116.00 X	NN	\$	116.00
1 pc	Front n/s door outer handle X	NN	\$	40.00
1 pc	Rear bumper X	NN	\$	696.00
1 pc	Moulding assy front n/s door frame X	NN	\$	47.00
1 pc	Rear n/s fender X Repair	NN	\$	1,205.00
1 pc	Rear n/s fender inner shield X	NN	\$	212.00
1 pc	n/s side mirror X Repair	NN	\$	590.00
1 pc	Front n/s rim X	NN	\$	246.00
			\$	6,221.00
			Less 10%	\$ 622.10
			\$	5,598.90

S/NETT

1 set	Front bumper clips X	NN	\$	48.00
1 pc	Front n/s fender sticker /	MLC	\$	30.00
1 set	Front n/s fender inner shield clips X	NN	\$	28.00
1 set	n/s rocker panel garnish clips X	NN	\$	38.00
1 set	n/s door stickers /	NN	\$	100.00
1 pc	Rear n/s fender sticker /	NN	\$	60.00

29-Apr-22

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6841 P

Sundry	\$	50.00	X
To check wheel alignment	\$	80.00	X
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	60.
To dismantle / refit inner components of the front o/s door & rear o/s door into new shell door	\$	300.00	60.
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear n/s door etc.	\$	1,600.00	700
To putty and spray painting on front bumper, front n/s fender, front n/s door, rear n/s door, n/s rocker panel garnish, rear n/s fender, n/s mirror cover, rear bumper	\$	1,800.00	1000
To apply rustproofing on the repaired and replaced panels.	\$	120.00	X
	\$	16,876.00	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

5 Days .

Lumpsum repair

After repair photos.

Eno Qiang - 8288082

Eno Qiang @ lkk auto. com

5/5 /22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: