



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Ref: CS3/GAI21011265/Gty3e2-1 Date: 17/05/2022 Code: GAI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBJ 6754S	Veh. Inspected	SLP 111L	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVC000004073	Excess (\$)	0.00	
Assign From	ELIZABETH CHEW	Assign Date	27/04/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	AUDI A5 SPORTBACK 2.0	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WAUZZZ8T3BA010239	Colour	WHITE	
Odometer	126220 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	245/35 R19	YOKOHAMA	6 mm	
L/H Front Tyre	245/35 R19	YOKOHAMA	6 mm	
R/H Rear Tyre	245/35 R19	YOKOHAMA	6 mm	
L/H Rear Tyre	245/35 R19	YOKOHAMA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	29/10/2021	Inspection Date	05/11/2021	
Survey held at	1 STOP GARAGE PTE. LTD. 25 KAKI BUKIT ROAD 4 #01-52 SYNERGY @ KB SINGAPORE 417800			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	