

Claim Audit

AUDIT TRAIL			
No.	On	Audit	Remarks
1	26 Apr 2022 19:36	Clm Veh Model Changed	
2	26 Apr 2022 19:36	Clm Created	Reg No: SKR6707E. Policy No: 2100404089-07. Acct Date: 2022/03/29. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP0R224Q0001
3	04 May 2022 12:17	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.
4	04 May 2022 12:17	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)
5	04 May 2022 12:17	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):
6	04 May 2022 12:17	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/05/13
7	04 May 2022 12:17	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.
8	04 May 2022 12:17	Clm Registration Modified	Rep:1137->200611.
9	04 May 2022 12:17	Clm Veh Model Changed	(205448) AUDI A3 1.4 TFSI AMBIENTE MY 15 (A).
10	04 May 2022 12:18	Adj Adjuster Assigned	[None] -> XING GUO QIANG
11	04 May 2022 14:59	Clm Registration Modified	Init.Est.:->5,000 - 6,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.
12	04 May 2022 17:35	Adj Rpt Initiated	
13	04 May 2022 17:35	Clm Dtl Modified	Claim Conclusion: -> 3.
14	04 May 2022 17:35	Clm Dtl Modified	JPJ Reg. Date: -> 2015/02/27.
15	04 May 2022 17:35	Clm Details Notified	
16	05 May 2022 09:52	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/05/13
17	05 May 2022 09:52	Adj Mandate Request	Cur.Req:9253.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NO T AUTHORISE REPAIR.

By

[] Merimen Administrator

[I] Merimen Administrator

[] CELINE FONG

[] CELINE FONG

[A] CELINE FONG

[A] CELINE FONG

[A] CELINE FONG

[A] CELINE FONG

[A] CELINE FONG

[A] CELINE FONG

[I] Loo, Tong Shing

[A] Elaine Kuan Hwa Meen

[A] Elaine Kuan Hwa Meen

[A] Elaine Kuan Hwa Meen

[A] Elaine Kuan Hwa Meen

[A] SHIAU CHAN

[A] SHIAU CHAN

AUDIT TRAIL				
No.	On	Audit	Remarks	By
18	05 May 2022 16:49	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/05/13. Mandate Remarks: Vehicle may commence repair - To check Front Bumper condition upon dismantle Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photo	[I] Lim, Kok-Chong
19	05 May 2022 16:49	Adj Mandate Set	Approved:9253.00:Vehicle may commence repair - To check Front Bumper condition upon dismantle Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts req	[I] Lim, Kok-Chong

Date From



Date To



Audit Type

None



Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2789117	04 May 2022 17:35:51	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKR6707E		11.00