

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0342/2022/JT  
DATE : 27-Apr-22  
WIP : 21588

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/4/2022

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**Hi Guo Qiang,**

**4 days - ok - Jy - 1 Jul 22**

OWNER'S NAME : MR VENTAKACHELAM RAMAN  
ADDRESS : 100 GRANGE ROAD  
#15-1501  
SINGAPORE 249591  
TELEPHONE : HP +65 92991629  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 2100404089-07  
VEHICLE NO : **SKR 6707 E**  
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI  
MODEL YEAR : 27/02/2015  
ENGINE NO : CZC 233017  
CHASSIS NO : WAUZZZ8V7F1096484  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 29-Mar-22  
PLACE OF ACCIDENT : GRANGE ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

### ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKR 6707 E

| S/N                         | NATURE OF JOBS                                                                                                                                 |          | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|----------|----------------------|-------------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.                  | S/N \$   | 360.00               |                               |
| 2                           | TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                          | S/N \$   | 350.00               |                               |
| 3                           | TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$       | 2,100.00             | \$ 1,000.00                   |
| 4                           | TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.                                                                                                  | \$       | 2,000.00             | \$ 1,100.00                   |
| 5                           | TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.                                                                                          | S/N \$   | 280.00               |                               |
| 6                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                 | S/N \$   | 192.00               | \$ 192.00                     |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                | <b>:</b> | <b>\$ 5,282.00</b>   | <b>\$ 2,292.00</b>            |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKR 6707 E**

|                             |                                             |     | DAMAGED PARTS & PRICES |                    |
|-----------------------------|---------------------------------------------|-----|------------------------|--------------------|
| S/N                         | PARTS DESCRIPTION                           | QTY | S/NETT                 | REMARKS            |
| 1                           | FRONT BUMPER                                | 1   | \$ 2,377.00            |                    |
| 2                           | FRONT BUMPER FIXING PARTS                   | 1   | \$ 195.00              |                    |
| 3                           | FRONT BUMPER TRIM COVER - RH                | 1   | \$ 182.00              |                    |
| 4                           | FRONT BUMPER CLOSING ELEMENT - LOWER CENTER | 1   | \$ 175.00              |                    |
| 5                           | FRONT BUMPER PULL STRAP - LOWER             | 4   | \$ 231.00              |                    |
| 6                           | FRONT BUMPER GUIDE SECTION - RH             | 1   | \$ 43.00               |                    |
| 7                           | FRONT BUMPER AIR GUIDE GRILLE - RH          | 1   | \$ 122.00              |                    |
| 8                           | FRONT FENDER - RH                           | 1   | \$ 954.00              | \$ 763.20          |
| 9                           | FRONT FENDER ATTACHMENT PARTS               | 1   | \$ 75.00               |                    |
| 10                          | FRONT FENDER BRACKT - RH                    | 1   | \$ 46.00               |                    |
| 11                          | FRONT FENDER POP RIVET                      | 5   | \$ 19.00               | \$ 15.20           |
| 12                          | FRONT FENDER BRACE - RH                     | 1   | \$ 107.00              | \$ 85.60           |
| 13                          | FRONT WHEEL HOUSING LINER                   | 1   | \$ 183.00              |                    |
| 14                          | FRONT WHEEL HOUSING LINER ATTACHMENT PARTS  | 1   | \$ 93.00               |                    |
| 15                          | HEADLIGHT - RH                              | 1   | \$ 2,810.00            |                    |
| 16                          | ALUMINIUM RIM                               | 1   | \$ 1,303.00            |                    |
| 17                          | RUBBER VALVE                                | 1   | \$ 4.00                |                    |
| 18                          | LIFT CYLINDER - RH                          | 1   | \$ 211.00              |                    |
| 19                          | LIFT CYLINDER HOSE                          | 1   | \$ 204.00              |                    |
| 20                          | SUNDRIES                                    |     | \$ 300.00              | \$ 11.20           |
| <b>TOTAL SPARE PARTS</b>    |                                             | :   | <b>\$ 9,634.00</b>     | <b>\$ 875.20</b>   |
| <b>TOTAL LABOUR CHARGES</b> |                                             | :   | <b>\$ 5,282.00</b>     | <b>\$ 2,292.00</b> |
| <b>GRAND TOTAL</b>          |                                             | :   | <b>\$ 14,916.00</b>    | <b>\$ 3,167.20</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.  
 bl-28/06/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**NAME :**  
**SURVEYED DATE :**  
**AUTHORISED DATE :**  
**EXCESS COST :**  
**LIABILITY :**  
**REMARKS :**

**PLEASE NOTE :** THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT