

ASS. REC. BY:

REF:

105 / 220040851kq

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Zhang Cheng

of Blk 6 399J

Insured: 838i

Policy No. _____

Claims No. DMPC2200168H

Sum Insured: _____ Excess: 7


(Client's Record)

Make of Veh: _____

42506777 Jason Wilson

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$94K

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMV 1851 J Yr Regn: 02 19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Mazda 6 C.C. 1998

Colour: M.P. White A/C: Insured / Std / NI / NA

Sp. Reading: 60398 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6GL1072K0312511

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/RIm / STD A/RIm or

Tyre Size: F: 225/55R17
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear
R/Bal. <u>7</u> mm		R/Bal. <u>7</u> mm
L/Bal. <u>7</u> mm		L/Bal. <u>7</u> mm

D.O.A. 24/4/22 D.O.I. 4/5/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or cl's Prt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>4/5</u>	<u>FR bumper and headlamp doesn't look consistent.</u>
<u>23/5</u>	<u>LI Rep @ 2750L Carbur 2/6/22 (Aged \$8056.16, 75%)</u>
<u>2/6</u>	<u>MCSP ext for DV.</u>

Date/Time, File Pass to?

: Prell. Report

1) 03/6/2022

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trlp: _____

Survey Fee:

Transportation: _____
S + RS: _____

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

) Fuel (\$)

) Others (\$)

TOTAL

Report Format: MED-0D

Lump Sum / I.B.I. TS: 2750

Empty box for additional notes or calculations.

Zhong Cheng Enterprise Pte Ltd - Woodlands (Co.Reg.No:201611525M)
 BLK 6 WOODLANDS ROAD, 399J YEW TEE INDUSTRIAL ESTATE
 Singapore 678008
 Tel: 67694686 Email: zhongchengauto@gmail.com

INSURER: **ECICS Limited (HQ)**

PARTICULARS OF CLAIM			
Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	MPC21P00152400	Date of Loss:	24/04/2022
Vehicle Reg. No.:	SMV1851J	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NG SHU XUAN		
Driver:	NG SHU XUAN		
<hr/>			
Make/Model:	MAZDA 6, 2.0 (A)	Vehicle Reg. Date:	13/02/2019
Vehicle Colour:	White/Pearl		
Engine No:	PE21259652	Chassis No:	JM6GL1072K0312511
Odometer:	58960 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4 ✓		
Present Location:	ZHONG CHENG ENTERPRISE PTE LTD - WOODLANDS (HQ)		<i>Excess ??</i>

Not Notified
 L1 Rep @ 2750h
 Recovery After Repair
 Excess ??

COST OF CLAIMS	Amount
Parts	7,752.80
Miscellaneous Items	1,253.36
Labour	900.00
Paintwork Labour	900.00
Towing	0.00
Nett Amount (S\$)	10,806.16

This claim is handled by: TAN SINI

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Apr 2022)
Parts: 143 MAZDA 6 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Zhong Cheng Enterprise Pte Ltd - Woodlands/SMV1851J/30/04/2022 18:53
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		Bumper, front	✓	0.00	0.00	*950.00 F X
2	1		Fender LH, front	✓	0.00	0.00	*180.00 F X
3	1		Fender moulding LH, front	✓	0.00	0.00	*60.00 F X
4	1		Fender shield LH, front	✓	0.00	0.00	*55.00 F X
5	1		Headlamp LH	✓	0.00	0.00	*1,650.00 F X
6	1		*FRONT DOOR OUTER MOUNLDING LH	✓	0.00	0.00	*70.00 F X
7	1		*side panel skirting LH		0.00	0.00	*350.00 F ✓
8	1		*Bumper bracket LH, front	✓	0.00	0.00	*10.00 F X
9	1		*Bumper retainer, front	✓	0.00	0.00	*15.00 F X
10	1		Absorber LH, front	✓	0.00	0.00	*190.00 F X
11	1		Knuckle arm LH, front	✓	0.00	0.00	*185.00 F X
12	1		Lower arm LH, front	✓	0.00	0.00	*175.00 F X
13	1		Lower arm shaft LH, front	✓	0.00	0.00	*150.00 F X
14	1		Wheel hub bearing LH, front	✓	0.00	0.00	*230.00 F X
15	1		Door glass LH, front	CM	0.00	0.00	*365.00 F ✓
16	1		Door handle outer LH, front	✓	0.00	0.00	*150.00 F X
17	1		Door hinge lower LH, front	✓	0.00	0.00	*65.00 F ✓
18	1		Door hinge upper LH, front	✓	0.00	0.00	*65.00 F ✓
19	1		Door inner lock LH, front		0.00	0.00	*125.00 F ✓
20	1		Door LH, front	✓	0.00	0.00	*1,300.00 F ✓
21	1		Door regulator motor LH, front	✓	0.00	0.00	*105.00 F ✓
22	1		Door trim inner LH, front		0.00	0.00	*85.00 F ✓
23	1		Door view side mirror bracket LH	✓	0.00	0.00	*40.00 F ✓
24	1		Door view side mirror LH, front	✓	0.00	0.00	*400.00 F ✓
25	1		Door weatherstrip LH, front		0.00	0.00	*48.00 F X
26	1		Sticker LH, body	✓	0.00	0.00	*30.00 F ✓

F=Franchise part.

Sub Total (S\$) **7,048.00**
 + Margin on L,N Items 10.00% (S\$) 704.80

 Total Parts (S\$) **7,752.80**

Zhong Cheng Enterprise Pte Ltd - Woodlands/SMV1851J/30/04/2022 18:53. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	front tyre LH	<i>R</i> 230.00 <i>X</i>
2	1	GST	<i>MT</i> 493.36 <i>X</i>
3	1	tyre rim front LH	<i>R</i> 450.00 <i>X</i>
4	1	wheel alignment	50.00 ✓
5	1	wheel balancing	<i>rr</i> 30.00 <i>X</i>
Sub Total (S\$)			<u>1,253.36</u>

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	front and front LH portion	New	900.00 <i>60d</i>
<u>Labour Items</u>			
2	panel beating/dismantle and refix front/LH portions	New	900.00 <i>60d</i>
Gross Labour Cost (S\$)			<u>1,800.00</u>

Zhong Cheng Enterprise Pte Ltd - Woodlands/SMV1851J/30/04/2022 18:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >