

REF: SMR/ 220040891K4

ASSIGNMENT

金興(興)汽車私人有限公司
K. KIM HIN AUTO PTE LTD
160 Sin Ming Drive #02-18/19/20
Sin Ming AutoCity
Singapore 575722
Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Not Authorized
11 Sep 82400f
Penny After Rain
4day

Vehicle Insured : SG 5961 G
Accident Date : 27-Apr-2022

No. : 32337

Date : 29-Apr-2022

Our Ref : 021797 (SMRT) / SANDRA

PAGE : 1

BUKIT BATOK DRIVING CENTRE LTD
Singapore

ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.5 VTIR M/T ABS D(2017) SLL3464U

1 pc front bumper		mgc	538.10	✓
1 pc o/s front bumper side retainer		rd	10.40	✓
10 pcs front bumper clips	@ S\$ 3.80	mgc	38.00	✓
1 pc o/s front fender		rd	517.70	✓
1 pc o/s front inner shield		sm	107.80	✓
10 pcs o/s front inner shield clips	@ S\$ 3.80	mgc	38.00	✓
1 pc o/s front inner panel - outer		rd	109.40	X
1 pc o/s headlamp		mgc	1,216.80	✓
1 pc o/s headlamp lower bracket		sm	39.60	X
1 pc o/s front sport rim (original) 16"		rd	358.70	✓
1 pc o/s front lower arm		sm	178.50	X
1 pc o/s front knuckle arm		sm	146.20	X
1 pc o/s front knuckle arm bearing		sm	157.40	X
1 pc o/s front shock absorber		sm	338.20	X
1 pc o/s front shock absorber mounting		sm	32.60	X
1 pc o/s front shock absorber bearing		sm	42.20	X
1 pc o/s front shock absorber stopper		sm	25.20	X
1 pc o/s front stabilizer bar linkage		sm	65.60	X

3,960.40

Less 20% : -792.08

3,168.32

1 pc o/s front tyre 16"

See 180.00 sn

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Con't Page 2 ...

Acknowledged by Repairer

Signature:

Date:

MR/ 22004089/K/

ASSIGNMENT

4-32-C6Z5



Press any key to continue... vDos 2021.05.01 (vdos.info)

金興(興)汽車私人有限公司
K. KIM HIN AUTO PTE LTD
160 Sin Ming Drive #02-18/19/20
Sin Ming AutoCity
Singapore 575722
Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Vehicle Insured : SG 5961 G
Our Ref : 021797

Page : 2
No. : 32337

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

650.00 400

To apply undersealing

30.00 —

To dismantle and check front under-
carriages. To replace affected
portions.

na 180.00 X

To conduct front wheel alignment
test.

80.00 60

To putty and respray on affected
portions.

600.00 400

Total : S\$ 4,888.32

Singapore Dollars FOUR THOUSAND EIGHT HUNDRED
EIGHTY EIGHT AND CENTS THIRTY TWO Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.