

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.
Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 05 May 2022

Preliminary Advice

Vehicle No	: SNC3726M	Accident Date	: 28/04/2022
Make	: AUDI A4	Policy No.	: 7210123870
Assignment Date	: 04/05/2022	Excess	: S\$100.00
Date of Inspection	: 29/04/2022	Est. Duration of Repair	: 35
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 120,623.00
Revised Amount	:S\$ 78,119.00
Check Items (Estimated)	:S\$ 16,629.00
Total	:S\$ 94,748.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$ 240,013.00
Pre-Accident Value	:S\$ 185,000.00
COE / PARF Rebate	:S\$ 93,225.00
Salvage Value	:S\$

Margin for Repair (New for Old Value) :S\$ 146,788.00

Margin for Repair (Pre-Accident Value) :S\$ 91,775.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.