

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

Xiao Chan.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0350/2022/JT
1-Jun-22
CHANG
1 of 1
SNC 3726 M
AUDI A4 2.0 TFSI

Quantity	Description	Unit Price	Amount
Parts			
1	ROUND CONNECTOR HSG WITH CABLE <i>cracked</i>	\$ 290.00	✓
2	VENT TRIM <i>dehmed</i>	\$ 75.00	✓
3	BASS LOUDSPEAKER <i>cracked</i>	\$ 158.00	✓
4	REAR DOOR WINDOW GUIDE - LH <i>torn</i>	\$ 501.00	✓
GRAND TOTAL		\$ 1,024.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
01/06/22.

Resurveyed.

Additional 05 Days. for
replacement of item 42, 43.

[Signature]

Car in

10/5/22

wip: 21987

PREMIUM AUTOMOBILES

Kiam/Hong



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 3726 M

HIG- Adrian - 35 days

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Rehd</i>	1	\$ 2,493.00	✓
2	REAR BUMPER FIXING PARTS <i>Not Nec</i>	1	\$ 173.00	✓
3	REAR BUMPER SECURING STRIP <i>Nec</i>	1	\$ 125.00	✓
4	REAR BUMPER SECURING STRIP - UPPER <i>Nec</i>	1	\$ 249.00	✓
5	REAR BUMPER SPOILER <i>Rehd</i>	1	\$ 276.00	✓
X 6	REAR BUMPER BRACKET - LH / RH ?	2	\$ 456.00	?
7	REAR LIGHT REFLECTOR INNER - LH / RH ?	2	\$ 96.00	?
8	REAR LIGHT REFLECTOR OUTER - LH / RH ?	2	\$ 96.00	?
9	TAIL LIGHT OUTER - LH / RH <i>RH crubd</i>	2	\$ 2,270.00	1135
10	TAIL LIGHT OUTER TRIM - LH / RH <i>RH ut</i>	2	\$ 68.00	34
11	TAIL LIGHT INNER - LH / RH <i>RH ut</i>	2	\$ 2,270.00	1135
12	TAIL LIGHT INNER TRIM - LH / RH <i>RH ut, LH Ma</i>	2	\$ 68.00	34
13	REAR BUMPER REINFORCEMENT BEAM ?	1	\$ 1,131.00	?
14	REAR BUMPER SEAL ?	2	\$ 32.00	?
15	REAR BUMPER GUIDE SECTION LOWER - LH / RH <i>RH Dng</i>	2	\$ 100.00	50
16	REAR BUMPER GUIDE SECTION UPPER - LH / RH <i>crubd</i>	2	\$ 52.00	✓ <i>88.5</i>
17	GUIDE SECTION PIN <i>crubd</i>	1-2	\$ 6.00	✓ <i>88.5</i>
18	REAR BUMPER HOLDING STRAP - LH / RH <i>Best</i>	2	\$ 188.00	94 <i>88.5</i>
19	REAR PARKING AID SENSOR - INNER / OUTER <i>at m</i>	4	TBC	*
20	REAR PARKING AID SENSOR SEAL RING ?	4	\$ 10.00	?
SUB TOTAL SPARE PARTS			\$ 10,159.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 3726 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR BUMPER WIRING SET <i>new</i>	1	\$ 449.00	X.
22	BOOT LID OPENING CONTROL UNIT <i>new</i>	1	\$ 454.00	X
23	BOOTLID OPENING SENSOR LINE <i>new</i>	1	\$ 228.00	X
24	CONTROL UNIT RETAINER <i>new</i>	1	\$ 9.00	X.
25	REAR PACKING ADHESIVE <i>new</i>	1	\$ 21.00	✓
26	REAR LID FLAP GASKET <i>new</i>	1	\$ 229.00	✓
27	AUDI EMBLEM <i>new</i>	1	\$ 144.00	✓
28	A4 EMBLEM <i>new</i>	1	\$ 104.00	✓
29	TAILGATE CHROME TRIM STRIP - CENTER <i>new</i>	1	\$ 272.00	✓
30	REAR SIDE PANEL FRAME - LH <i>Distorted</i>	1	\$ 3,199.00	✓
31	REAR FENDER - RH <i>Distorted</i>	1	\$ 4,357.00	✓
32	GROMMET <i>new</i>	2	\$ 4.00	✓
33	BLIND RIVET STUD <i>new</i>	2	\$ 20.00	✓
34	REAR WINDSCREEN <i>new</i>	1	\$ 1,287.00	✓
35	REAR QUARTER GLASS - LH / RH <i>new</i>	2	\$ 1,460.00	✓
36	PRIMER <i>new</i>	3	\$ 66.00	✓
37	FUEL INSERT <i>Not new</i>	1	\$ 100.00	X.
38	REAR WHEEL HOUSING OUTER PANEL - LH <i>Dented</i>	1	\$ 687.00	✓
39	C PILLAR REINFORCEMENT INNER - LH LOWER <i>Dented</i>	1	\$ 220.00	✓
40	B-PILLAR INNER - LH <i>Dented</i>	1	\$ 607.00	✓
SUB TOTAL SPARE PARTS			\$ 13,917.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 3726 M

					DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT			REMARKS	
41	B-PILLAR REINFORCEMENT INNER - LH Distorted	1	S	446.00	✓	J.H.S.	
42	SIDE PANEL FRAME CLOSING ELEMENT INNER - LH Bented	1	S	604.00	✓		
43	SIDE MEMBER REINFORCEMENT LOWER INNER - LH Bented	1	S	394.00	✓		
44	REAR WHEEL HOUSING LINER - LH Bented	1	S	260.00	✓		
45	PICTOGRAM STICKER New	1	S	27.00	✓		
46	REAR DOOR - LH Distorted	1	S	3,431.00	✓		
47	REAR DOOR OUTER SEAL - LH New	1	S	229.00	✓		
48	BONDING AGENT ?	1	S	51.00	?		
49	CLEANING SOLUTION ?	1	S	74.00	?		
50	APPLICATOR ?	1	S	8.00	?		
51	REAR DOOR SEALING STRIP New	1	S	19.00	+		
52	REAR DOOR ATTACHMENT PARTS New	1	S	943.00	+		
53	REAR DOOR CATCH - LH Bented	1		TBC	✓		
54	REAR DOOR SEAL INNER - LH New Bented	1	S	247.00	✓		
55	REAR DOOR HINGE - LEFT UPPER	1		TBC	✓		
56	REAR DOOR HINGE HALVES - LEFT UPPER	1		TBC	✓		
57	REAR DOOR HINGE HALVES - LEFT LOWER } Damrd	1		TBC	✓		
58	REAR DOOR HINGE - LEFT LOWER	1		TBC	✓		
59	REAR DOOR HANDLE TRIM PLATE - LH New	1	S	98.00	+		
60	REAR DOOR HOUSING - LH } New	1	S	9.00	+		
61	REAR DOOR HANDLE COVER - LH	1	S	7.00	+		
SUB TOTAL SPARE PARTS				:	\$	6,847.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 3726 M

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
61	REAR DOOR HANDLE SENSOR - LH <i>new</i>	1	\$	255.00	x
62	REAR DOOR HANDLE ,EXTERIOR - LH <i>new</i>	1	\$	47.00	x
63	LH DOOR HANDLE UNDERLAY - FRONT / REAR <i>new</i>	2	\$	8.00	x
64	REAR DOOR MOUNTING BAR - LH <i>new</i>	1		TBC	x
65	REAR DOOR LOCK - LH	1	\$	630.00	
66	REAR DOOR STRIKER <i>new</i>	1	\$	77.00	x
67	REAR DOOR INNER PANEL COVER - LH <i>new</i>	1	\$	37.00	x
68	REAR DOOR LOCK BOWDEN CABLE - LH <i>new</i>	1	\$	43.00	x
69	REAR DOOR GUIDE TRIM STRIP - LH <i>new</i>	1	\$	265.00	✓ <i>88/s</i>
70	REAR DOOR GLASS APERTURE SEAL - LH INNER <i>new</i>	1	\$	125.00	x
71	REAR DOOR GLASS GUIDE RAIL - LH ?	1	\$	79.00	?
72	BLACK GLOSSY C-PILLAR TRIM - LH OUTER ? <i>new</i>	1	\$	159.00	x
73	BLACK GLOSSY B-PILLAR TRIM - LH OUTER <i>new</i>	1	\$	167.00	✓
74	REAR DOOR WINDOW SLOT SEAL TRIM STRIP - LH <i>new</i>	1	\$	410.00	✓ <i>88/s</i>
75	REAR DOOR WINDOW REGULATOR - LH <i>new</i>	1	\$	305.00	✓
76	REAR DOOR WINDOW REGULATOR WITH MOTOR - LH ?	1	\$	371.00	?
77	REAR DOOR WINDOW CONTROL UNIT ?	1	\$	840.00	?
78	REAR DOOR BOARD - LH INNER ?	1	\$	2,471.00	?
79	REAR DOOR TRIM PANEL WIRE HARNESS <i>new</i>	1	\$	328.00	x
80	REAR DOOR WIRING SET - LH <i>new</i>	1	\$	587.00	✓ <i>88/s</i>
SUB TOTAL SPARE PARTS			:	\$	7,204.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 3726 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
81	FRONT DOOR - LH <i>Distorted</i>	1	\$	3,431.00	✓
82	FRONT DOOR OUTER SEAL - LH	1	\$	229.00	✓
83	BONDING AGENT	1	\$	51.00	?
84	CLEANING SOLUTION	1	\$	74.00	?
85	APPLICATOR	1	\$	8.00	?
86	FRONT DOOR ATTACHMENT PARTS <i>new</i>	1	\$	1,153.00	x
87	FRONT DOOR CATCH - LH	1		TBC	?
88	FRONT DOOR SEAL INNER - LH	1	\$	229.00	f
89	FRONT DOOR HANDLE TRIM PLATE - LH	1	\$	98.00	x
90	FRONT DOOR HOUSING - LH	1	\$	9.00	f
91	FRONT DOOR COVER - LH	1	\$	7.00	x
92	FRONT DOOR MOUNTING BAR - LH	1		TBC	x
93	FRONT DOOR WINDOW GUIDE - LH	1	\$	501.00	2
94	FRONT DOOR WINDOW GUIDE TRIM STRIP - LH <i>Distorted</i>	1	\$	287.00	2
95	GLOSSY BLACK B-PILLAR TRIM - LH OUTER <i>new</i>	1	\$	256.00	✓
96	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - LH	1	\$	344.00	?
97	FRONT DOOR WINDOW REGULATOR - LH	1	\$	305.00	?
98	FRONT DOOR WINDOW REGULATOR WITH MOTOR - LH	1	\$	345.00	?
99	FRONT DOOR CONTROL UNIT - LH <i>new</i>	1	\$	672.00	x
100	FRONT DOOR BOARD - LH INNER	1	\$	2,945.00	?
SUB TOTAL SPARE PARTS			:	\$ 10,944.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 3726 M

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
101	FRONT DOOR SILL TRIM STRIP - LH <i>NR</i>	1 S	687.00	✓
102	SEAT AIRBAG UNIT - LH <i>NR</i>	1 S	1,688.00	✓
103	CURTAIN AIRBAG UNIT - LH / RH	2 S	4,138.00	✓
104	AIRBAG CONTROL UNIT	1 S	2,364.00	✓
105	REAR AIRBAG CRASH SENSOR	2	TBC	✓
106	CENTRAL PROTECTION FUSE	1 S	590.00	✓
107	ROOF LINER <i>crumpled</i>	1 S	2,339.00	✓
108	A-PILLAR TRIM UPPER - LH / RH - INNER <i>?</i>	2 S	458.00	?
109	B-PILLAR TRIM UPPER - LH / RH - INNER <i>?</i>	2 S	520.00	?
110	C-PILLAR TRIM - LH / RH - INNER <i>?</i>	2 S	508.00	?
111	D-PILLAR TRIM - LH / RH - INNER <i>?</i>	2 S	508.00	?
112	B-PILLAR TRIM LOWER - LH INNER <i>del</i>	1 S	171.00	✓
113	WHEEL HOUSING TRIM LOWER - LH INNER <i>?</i>	1 S	166.00	?
114	FRONT GRAB HANDLE - LH / RH <i>?</i>	2	TBC	?
115	REAR GRAB HANDLE - LH / RH <i>?</i>	2	TBC	?
116	FRONT SEAT BELT - LH / RH <i>Activated</i>	2 S	2,454.00	✓
117	FRONT SEAT BELT HEIGHT ADJUSTER - LH / RH <i>?</i>	2 S	383.00	?
118	FRONT PASSENGER SEAT BACKREST COVER - LH <i>for</i>	1 S	3,409.00	✓
119	UTR CAMERA <i>?</i>	1	TBC	?
120	UTR CAMERA WIRING SET <i>?</i>	1	TBC	?
SUB TOTAL SPARE PARTS		:	\$ 20,383.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 3726 M

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
121	FOAM TUBE ?	3	\$	21.00	?
122	FLAT CONTACT HOUSING ?	1	\$	11.00	?
123	FLAT CONTACT HOUSING ?	2	\$	35.00	?
124	RETAINING HOSE ?	1		TBC	
125	ALUMINIUM RIM <i>cut</i>	2	\$	2,584.00	✓
126	RUBBER VALVE <i>new</i>	2	\$	8.00	+
127	EXHAUST TAIL PIPE TRIM - LH / RH <i>RH Bent</i>	2	\$	766.00 383.	
128	ARYLIC SEALANT ?	S/N	\$	180.00	✓
129	CAVITY WAX	S/N	\$	140.00	✓
130	STONE CHIP <i>new</i>	S/N	\$	18.00	✓
131	METAL FILLER POWDER	S/N	\$	280.00	✓
132	REAR WINDSCREEN SEALANT <i>new</i>	S/N	\$	200.00	✓
133	1/4 GLASS SEALANT	S/N	\$	200.00	✓
134	SUNDRIES ?		\$	1,000.00	?
TOTAL SPARE PARTS		:	\$	74,897.00	
TOTAL LABOUR CHARGES		:	\$	45,564.00	
GRAND TOTAL		:	\$	120,461.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNC 3726 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
8	TO DISMANTLE AND REINSTALL CENTER CONSOLE. RENEW AIRBAG CONTROL UNIT AND BOTH FRONT SEATBELT, ROOF LINING, BOTH CURTAIN AIRBAGS AND LHS FRONT SEAT AIRBAG.	S/N \$ 3,200.00 ✓	
9	TO REMOVE AND RENEW LHS FRONT SEAT BACKREST COVER.	S/N \$ 780.00 ✓	
10	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS. AND FUSE TRAYS.	S/N \$ 1,800.00 ✓	
11	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 700.00 560	
12	TO SETUP THE VEHICLE ON CAR O-LINER TO FACILITATE THE REPAIR.	S/N \$ 2,400.00 ✓	
13	TO DISMANTLE AND RENEW REAR BUMPER, LHS REAR DOOR AND LHS FRONT DOOR. TO REPAIR RHS REAR DOOR, REAR LID AND REAR END PANELLING. TO CUT OUT AND WELD BOTH REAR FENDERS, LHS REAR END PANELLING. TO CUT OUT AND WELD BOTH REAR FENDERS, LHS REAR WHEEL HOUSING OUTER, LHS REAR SIDE PANEL REINFORCEMENT, LHS SILL PANEL REINFORCEMENT, LHS B-PILLAR REINFORCEMENT, LHS SILL PANEL AND LHS B-PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 18,000.00 8500 + 1000 ✓	
14	TO RESPRAY REAR BUMPER, REAR LID, BOTH REAR FENDERS, LHS REAR DOOR, LHS FRONT DOOR, DOOR HANDLES, HINGES, RHS REAR DOOR, BOTH SILL PANEL, BOTH ROOF CHANNEL, BOTH DOOR ENTRANCES, BOTH DRAIN CHANNEL, LHS B-PILLAR AND REAR END PANELLING.	\$ 12,000.00 6350. Handle: 100. Hinge: 200. 6350 + 1100 ✓	
SUB TOTAL LABOUR CHARGES		\$ 38,880.00	

Fender x 2 = 5700
 Boot
 Door x 3.
 Bumper
 B-Pillar
 11 Pieces.