

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0350/2022/JT
DATE : 29-Apr-22
WIP : 21987

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/4/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LIM SZE YI ANDY
ADDRESS : BLK 2 SHANGHAI ROAD
#04-14 RV EDGE
SINGAPORE 248209
TELEPHONE : HP +65 97619000
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210123870
VEHICLE NO : **SNC 3726 M**
MODEL CODE : AUDI A4 2.0 TFSI S TRONIC
MODEL YEAR : 15/10/2021
ENGINE NO : DEM 032752
CHASSIS NO : WAUZZZF46MA071650
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Apr-22
PLACE OF ACCIDENT : ALONG AYE TOWARDS TUAS
BEFORE EXIT 7A



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNC 3726 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00 ✓	
2	TO RENEW REAR WINDSCREEN AND BOTH 1/4 GLASS TO FACILITATE RENEWAL OF BOTH REAR FENDERS.	S/N \$ 900.00 ✓	
3	TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN.	S/N \$ 200.00 150 ✓	
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND BOTH 1/4 GLASS.	S/N \$ 400.00 ✓	
5	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.	S/N \$ 800.00 ✓	
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGES AND RENEW WHERE NECESSARY.	S/N \$ 1,400.00 ✓	
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN ATRRAG, ETC.	S/N \$ 1,400.00 ✓	
SUB TOTAL LABOUR CHARGES		: \$ 5,460.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNC 3726 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
8	TO DISMANTLE AND REINSTALL CENTER CONSOLE. RENEW AIRBAG CONTROL UNIT AND BOTH FRONT SEATBELT, ROOF LINING, BOTH CURTAIN AIRBAGS AND LHS FRONT SEAT AIRBAG.	S/N \$ 3,200.00 ✓	
9	TO REMOVE AND RENEW LHS FRONT SEAT BACKREST COVER.	S/N \$ 780.00 ✓	
10	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS. AND FUSE TRAYS.	S/N \$ 1,800.00 ✓	
11	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 700.00 ✓	560
12	TO SETUP THE VEHICLE ON CAR O-LINER TO FACILITATE THE REPAIR.	S/N \$ 2,400.00 ✓	
13	TO DISMANTLE AND RENEW REAR BUMPER, LHS REAR DOOR AND LHS FRONT DOOR. TO REPAIR RHS REAR DOOR, REAR LID AND REAR END PANELLING. TO CUT OUT AND WELD BOTH REAR FENDERS, LHS REAR END PANELLING. TO CUT OUT AND WELD BOTH REAR FENDERS, LHS REAR WHEEL HOUSING OUTER, LHS REAR SIDE PANEL REINFORCEMENT, LHS SILL PANEL REINFORCEMENT, LHS B-PILLAR REINFORCEMENT, LHS SILL PANEL AND LHS B-PILLAR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 18,000.00 ✓	8500
14	TO RESPRAY REAR BUMPER, REAR LID, BOTH REAR FENDERS, LHS REAR DOOR, LHS FRONT DOOR, DOOR HANDLES, HINGES, RHS REAR DOOR, BOTH SILL PANEL, BOTH ROOF CHANNEL, BOTH DOOR ENTRANCES, BOTH DRAIN CHANNEL, LHS B-PILLAR AND REAR END PANELLING.	\$ 12,000.00 ✓	6350 10 x 550 = 6500 Handle : 100 Hinge : 200 6350
SUB TOTAL LABOUR CHARGES		: \$ 38,880.00	

Fender x 2 = 57 pieces
 Boot
 Door x 3
 Bumper
 B-Pillar
 } 11 Pieces.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNC 3726 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
15	TO RENEW BOTH REAR RIMS. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 560.00	28 320
16	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	X
17	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 45,564.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 3726 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>Dehd</i>	1	\$ 2,493.00	✓	
2	REAR BUMPER FIXING PARTS <i>Nec</i>	1	\$ 173.00	X	
3	REAR BUMPER SECURING STRIP <i>Nec</i>	1	\$ 125.00	✓	
4	REAR BUMPER SECURING STRIP - UPPER <i>Nec</i>	1	\$ 249.00	✓	
5	REAR BUMPER SPOILER <i>Dehd</i>	1	\$ 276.00	✓	
6	REAR BUMPER BRACKET - LH / RH ?	2	\$ 456.00	?	
7	REAR LIGHT REFLECTOR INNER - LH / RH ?	2	\$ 96.00	?	
8	REAR LIGHT REFLECTOR OUTER - LH / RH ?	2	\$ 96.00	?	
9	TAIL LIGHT OUTER - LH / RH <i>RH cracked</i>	2	\$ 2,270.00	1135	
10	TAIL LIGHT OUTER TRIM - LH / RH <i>RH cut</i>	2	\$ 68.00	34	
11	TAIL LIGHT INNER - LH / RH <i>RH cut</i>	2	\$ 2,270.00	1135	
12	TAIL LIGHT INNER TRIM - LH / RH <i>RH cut, LH MA</i>	2	\$ 68.00	34	
13	REAR BUMPER REINFORCEMENT BEAM ?	1	\$ 1,131.00	?	
14	REAR BUMPER SEAL ?	2	\$ 32.00	?	
15	REAR BUMPER GUIDE SECTION LOWER - LH / RH <i>RH Dehd</i>	2	\$ 100.00	50	
16	REAR BUMPER GUIDE SECTION UPPER - LH / RH ?	2	\$ 52.00	?	
17	GUIDE SECTION PIN ?	2	\$ 6.00	?	
18	REAR BUMPER HOLDING STRAP - LH / RH ?	2	\$ 188.00	?	
19	REAR PARKING AID SENSOR - INNER / OUTER <i>2 m</i>	4	TBC	+	
20	REAR PARKING AID SENSOR SEAL RING ?	4	\$ 10.00	?	
SUB TOTAL SPARE PARTS		:	\$ 10,159.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 3726 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	REAR BUMPER WIRING SET <i>Not m</i>	1	\$ 449.00	X.	
22	BOOT LID OPENING CONTROL UNIT <i>Not m</i>	1	\$ 454.00	X	
23	BOOTLID OPENING SENSOR LINE <i>Not m</i>	1	\$ 228.00	X	
24	CONTROL UNIT RETAINER <i>Not m</i>	1	\$ 9.00	X.	
25	REAR PACKING ADHESIVE <i>Not m</i>	1	\$ 21.00	✓	
26	REAR LID FLAP GASKET <i>Not m</i>	1	\$ 229.00	✓	
27	AUDI EMBLEM <i>Not m</i>	1	\$ 144.00	✓	
28	A4 EMBLEM <i>Not m</i>	1	\$ 104.00	✓	
29	TAILGATE CHROME TRIM STRIP - CENTER <i>Not m</i>	1	\$ 272.00	✓	
30	REAR SIDE PANEL FRAME - LH <i>Distorted</i>	1	\$ 3,199.00	✓	
31	REAR FENDER - RH <i>Distorted</i>	1	\$ 4,357.00	✓	
32	GROMMET <i>Not m</i>	2	\$ 4.00	✓	
33	BLIND RIVET STUD <i>Not m</i>	2	\$ 20.00	✓	
34	REAR WINDSCREEN	1	\$ 1,287.00	✓	
35	REAR QUARTER GLASS - LH / RH <i>Not m</i>	2	\$ 1,460.00	✓	
36	PRIMER <i>Not m</i>	3	\$ 66.00	✓	
37	FUEL INSERT <i>Not m</i>	1	\$ 100.00	X.	
38	REAR WHEEL HOUSING OUTER PANEL - LH <i>Distorted</i>	1	\$ 687.00	✓	
39	C PILLAR REINFORCEMENT INNER - LH LOWER <i>Distorted</i>	1	\$ 220.00	✓	
40	B-PILLAR INNER - LH <i>Distorted</i>	1	\$ 607.00	✓	
SUB TOTAL SPARE PARTS			\$ 13,917.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 3726 M
DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	B-PILLAR REINFORCEMENT INNER - LH <i>Distorted</i>	1	\$ 446.00	✓
42	SIDE PANEL FRAME CLOSING ELEMENT INNER - LH ?	1	\$ 604.00	?
43	SIDE MEMBER REINFORCEMENT LOWER INNER - LH ?	1	\$ 394.00	?
44	REAR WHEEL HOUSING LINER - LH <i>Del</i>	1	\$ 260.00	✓
45	PICTOGRAM STICKER <i>new</i>	1	\$ 27.00	✓
46	REAR DOOR - LH <i>Distorted</i>	1	\$ 3,431.00	✓
47	REAR DOOR OUTER SEAL - LH <i>new</i>	1	\$ 229.00	✓
48	BONDING AGENT ?	1	\$ 51.00	?
49	CLEANING SOLUTION ?	1	\$ 74.00	?
50	APPLICATOR ?	1	\$ 8.00	?
51	REAR DOOR SEALING STRIP <i>new</i>	1	\$ 19.00	+
52	REAR DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 943.00	+
53	REAR DOOR CATCH - LH ?	1	TBC	?
54	REAR DOOR SEAL INNER - LH <i>new</i>	1	\$ 247.00	+
55	REAR DOOR HINGE - LEFT UPPER	1	TBC	✓
56	REAR DOOR HINGE HALVES - LEFT UPPER	1	TBC	✓
57	REAR DOOR HINGE HALVES - LEFT LOWER } <i>Distorted</i>	1	TBC	✓
58	REAR DOOR HINGE - LEFT LOWER	1	TBC	✓
59	REAR DOOR HANDLE TRIM PLATE - LH <i>new</i>	1	\$ 98.00	+
60	REAR DOOR HOUSING - LH } <i>new</i>	1	\$ 9.00	+
61	REAR DOOR HANDLE COVER - LH	1	\$ 7.00	+
SUB TOTAL SPARE PARTS		:	\$ 6,847.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 3726 M

				DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT		REMARKS	
61	REAR DOOR HANDLE SENSOR - LH <i>new</i>	1	\$	255.00	x	
62	REAR DOOR HANDLE ,EXTERIOR - LH <i>new</i>	1	\$	47.00	x	
63	LH DOOR HANDLE UNDERLAY - FRONT / REAR <i>new</i>	2	\$	8.00	x	
64	REAR DOOR MOUNTING BAR - LH <i>new</i>	1		TBC	x	
65	REAR DOOR LOCK - LH	1	\$	630.00		
66	REAR DOOR STRIKER <i>new</i>	1	\$	77.00	x	
67	REAR DOOR INNER PANEL COVER - LH <i>new</i>	1	\$	37.00	x	
68	REAR DOOR LOCK BOWDEN CABLE - LH <i>new</i>	1	\$	43.00	x	
69	REAR DOOR GUIDE TRIM STRIP - LH ?	1	\$	265.00	?	
70	REAR DOOR GLASS APERTURE SEAL - LH INNER <i>new</i>	1	\$	125.00	x	
71	REAR DOOR GLASS GUIDE RAIL - LH ?	1	\$	79.00	?	
72	BLACK GLOSSY C-PILLAR TRIM - LH OUTER <i>new</i>	1	\$	159.00	x	
73	BLACK GLOSSY B-PILLAR TRIM - LH OUTER <i>new</i>	1	\$	167.00	✓	
74	REAR DOOR WINDOW SLOT SEAL TRIM STRIP - LH <i>new</i>	1	\$	410.00	x	
75	REAR DOOR WINDOW REGULATOR - LH ?	1	\$	305.00	?	
76	REAR DOOR WINDOW REGULATOR WITH MOTOR - LH ?	1	\$	371.00	?	
77	REAR DOOR WINDOW CONTROL UNIT ?	1	\$	840.00	?	
78	REAR DOOR BOARD - LH INNER ?	1	\$	2,471.00	?	
79	REAR DOOR TRIM PANEL WIRE HARNESS <i>new</i>	1	\$	328.00	x	
80	REAR DOOR WIRING SET - LH <i>new</i>	1	\$	587.00	x	
SUB TOTAL SPARE PARTS			:	\$ 7,204.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 3726 M

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
81	FRONT DOOR - LH <i>Distorted</i>	1	\$ 3,431.00	✓	
82	FRONT DOOR OUTER SEAL - LH	1	\$ 229.00	✓	
83	BONDING AGENT	1	\$ 51.00	?	
84	CLEANING SOLUTION	1	\$ 74.00	?	
85	APPLICATOR	1	\$ 8.00	?	
86	FRONT DOOR ATTACHMENT PARTS <i>Ken</i>	1	\$ 1,153.00	X	
87	FRONT DOOR CATCH - LH	1	TBC	?	
88	FRONT DOOR SEAL INNER - LH	1	\$ 229.00	f	
89	FRONT DOOR HANDLE TRIM PLATE - LH	1	\$ 98.00	X	
90	FRONT DOOR HOUSING - LH	1	\$ 9.00	X	
91	FRONT DOOR COVER - LH	1	\$ 7.00	f	
92	FRONT DOOR MOUNTING BAR - LH	1	TBC	X	
93	FRONT DOOR WINDOW GUIDE - LH	1	\$ 501.00	?	
94	FRONT DOOR WINDOW GUIDE TRIM STRIP - LH	1	\$ 287.00	?	
95	GLOSSY BLACK B-PILLAR TRIM - LH OUTER <i>Ken</i>	1	\$ 256.00	X	
96	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - LH	1	\$ 344.00	?	
97	FRONT DOOR WINDOW REGULATOR - LH	1	\$ 305.00	?	
98	FRONT DOOR WINDOW REGULATOR WITH MOTOR - LH	1	\$ 345.00	?	
99	FRONT DOOR CONTROL UNIT - LH <i>Ken</i>	1	\$ 672.00	X	
100	FRONT DOOR BOARD - LH INNER	1	\$ 2,945.00	?	
SUB TOTAL SPARE PARTS		:	\$ 10,944.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 3726 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
101	FRONT DOOR SILL TRIM STRIP - LH <i>ru</i>	1	\$ 687.00	✓	
102	SEAT AIRBAG UNIT - LH <i>ru</i>	1	\$ 1,688.00	✓	
103	CURTAIN AIRBAG UNIT - LH / RH	2	\$ 4,138.00	✓	
104	AIRBAG CONTROL UNIT	1	\$ 2,364.00	✓	
105	REAR AIRBAG CRASH SENSOR	2	TBC	✓	
106	CENTRAL PROTECTION FUSE	1	\$ 590.00	✓	
107	ROOF LINER <i>crumpled</i>	1	\$ 2,339.00	✓	
108	A-PILLAR TRIM UPPER - LH / RH - INNER ?	2	\$ 458.00	?	
109	B-PILLAR TRIM UPPER - LH / RH - INNER ?	2	\$ 520.00	?	
110	C-PILLAR TRIM - LH / RH - INNER ?	2	\$ 508.00	?	
111	D-PILLAR TRIM - LH / RH - INNER ?	2	\$ 508.00	?	
112	B-PILLAR TRIM LOWER - LH INNER <i>del</i>	1	\$ 171.00	✓	
113	WHEEL HOUSING TRIM LOWER - LH INNER ?	1	\$ 166.00	?	
114	FRONT GRAB HANDLE - LH / RH ?	2	TBC	?	
115	REAR GRAB HANDLE - LH / RH ?	2	TBC	?	
116	FRONT SEAT BELT - LH / RH <i>Activated</i>	2	\$ 2,454.00	✓	
117	FRONT SEAT BELT HEIGHT ADJUSTER - LH / RH ?	2	\$ 383.00	?	
118	FRONT PASSENGER SEAT BACKREST COVER - LH <i>torn</i>	1	\$ 3,409.00	✓	
119	UTR CAMERA ?	1	TBC	?	
120	UTR CAMERA WIRING SET ?	1	TBC	?	
SUB TOTAL SPARE PARTS			\$ 20,383.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 3726 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
121	FOAM TUBE ?	3	\$ 21.00	?	
122	FLAT CONTACT HOUSING ?	1	\$ 11.00	?	
123	FLAT CONTACT HOUSING ?	2	\$ 35.00	?	
124	RETAINING HOSE ?	1	TBC		
125	ALUMINIUM RIM at	2	\$ 2,584.00	✓	
126	RUBBER VALVE ne n	2	\$ 8.00	+	
127	EXHAUST TAIL PIPE TRIM - LH / RH RH Best	2	\$ 766.00	383.	
128	ARYLIC SEALANT }	S/N	\$ 180.00	✓	
129	CAVITY WAX }	S/N	\$ 140.00	✓	
130	STONE CHIP } ne	S/N	\$ 180.00	✓	
131	METAL FILLER POWDER }	S/N	\$ 280.00	✓	
132	REAR WINDSCREEN SEALANT }	S/N	\$ 200.00	✓	
133	1/4 GLASS SEALANT }	S/N	\$ 200.00	✓	
134	SUNDRIES ?		\$ 1,000.00	?	
TOTAL SPARE PARTS			\$ 74,897.00	78984	75059
TOTAL LABOUR CHARGES			\$ 45,564.00		
GRAND TOTAL			\$ 120,461.00	124548	120623

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling*
SURVEYED DATE : *25/04/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorized, 35 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT