

ASS. REC. BY:

REF:

A16/22004092/ke

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SIG 34807 Yr Regn: 09, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius c.c. 1798

Colour

M.P. White A/C: Insured / Std / NI / NA

Sp. Reading

214292 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB31F-U 503535029

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

P. Intertral 195/65R15

R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9 mm

R/Bal.

6 mm

L/Bal.

9 mm

L/Bal.

6 mm

D.O.A.

29/4/22

D.O.I.

4/5/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/5/22 11:00 AM 12006 Carlow

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Not withered
11/2/2007
Manny Alu Peim
2 days

Date: 29/04/2022
Vehicle No: SLG3480Z
Model: TOYOTA PRIUS HYBRID 1.8 CVT
Chassis: JTDKB3FU503535029-2016
Reg.Year: 2016

Third Party Insurer: AIG
Third Party Veh No: SDK2205H
Date of Accident: 29/04/2022
Estimator: TING AN
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1	Avic/cm	\$548.00
2	REAR BUMPER SIDE BRACKET RH	1	By	\$112.00
3	REAR BUMPER TOWING COVER RH	1	By	\$35.00
4	REAR BUMPER LOWER GARNISH COVER	1	By	\$486.00
5	REAR BUMPER REINFORCEMENT	1	By	\$337.00
6	REAR LOWER TAIL LAMP RH	1	By	\$486.00
7	REAR END PANEL	1	By	\$629.00
8	REAR END PANEL UPPER COVER	1	By	\$145.00
9	REAR TAILGATE	1		REPAIR
SUB TOTAL				\$2,778.00
LESS 25%				-\$694.50
PARTS TOTAL				\$2,083.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1	By	\$50.00
2	REAR BUMPER REVERSE SENSOR	1	By	\$300.00
3	REAR END PANEL JOINT SEALANT	1	By	\$80.00
S/N TOTAL				\$430.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$700.00 200

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR END PANEL, REAR BUMPER & ETC.

\$700.00 200

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR.

nn \$100.00 X

TO CHECK WIRING & CENTRAL LOCKING SYSTEM & ETC.

nn \$80.00 X

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LABOUR TOTAL \$1,580.00

TING AN

TOTAL \$4,093.50

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Acknowledged by Repairer

Branch (Motor Insurance Claims)
9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)
Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

