

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHA3421Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Apr 2022
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV FL 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	G4LEKU406580
Chassis No.:	KMHC851CVLU189302
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$25,846.00
Original Registration Date:	27 Feb 2020
First Registration Date:	27 Feb 2020
Transfer Count:	0
Actual ARF Paid:	\$13,185.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Feb 2028
PARF Rebate Amount:	\$9,888.00
Intended COE Rebate Details	
COE Expiry Date:	26 Feb 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$26,431.00
COE Rebate Amount:	\$19,244.00
Total Rebate Amount:	\$29,132.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 30 Apr 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	30/04/2022 17:09 (SGT)
Date of Accident	29/04/2022 22:25 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	TOWARDS BKE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA3421Z
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-97473569
Alternative Phone No	(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Ae ioniq
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1580

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdPartyFireTheft
Fleet Policy	Yes
Policy Number	VFX/P2419138
Cover Note Number	-

DRIVER

Name of Driver	GOH KIM HUAT DANIEL
NRIC No	SXXXX714E

Date Of Birth	29/08/1971
Occupation	Outdoor
Date Of Driving Pass	12/10/1991
Driving experience	30 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97473569
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 422 SERANGOON CENTRAL #02-366
Address complement	-
Postcode	550422
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	UNKNOWN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 29/04/2022 AT ABOUT 22:25HRS, I WAS DRIVING VEHICLE A (SHA3421Z) ALONG PIE TOWARDS BKE. WHILE TRAVELLING STRAIGHT ON ON LANE 4, FRONT VEHICLE B (SMC5910X) APPLIED JAMMBRAKE SUDDENLY. I APPLY BRAKE AND STOP IN TIME. WHILE VEHICLE A WAS STATIONARY FOR FEW SECONDS, VEHICLE C (SMJ3037T) COLLIDED ONTO VEHICLE A REAR BUMPER. DUE TO THE IMPACT, MY VEHICLE PUSH FORWARD AND COLLIDED ONTO VEHICLE C REAR BUMPER. TOTAL 3 VEHICLES INVOLVED IN THIS ACCIDENT. MY PASSANGER CLAIM PAIN ON HIS NECK DUE TO THE IMPACT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE NOT SUITABLE
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMC5910X
Vehicle Manufacturer	Audi



Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	AKBAR ALI S/O HABIBULA ABDUL RASHID
NRIC No	SXXXX597A
Contact Number	(Phone) +65-87889786
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMJ3037T
Vehicle Manufacturer	Jaguar
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	WANG SAI
NRIC No	SXXXX924E
Contact Number	(Phone) +65-998762014
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	GOH KIM HUAT DANIEL
Gender	Male
Phone No	(Phone) +65-97473569
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	-
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No



SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

ON 29/04/2022 AT ABOUT 22:25HRS, I WAS DRIVING VEHICLE A (SHA3421Z) ALONG PIE TOWARDS BKE. WHILE TRAVELLING STRAIGHT ON ON LANE 4, FRONT VEHICLE B (SMC5910X) APPLIED JAMMBRAKE SUDDENLY. I APPLY BRAKE AND STOP IN TIME. WHILE VEHICLE A WAS STATIONARY FOR FEW SECONDS, VEHICLE C (SMJ3037T) COLLIDED ONTO VEHICLE A REAR BUMPER. DUE TO THE IMPACT, MY VEHICLE PUSH FORWARD AND COLLIDED ONTO VEHICLE C REAR BUMPER. TOTAL 3 VEHICLES INVOLVED IN THIS ACCIDENT. MY PASSANGER CLAIM PAIN ON HIS NECK DUE TO THE IMPACT.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

29/4/22 @ 2340H

Wheany

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 4-May-22

INSURANCE: PLS

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA 3421Z

Description	Qty	List Price	Amount
Radiator Grille NEW MODEL <i>crack / broken</i>	1	\$ 1,568.60	\$ 1,568.60
Flap Assy Active Air Upper, (LH/RH) <i>o/s HH H/s broken</i>	2	\$ 824.60	\$ 1,649.20
Flap Assy Active wire <i>not socket broken</i>	1	\$ 765.30	\$ 765.30
Front Number Plate garnish <i>deformed</i>	1	\$ 188.00	\$ 188.00
Front Bumper Cover <i>cut / broken</i>	1	\$ 481.10	\$ 481.10
Front bumper top cover <i>HH</i>	1	\$ 476.30	\$ 476.30
Front Bumper Sponge <i>torn</i>	1	\$ 186.90	\$ 186.90
Front Bumper Reinforcement <i>1st / Dent</i>	1	\$ 1,136.70	\$ 1,136.70
Front Bumper Reinforcement ABSORBER (LH/RH) <i>svz</i>	2	\$ 186.50	\$ 373.00
Front Bumper Towing Cover <i>HH</i>	1	\$ 29.00	\$ 29.00
Front Bumper Moulding Centre Upper <i>cut / mounting broken</i>	1	\$ 368.50	\$ 368.50
Front Bumper Moulding <i>HH</i>	1	\$ 93.60	\$ 93.60
Front Bumper Lower Stiffner <i>HH</i>	1	\$ 285.10	\$ 285.10
Front bumper lower grille <i>HH</i>	1	\$ 365.30	\$ 365.30
front bumper lower grille moulding <i>HH</i>	1	\$ 127.60	\$ 127.60
Front Bumper Lip <i>HH</i>	1	\$ 35.10	\$ 35.10
Front Bumper Bracket Top (LH/RH) <i>HH o/s H/s broken</i>	2	\$ 35.00	\$ 70.00
Front Bumper Bracket (LH/RH) <i>HH</i>	2	\$ 28.00	\$ 56.00
Front Bumper Retainer Mounting (LH/RH) <i>HH</i>	2	\$ 65.30	\$ 130.60
Front Bumper Clips 10 pcs <i>H/c</i>	1	\$ 25.00	\$ 25.00
Front Bumper Grille (LH/RH) <i>svz</i>	2	\$ 186.90	\$ 373.80
Front bumper air duct (LH) <i>HH</i>	1	\$ 153.80	\$ 153.80
Day Light ,LH <i>mounting crack</i>	1	\$ 642.50	\$ 642.50
BUZZER ASSY - PIEZO (LH) <i>HH</i>	1	\$ 388.00	\$ 388.00
Headlamp Support Panel Assy <i>crack</i>	1	\$ 1,139.30	\$ 1,139.30
Headlamp(LH/RH) <i>o/s HH H/s crack</i>	2	\$ 3,987.30	\$ 7,974.60
Horn Unit (LH/RH) <i>HH</i>	2	\$ 72.80	\$ 145.60
Horn Wire <i>HH</i>	1	\$ 386.70	\$ 386.70
Radiator Inverter <i>HH</i>	1	\$ 884.80	\$ 884.80
Radiator <i>1st / punctured</i>	1	\$ 710.50	\$ 710.50
Radiator Air Guard (LH/RH) <i>HH</i>	2	\$ 76.40	\$ 152.80
Radiator Air Guard, Upr (LH/RH) <i>HH</i>	2	\$ 127.50	\$ 255.00
Air Duct <i>HH</i>	1	\$ 156.80	\$ 156.80
air duct hose <i>HH</i>	1	\$ 86.40	\$ 86.40
Aircon Condenser <i>not 1st / punctured</i>	1	\$ 663.60	\$ 663.60
Boot Lid <i>Dent</i>	1	\$ 2,549.70	\$ 2,549.70
Boot Lid Rubber <i>H/c / deformed</i>	1	\$ 187.40	\$ 187.40
Boot Lid Lock Upper <i>svz</i>	1	\$ 224.00	\$ 224.00
Boot Lid 'H' Emblem <i>H/c</i>	1	\$ 28.00	\$ 28.00
Emblem-Hybrid <i>H/c</i>	1	\$ 24.30	\$ 24.30
Emblem-Ioniq <i>H/c</i>	1	\$ 31.30	\$ 31.30
Boot Lid Trimboard <i>HH</i>	1	\$ 259.70	\$ 259.70

[illegible]

Boot Lid Trimboard Clips (10pcs) <i>HN</i>	1	\$ 11.00	\$ 11.00
Boot Lid Trimboard, Centre <i>HN</i>	1	\$ 159.60	\$ 159.60
Boot Lid Trimboard SIDE (LH/RH) <i>HN</i>	2	\$ 92.50	\$ 185.00
Boot Lid Trimboard REAR <i>HN</i>	1	\$ 124.80	\$ 124.80
Boot Lid Glass Upper Moulding <i>HN</i>	1	\$ 186.30	\$ 186.30
Boot Lid Glass Lower Moulding <i>HN</i>	1	\$ 145.20	\$ 145.20
Rear Bumper <i>distorted / broken</i>	1	\$ 459.40	\$ 459.40
Rear Bumper Reinforcement <i>CRACK</i>	1	\$ 394.80	\$ 394.80
Rear Bumper Reinforcement Bracket (LH/RH) <i>0/5 HN H/S Dashed</i>	2	\$ 188.10	\$ 376.20
Rear Bumper Centre Moulding Assy <i>broken</i>	1	\$ 451.25	\$ 451.25
Rear Bumper Lower Centre Moulding Assy <i>mostly broken</i>	1	\$ 47.50	\$ 47.50
Rear Bumper Stay <i>HN</i>	1	\$ 138.10	\$ 138.10
Rear Bumper Side retainer (LH/RH) <i>HN</i>	2	\$ 85.80	\$ 171.60
Rear Bumper Cover Clips <i>HLC</i>	1	\$ 22.00	\$ 22.00
Rear Bumper Under Centre <i>mostly CRACK</i>	1	\$ 123.85	\$ 123.85
Rear Bumper Side Under (LH/RH) <i>HN</i>	2	\$ 123.10	\$ 246.20
Rear Bumper Reflector Lamp (LH) <i>SC</i>	1	\$ 82.90	\$ 82.90
Rear Bumper Towing Cover <i>CRACK</i>	1	\$ 98.80	\$ 98.80
Rear Bumper Reserve Light (Parking Brake Light) <i>socket</i>	1	\$ 328.60	\$ 328.60
Licence Lamp <i>HN</i> <i>broken</i>	1	\$ 193.53	\$ 193.53
Licence Lamp WIRE <i>HN</i>	1	\$ 135.80	\$ 135.80
Rear Panel <i>Dashed</i>	1	\$ 532.00	\$ 532.00
Rear Panel Garnish <i>damaged</i>	1	\$ 346.80	\$ 346.80
Rear tray tools box RH <i>HN</i>	1	\$ 675.30	\$ 675.30
Rear tray tools box LH <i>HN</i>	1	\$ 693.20	\$ 693.20
REAR TRAY LUGGS CENTER <i>HN</i>	1	\$ 354.20	\$ 354.20
Exhaust Silencer <i>HN</i>	1	\$ 943.50	\$ 943.50
Exhaust Pipe Hanger <i>HN</i>	1	\$ 29.20	\$ 29.20
SUB TOTAL			\$ 33,486.13
LESS 20%			\$ 6,697.23
DISCOUNTED TOTAL			\$ 26,788.90
Front Number Plate <i>CRACK</i> SN	1	\$ 25.00	\$ 25.00
Front No Plate Trim Cover <i>Dashed</i> SN	1	\$ 30.00	\$ 30.00
COOLANT <i>HN</i> SN	1	\$ 45.00	\$ 45.00
Boot Lid Comfort Logo & Tel No. Sticker <i>HLC</i> SN	1	\$ 35.00	\$ 35.00
Boot Lid Comfort Cablink Tel No. Sticker <i>HN</i> SN	1	\$ 30.00	\$ 30.00
Boot Lid Advertisement Logo <i>HLC</i> SN	1	\$ 100.00	\$ 100.00
Rear No. Plate + Trim Cover <i>CRACK / Dashed</i> SN	1	\$ 45.00	\$ 45.00
Rear Windscreen Sealant <i>HLC</i> SN	2	\$ 46.00	\$ 92.00
Rear Bumper Rubber Mat <i>HLC</i> SN	1	\$ 50.00	\$ 50.00
Rear Bumper Reverse Sensor <i>Dam</i> SN	1	\$ 180.00	\$ 180.00
SUB TOTAL			\$ 632.00
Labour Charge			
Panel Beating	1	\$1,800.00	\$1,800.00
Spray Painting Charge	1	\$1,600.00	\$1,600.00
Wiring Charge	1	\$100.00	\$100.00
Tuff Kote	1	\$100.00	\$100.00
Towing Charge	1	\$80.00	\$80.00
Remove/Refix Rear Windscreen Glass	2	\$120.00	\$240.00
Remove/Refix Reverse Sensor	1	\$120.00	\$120.00

2993.10

16,659.70

13,327.76

Remove/Refix Exhaust Pipe	1	\$80.00	\$80.00
Remove/Refix Radiator	1	\$90.00	\$90.00
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00
TOTAL LABOUR			\$4,890.00
ESTIMATE TOTAL			\$ 32,310.90

44-
50/-
80/-
150/-

1870.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance

? / P 15,744.76

05/05/2022 0945hrs

Not Antenna

? / Part 9 days.

P Ryan

LKK Auto



Photo after
repair with
damaged parts.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: