

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 05 Aug 2022

**Preliminary Advice**

Insured Vehicle No	: XE3360E	Accident Date	: 30/04/2022
TP Vehicle No	: GBF3433J	Assignment Date	: 04/05/2022
Make	: HONDA 660CVT	Est. Duration of Repair	: 5
Date of Inspection	: 05/05/2022		
Inspection At	: RYDER AUTO PTE LTD (HQ) 2 KAKI BUKIT AVE 2, #02-19 AUTOHUB @ KAKI BUKIT SINGAPORE 417921		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,031.43
Revised Amount	:S\$	4,682.10
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,682.10
 Lump Sum Repair	 :S\$	 3,700.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.