

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. DM 224000683 / MT


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1-B1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S1TC 5485R Yr Regn: 11, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Toy Prius c.c. 1798

Colour Mr. White / R A/C: Insured / Std / NI / NA

Sp. Reading 130635 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB31U403092801

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: Pirelli 195/65R15

R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 2 mm R/Bal. 5 mm

L/Bal. 2 mm L/Bal. 5 mm

D.O.A. 29/4/22 D.O.I. 5/5/2022

Survey held at _____

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

& 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Got BI

1815 @ 3029.00 Car has used to 13899-73, 821/2

Date/Time, File Pass to?

1) 14/06 Typist

Date/Time, File Return to?

2)

☐ : Prell. Report

☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. SI

Fines

Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TP
3029

Not Attached
Penny B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5485R

AAD2205-003

83029.00

Vehicle No.:

05 MAY 2022

Chassis No.:

SHC5485R

JTDKB3FU403092601

Co UEN:

200303878K

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS GEN 4

Date of Accident :

29/04/2022

Third Party Insurer :

SMW9390P/EQ

Date of Registration:

06/11/2020

PART		LIST	
1	COVER, REAR BUMPER	\$ Bu	485.60 ✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER	\$ Bu	332.70 ✓
1	COVER, REAR BUMPER, LOWER	\$ Su	22.00 X
1	GUARD, REAR BUMPER, CENTER	\$ Bu	374.50 ✓
1	RETAINER, REAR BUMPER SIDE, LH	\$ Su	132.60 X
1	RETAINER, REAR BUMPER SIDE, RH	\$ Su	132.60 ✓
1	PANEL SUB-ASSY, BACK DOOR	\$ R	1,147.80 ✓
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2	\$ Ru	54.60 X
1	PLATE, BACK DOOR NAME, NO.1	\$ Ru	54.60 X
1	ORNAMENT SUB-ASSY, BACK DOOR	\$ Ru	47.90 ✓
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	\$ Su	913.60 X
1	COVER, FLOOR UNDER, NO.1 LH	\$ Su	175.10 X
1	COVER, FLOOR UNDER, NO.2 RH	\$ Su	241.90 X
1	COVER, REAR FLOOR CTR	\$ CM Su	229.90 ✓
1	COVER, DECK TRIM, REAR	\$ Su	126.70 X
1	PANEL SUB-ASSY, BODY LOWER BACK	\$ R	651.00 X
1	COVER, FRONT BUMPER	\$ Bu	521.00 ✓
1	BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$ Su	110.50 X
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$ R	716.60 X
1	ABSORBER, FRONT BUMPER ENERGY	\$ Su	80.20 X
1	GRILLE SUB-ASSY, RADIATOR	\$ ndlpr	422.50 ✓
1	GRILLE, RADIATOR, LOWER NO.1	\$ Su	178.60 X
1	EMBLEM ASSY, RADIATOR GRILLE	\$ mc	105.80 ✓
TOTAL		\$	7,258.30 - 2435.10
25%		\$	1,814.58
		\$	5,443.73 4323.20
			- 75%
			3742.40

Trans-cab Auto Services Pte Ltd

AAD2205-003

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5485R

Special Nett

1SET PARKING AID	\$	700.00	X
1SET REAR BUMPER CLIP	\$	95.00	605N
2 WINDSCREEN SEALANT	\$	150.00	X
1 WINDSCREEN MOULDING	\$	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	130.00	X
1 REAR TAILGATE STICKER "Trans-Cab"	\$	80.00	X
1 REAR TAILGATE STICKER "6555-3333"	\$	80.00	X
1 REAR BUMPER PROTECTOR	\$	180.00	X
1SET REAR BUMPER RETAINER CLIP	\$	85.00	X
1 END PANEL TRIM CLIP	\$	65.00	X
1SET BUMPER CLIP FRT	\$	95.00	605N
1 FRONT NUMBER PLATE WITH MOULDING	\$	200.00	455N
1SET FRNT BUMPER RETAINER CLIP	\$	85.00	X
TOTAL	\$	2,145.00	1965

TOTAL PARTS \$ 7,588.73**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	500
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	480.00	X

Trans-cab Auto Services Pte Ltd

AAD2205-003

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5485R

To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>nn</i> 480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	<i>4</i> 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>4</i> 380.00	X
To check steering geometry and computer wheel alignment	\$	<i>4</i> 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>4</i> 250.00	X
Towing Fees	\$	<i>4</i> 150.00	X
Putty And Spray Painting Of The Affected Portion.	\$	<i>800</i> 2,200.00 <i>4401</i>	
To reinstall rear bumper parking sensor.	\$	170.00 <i>501</i>	
To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>	
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i> 220.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	<i>4</i> 380.00	X
TOTAL	\$	9,300.00	<i>4740</i>

Over All Total \$ 16,888.73*9947.40***(PART-BY-PART) Repair Days****25 DAYS***3 days***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: