



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:YVONNE			Ref: CC4/ASM22004121/Upa3q2 Date: 14/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLG 8022E	Veh. Inspected	SMS 7470B	
Policy No.	GA579647	Coverage (\$)	0.00	
Claim No.	S2M03ZWW	Excess (\$)	0.00	
Assign From		Assign Date	04/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA NOAH HYBRID (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	ZWR800433033	Colour	BLACK	
Odometer	160287 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FIRENZA	6 mm	
L/H Front Tyre	195/65 R15	FIRENZA	6 mm	
R/H Rear Tyre	195/65 R15	PREMIO	6 mm	
L/H Rear Tyre	195/65 R15	PREMIO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/04/2022	Inspection Date	04/05/2022	
Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		