

KAKI BUKIT AUTOHIRE AND AUTO SERVICES

NO. 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHIRE NO. 15 SINGAPORE 617921.
TEL: 6747 2755 FAX: 6746 5922 EMAIL: kbp@kbp232@kbp232.com ROC 530424422

Vehicle No: 2MM 82-461
Make/Model: W/61/1A1
Chassis No: 131W 1409-62076921

INDEPENDENT SURVEYOR	DIRECT SETTLEMENT
----------------------	-------------------


Date: _____

Estimate cost of repair to the above mentioned

NO.	QTY	LIST ITEMS	SPECIAL NETT PRICE	MARKING	UNITS	AMOUNT (\$)
1	1	FRONT BUSHING	/MT		21630	
2	1	FRONT BUSHING HAT BUSHED	/MT		132	
3	1	FRONT BUSHING HAT BUSHED CLIP	/MT		67	
4	2	FRONT BUSHING HAT BUSHED AIR	477	X/L	154	
5	1	RH FRONT FINDER	/MT		330	
6	1	RM FRONT FINDER WHEEL ARCS / MT			68	
7	1	RM FRONT FINDER FINDER BUSHED	/MT		135	
8	1	RM FRONT FINDER FINDER BUSHED CLIP	94	/MT	467	30
9	1	RM FRONT HAT LAMP	/MT		1454	
10	1	RM FRONT HAT LAMP LOWER BRACKET	/MT		96	
11	1	FRONT BUMPER	/MT		415	
12	1	FRONT LOWER BUMPER	/MT		415	
13	1	FRONT BUMPER REINFORCEMENT	/MT		475	
14	2	FRONT BUMPER REINFORCEMENT	453	/MT	106	
15	1	FRONT BUMPER CLIP	NEC	94	57	30
16	1	FRONT RADIATOR GRILLE	/MT		1200	
17	1	FRONT BUMPER LOWER GUARDIAN	/MT		138	
18	1	FRONT BUMPER LOWER GUARDIAN (SILVER)	/MT		97	
19	1	FRONT SUPPORT PANEL	(45)		338	
20	1	FRONT SUPPORT PANEL TOP PANEL, RH	/MT		72	

REMARKS:

NO OF DAYS:			
AGREED FIGURE/LUMP SUM:	\$	.	
SURVEYOR NAME	CONTACT:		
EMAIL ADD:			



HUP SOON BATTERIES AND AUTO SERVICES

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #01-15 SINGAPORE 417921.

TEL: 6747 2755 FAX: 6746 5922 email: hupsoon238@yahoo.com ROC 53043448B

Vehicle No: 8MM88446
Make/Model: ULH/BV
CHASSIS NO: LSJW74092L2075941

INDEPENDENT SURVEYOR
DIRECT SETTLEMENT

Date: _____

Estimate cost of repair to the above mentioned

NO. QTY LIST ITEMS

MARKING

UNIT \$

AMOUNT (\$\$)

1	1	FRONT DRIVER SEAT BELT	/jan 7		\$ 854	
2	1	SEAT BELT CONTROL UNIT.	XR 1		\$ 833	
3	1	FRONT AIR COND CONDENSOR	SU X 7		\$ 488	
4	1	FRONT RADIATOR	SU X 1		\$ 670	
5	2	RH FRONT DOOR HINGE X L/R	\$ 58 /sh		\$ 116	
6	1	RH FRONT DOOR	XR		\$ 1900	
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						

-56/6

REMARKS:

NO OF DAYS:	
AGREED FIGURE/LUMP SUM:	\$ -
SURVEYOR NAME	CONTACT:
EMAIL ADD:	



HUP SOON BATTERIES AND AUTO SERVICES

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #01-15 SINGAPORE 417921.
TEL: 6747 2755 FAX: 6746 5922 email: hupsoon238@yahoo.com ROC 53043448B

Vehicle No: <u>8MM 88447</u>	INDEPENDENT SURVEYOR
Make/Model: <u>MG1 / 1.6</u>	DIRECT SETTLEMENT
CHASSIS NO: <u>1S1W74092LZ075941</u>	Date: _____

Estimate cost of repair to the above mentioned

NO.	QTY	LIST ITEMS	MARKING	UNIT \$	AMOUNT (\$\$)
1		PAINT BAY	1000	800	\$ 1500
2					
3		REPAIR PAINT	1000	800	\$ 1500
4					
5		TO REMOVE AND REPAIR FRONT BAY BOLT AND		1250	\$ 350
6		CONTROL UNIT PLUS PROGRAMMING			
7					
8		CHECK WIRING		30	\$ 100
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					

L/S 8000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

REMARKS:		
NO OF DAYS:	6 days w/p	
AGREED FIGURE/LUMP SUM:	\$ -	
SURVEYOR NAME	Thirvan 5/3/22 1200	CONTACT: 82235709
EMAIL ADD:		