

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jacqueline Tan

Date: 24 May 2022

Preliminary Advice

Vehicle No	: SMM8844G	Accident Date	: 23/04/2022
Make	: M.G. ZS EV	Policy No.	: DMPCSNA00139362100
Assignment Date	: 05/05/2022	Excess	: S\$1,500.00
Date of Inspection	: 05/05/2022	Est. Duration of Repair	: 6
Inspection At	: HUP SOON BATTERIES & AUTO SERVICES (HQ) BLK 1059 EUNOS AVE 3 #01-150 SINGAPORE 409849		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,898.70
Revised Amount	:S\$	9,933.70
Check Items (Estimated)	:S\$	0.00
Total	:S\$	9,933.70

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	106,000.00
COE / PARF Rebate	:S\$	40,784.00
Salvage Value	:S\$	
Margin for Repair	:S\$	65,216.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :