

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Liu Chun Cheong

Date: 27 May 2022

Preliminary Advice

Vehicle No	: SLX4966T	Accident Date	: 27/04/2022
Make	: KIA CARENS	Policy No.	: MCF22A00000100
Assignment Date	: 04/05/2022	Excess	: S\$2,000.00
Date of Inspection	: 05/05/2022	Est. Duration of Repair	: 6
Inspection At	: MUNICH AUTOCARE PTE LTD (HQ) 60 JALAN LAM HUAT, #07-43 SINGAPORE 737869		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,793.70	
Revised Amount	:S\$	5,474.30	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	509.40	
Total	:S\$	5,983.70	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	73,000.00
COE / PARF Rebate	:S\$	39,525.00

Salvage Value	:S\$
Margin for Repair	:S\$ 33,475.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.