

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	SM8224S0001
Policy No:	MCF22A00000100	Date of Loss:	27/04/2022
Vehicle Reg. No.:	SLX4966T	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		
Make/Model:	KIA CARENS, 1.7 D DCT 5DR FWD (A)	Vehicle Reg. Date:	29/03/2018
Vehicle Colour:	Brown		
Engine No:	D4FDJH551006	Chassis No:	KNAHU815VJ7203852
Odometer:	330000 KM		
Paint Type:			<i>Not available</i>
Total Loss?	NO		<i>Rebody B4 paint</i>
Est. Duration of Repair (day) 6	✓		<i>Ex @ 2000h</i>
Present Location:	MUNICH AUTOCARE PTE LTD (HQ)		<i>@ 5612.90 B4 excess</i>

COST OF CLAIMS

	Amount
Parts	3,927.00
Miscellaneous Items	145.00
Labour	2,670.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	6,742.00
- Excess (S\$)	2,000.00
(S\$)	4,742.00
+ GST 7.00% (S\$)	331.94
Nett Amount (S\$)	5,073.94

This claim is handled by: TAN CHIN CHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 May 2022)
Parts: M1-MPV KIA CARENS 1.7 D DCT 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Munich Autocare Pte Ltd/SLX4966T/04/05/2022 14:59
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR TAIL LAMP LH 114	0.00	0.00	*114.00 F ✓
2	1		*REAR TAIL GATE LAMP LH 180	0.00	0.00	*180.00 F ✓
3	1		*REAR FENDER LH 720	0.00	0.00	*720.00 F ✓
4	1		*REAR OUTER GLASS LH	0.00	0.00	*216.00 F X
5	1		*REAR BUMPER 264	0.00	0.00	*264.00 F ✓
6	1		*REAR BUMPER SIDE BRACKET LH 18	0.00	0.00	*18.00 F ✓
7	1		*REAR DOOR LH 576	0.00	0.00	*576.00 F ✓
8	1		*REAR RIMS R16 360	0.00	0.00	*360.00 F ✓
9	1		*REAR AXLE WITH KNUCKLE ARM 816	0.00	0.00	*816.00 F ✓
10	1		*REAR ABSORBER LH 138	0.00	0.00	*138.00 F ✓
11	1		*REAR HEEL HUB 168	0.00	0.00	*168.00 F ✓

F=Franchise part.

Sub Total (S\$) 3,570.00
 + Margin on L,N Items 10.00% (S\$) 357.00
Total Parts (S\$) 3,927.00

Munich Autocare Pte Ltd/SLX4966T/04/05/2022 14:59. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	REAR BUMPER CLIPS	25.00 ✓
2	1	REAR TYRE 205/55/R16	120.00 X
Sub Total (S\$)			145.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO PANEL BEATING, REALIGN DISMANTLE REAR BUMPER, REAR BOOT LID, END PANEL OUTER, REAR TAILLAMP PANEL LH, REAR FENDER LH/INNER, REAR CHASSIS LH, REAR DOOR LH & ALL NECESSARY ETC	New	1,200.00 800 ✓
2	TO CHECK ELECTRICAL WIRING SYSTEM OF REAR SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF REAR TAIL GATE LAMP & TAIL LAMP LH/RH	New	120.00 20 ✓
3	TO DISMANTLE & RENEW REVERSE SENSOR	New	120.00 50 ✓
4	TO REMOVE & INSTALL LUGGAGE COMPARTMENT AND SIDE FENDER INNER TRIM TO FACILITATE REPAIR	New	120.00 100 ✓
5	TO PUTTY & SPRAY PAINT REAR BUMPER, REAR BOOT LID, END PANEL, REAR FENDER LH, REAR TAILLAMP PANEL LH, FENDER INNER LH, REAR DOOR CHASSIS LH/RH AND ALL NECESSARY ETC	New	600.00 ✓
6	TO REMOVE AND INSTALL REAR QUARTER GLASS LH INCLUDING TO CONDUCT WATERLEAK TEST	New	80.00 50 ✓
7	TO REPLACE REAR LEFT TYRE AND WHEEL RIM INCLUDING WHEEL BALANCING	New	80.00 20 ✓
8	TO REMOVE AND INSTALL REAR SUSPENSION, REAR AXLE AND CONTROL SYSTEM TO FACILITATE THE WORK	New	150.00 100 ✓
9	TO CONDUCT 4 WHEEL ALIGNMENT	New	80.00 60 ✓
10	TO REMOVE AND INSTALL FUEL TANK IN ORDER TO CARRY OUT REPAIR JOB INCLUDING TO CHECK FOR LEAK	New	120.00 60 ✓
Gross Labour Cost (S\$)			2,670.00

Munich Autocare Pte Ltd/SLX4966T/04/05/2022 14:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Reference

Estimates on Parts

F=Franchise part.

Munich Autocare Pte Ltd/SLX4966T/18/05/2022 15:32. Not valid without Reference section.
Generated using Merimen e-Claims IEAS