



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI22004132/Avcm4	
			Date: 09/11/2022	
			Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 8370J		Veh. Inspected	YN 6891K
Policy No.			Coverage (\$)	0.00
Claim No.	M11D15132205		Excess (\$)	0.00
Assign From	JOSEPHINE WONG		Assign Date	05/05/2022
2. Vehicle Particulars & Condition				
Make & Model	HINO XZU710R		c.c	4009
Engine No.	HIDDEN		Year of Reg.	2014
Chassis No.	JHHUCS3H10K010379		Colour	WHITE
Odometer	405992 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre	7.00 R16		KENDA	6 mm
L/H Front Tyre	7.00 R16		KENDA	6 mm
R/H Rear Tyre	7.00 R16		KENDA	6 mm
L/H Rear Tyre	7.00 R16		KENDA	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/05/2022		Inspection Date	05/05/2022
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			14 Working Days	