

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

JHHUCS3H10K010379

ESTIMATE OF REPAIR

Veh# : YN6891K

TP UOI

Model:

HINO XZU710R

Accident Date : 4/5/2022

VERON.

27/11/2014

Location : PIE TOWARDS BKE

3P:

YN1112J (MSIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper <i>Distorted</i>	740.00	✓	
2	1 pc	Front bumper bracket <i>damaged</i>	145.60		
3	1 pc	Front n/s fog lamp <i>Missing</i>	265.70	✓	
4	1 pc	Front grille <i>smashed</i>	460.50	✓	
5	8 pcs	Front grille clips <i>new</i>		40.00	✓
6	1 pc	Front "HINO" logo <i>new</i>	83.40	✓	
7	2 pcs	Front no head lamp <i>smashed n/s, d/s could</i>	4620.40 1700		
8	2 pcs	Front n/s head lamp seal (lower) <i>torn</i>	60.00	10.	
9	1 pc	Front panel <i>Distorted</i>	810.50	✓	
10	8pcs	Front panel clips <i>new</i>		80.00	x.
11	1 pc	Front panel inner <i>Distorted.</i>	1340.30	✓	
12	1 pc	Front panel HINO sticker <i>3 new</i>		50.00 30	
13	1 pc	Front panel 300 sticker		50.00 25.	
14	1 pc	Front wiper panel <i>new</i>	855.70	x.	
15	1 pc	Front wiper linkage <i>Bent</i>	645.40 398		
16	1 pc	Front wiper motor <i>new</i>	310.50	x	
17	2pcs	Front wiper <i>cut</i>		120.00	✓
18	1 pc	Front n/s side mirror bracket <i>Bent</i>		234.50	✓
19	1 pc	Front n/s side mirror bracket side mirror long		80.00	✓
20	1 pc	Front n/s side mirror bracket side mirror round		68.00	✓
21	1 pc	Front n/s side mirror bracket garnish		40.00	✓
22	1 pc	Front n/s side mirror bracket garnish (round)		40.00	✓
23	1 pc	Front n/s corner panel garnish <i>missing</i>	344.50	✓	
24	1 pc	Front n/s door <i>Repr</i>	1258	x	
25	1 pc	Front n/s door hinges <i>new</i>	58	x	
26	1 pc	Front n/s door company sticker		100.00 80	
27	1 pc	Front n/s door 616 sticker		60.00 30	
28	1 pc	Front n/s door Euro5 sticker		60.00 30.	
29	1 pc	Front n/s step garnish <i>cut</i>	260.30	✓	
30	1 pc	Front dash board wiring harness <i>new</i>	2144.30	x.	
31	1 pc	Front dash board <i>torn</i>	1730.40	✓	
32	1 pc	Front dash board speaker <i>new</i>		200.00	x
33	3pcs	Front dash board bracket <i>Bent</i>	340.50	✓	
34	1 pc	Front dash board reinforcement <i>Bent.</i>	980.50	✓	
35	1 pc	Front dash board luggage compartment casing	550.40	✓	
36	1 pc	Front dash board luggage compartment drawer	340.50	✓	
37	1 pc	Front dash board garnish middle <i>Repr.</i>	155.40	✓	
38	1 pc	Front gear selector garnish <i>new</i>	164.30	x.	

39	1 pc	Air cond blower <i>Cracked.</i>	2230.60 ✓	1493	
40	1 pc	Air cond coil <i>Cracked.</i>	3588.40 ✓	1650	
41	1 pc	Front windscreen <i>Shattered.</i>	1520.00 ✓	1350.	
42	1 pc	Front windscreen moulding <i>Nu</i>	210.00 ✓		
43	1 pc	Front windscreen sealent <i>Nu</i>		60 ✓	
44	1 pc	Front n/s A pillar inner trim <i>Not Nu</i>	232.60 X.		
45	1 pc	washer tank <i>Deformed.</i>	220.00 ✓		
46	1 pc	Brake servo <i>Not Nu</i>	1640.60 X		
47	1 pc	Brake fluid <i>Not Nu</i>		80.00 40.	
48	1 pc	Air con hose component suction <i>3 Bent</i>	210.40 ✓		
49	1 pc	Air con hose component discharge	190.00 ✓		
50	1 pc	Engine bypass hose suction <i>3 Not Nu</i>	244.50 ✓		
51	1 pc	Engine bypass hose discharge	254.60 ✓		
52	1 pc	Coolant <i>Nu</i>		140.00 X.	
53	1 pc	Converter sub assembly <i>Not Nu</i>	1600.40 X		
54	1 pc	Computer assembly electrical control <i>Nu</i>	2904.40 X		
55	1 pc	Front cabin floor panel <i>Reis</i>	repair X		
56	1 pc	washer tank <i>Repeated.</i>	220.00 X.		
57	1 pc	Front cabin mounting <i>Not Nu</i>	610.60 X		
58	1 pc	Front cabin mounting cross member <i>Not Nu</i>	2104.30 X		
1599.90 S.N: 897.50			Total:	35,331.50	1,442.50 0.00
14381.91				10%	0% 0%
			After Less %:	31,798.35	1442.50 0.00
Labour					
1		To dismantle damaged parts, straighten & welding.	3,000.00	1600	
2		To spray painting.	1,800.00	1300.	
3		To remove and replace front dash board	500.00	220.	
4		To remove and replace front cabin mounting & cross member	300.00	X	
5		To remove & refit windscreen	180.00	120.	
6		To top up air con gas	100.00	80.	
7		To remove and refit & pressure test check on radiator	100.00	60.	
8		To remove & refit front o/s & n/s door to facilitate repair	200.00	X.	
9		To remove and refit upholstery to facilitate repair	150.00	✓	
10		To remove & replace blower.	150.00	100.	
11		To re set electrical system.	250.00	100	
12		To check wiring.	200.00	50	
13		To re seal anti rust.	100.00	✓	
Sub Total:			7,030.00		
Total:			40,270.85		41,515.25
After less 20%			32,216.68		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

John: 1915 94 / Adrian L
L/C: 15.3K H/S 14 Days.

bizSAFE
ST R

8778 1999
24 hr accident call

Mobil 1

