

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

Not Authorized
 with
 names
 29/4/22
 H/S 5400
 28/4/22
 P. Chrys

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
 3 Anson Road
 Springleaf Tower #16-00
 Singapore 079909
TEL: 63896111 **FAX:** 6221033
ATTN: Motor Claim Department \ CHINA

Estimate No: EST1508089
Date: 28 Apr 2022
Policy No: 5109583034-02
Veh Reg No: SMK7838S
Make/Model: TOYOTA TOYOTA
 COROLLA ALTIS 1.6L
 CVT
Chassis No: MR053REH104535931
Engine No: 1ZR521398
Reg. Date: 30/06/2015

Your Ref No: TP 0422-6758
Claim Type: Third Party
Accident Date: 28/04/2022
TP Veh Reg No: SMR1169S

Estimate Repair Cost to Vehicle No :SMK7838S

Description	U/Price	Quantity	Price	Amount
			S\$	S\$
List Price				
1 REAR BUMPER Dis	589.90	1 PC	589.90	✓
2 REAR BUMPER SIDE HOLDER -LH/RH olcno	116.00	2 PC	232.00	1PC
3 REAR BUMPER CLIPS see	5.50	10 PC	55.00	✓
4 REAR BUMPER REINFORCEMENT best	423.90	1 PC	423.90	✓
5 REAR BUMPER REINFORCEMENT BRACKET -LH/RH m	72.20	2 PC	144.40	✓
6 REAR BUMPER SENSOR m	320.50	2 PC	641.00	X
7 REAR BUMPER REFLECTORS -RH BRO	63.40	1 PC	63.40	✓
8 REAR FENDER -RH Bedgio / auc	1,218.20	1 PC	1,218.20	✓
9 REAR FENDER COWLING -RH Toon / mcs	58.50	1 PC	58.50	✓
10 REAR FENDER COWLING CLIPS -RH see	5.50	10 PC	55.00	✓
11 REAR FENDER INNER PANEL -RH DAM	364.50	1 PC	364.50	✓
12 TAIL LAMP -RH see	369.50	1 PC	369.50	✓
13 TAIL LAMP CLIP -RH m	5.50	1 PC	5.50	X
14 TAIL LAMP INNER PANEL -RH m / see	117.90	1 PC	117.90	✓
15 REAR BOOT LAMP -RH m	370.00	1 PC	370.00	X
16 REAR BOOT COROLLA WORDINGS see	67.20	1 PC	67.20	✓
17 REAR BOOT ALTIS WORDINGS see	67.20	1 PC	67.20	✓
18 REAR BOOT TOYOTA EMBLEM see	72.20	1 PC	72.20	✓
19 REAR BOOT OUTER CHROME GARNISH m	258.40	1 PC	258.40	X
20 REAR EXHAUST m	1,194.60	1 PC	1,194.60	X
21 REAR EXHAUST TOP MOUNTING m	52.20	1 PC	52.20	X
22 REAR EXHAUST TOP PLATE best	71.20	1 PC	71.20	✓
23 REAR END PANEL D / Buf	710.40	1 PC	710.40	✓
24 REAR END PANEL TOP GARNISH m	256.50	1 PC	256.50	X
25 REAR DOOR -RH R	1,323.00	1 PC	1,323.00	X
26 REAR DOOR RUBBER -RH m	191.00	1 PC	191.00	X
27 REAR DOOR STICKER - RH m	46.20	1 SET	46.20	X
			8,969.30	
		Less 25%	2,242.33	6,726.98
Special Net				
28 SEALANT Rear window screen	20.00	2 PC	40.00	✓
29 SPONGE TAPE Rear window screen	10.00	1 PC	10.00	✓
			50.00	50.00

440

Labour

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 Anson Road
 Springleaf Tower #16-00
 Singapore 079909

TEL: 63896111 FAX: 6221033
 ATTN: Motor Claim Department \ CHINA

Estimate No: EST1508089
Date: 28 Apr 2022
Policy No: 5109583034-02
Veh Reg No: SMK7838S
Make/Model: TOYOTA TOYOTA
 COROLLA ALTIS 1.6L
 CVT

Your Ref No: TP 0422-6758
Claim Type: Third Party
Accident Date: 28/04/2022
TP Veh Reg No: SMR1169S

Chassis No: MR053REH104535931
Engine No: 1ZR521398
Reg. Date: 30/06/2015

Estimate Repair Cost to Vehicle No :SMK7838S

Description	U/Price	Quantity	Price	Amount
			S\$	S\$
30 TO KNOCK OUT DENTS, CUT/WELD REAR END PANEL, FENDER INNER PANEL, REMOVE, REPLACE ACCIDENT PARTS	1,200.00	1 JOB	1,200.00 ✓	
31 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,400.00	1 JOB	1,400.00 1200	
32 TO CHECK WIRING	40.00	1 JOB	40.00 20	
33 TO TUFF-KOTE	90.00	1 JOB	90.00 ✓	
34 TO 4 WHEEL ALIGNMENT	100.00	1 JOB	100.00 60	
35 TO REMOVE, REFIT REAR WINDSCREEN TO FACILITATE REPLACEMENT OF REAR FENDER	200.00	1 JOB	200.00 120	
36 TO REMOVE, REPLACE REAR EXHAUST	120.00	1 JOB	120.00 60	
37 TO TRANSFER DOOR AND DOOR FITTINGS	80.00	1 JOB	80.00 ✗	
38 TO REMOVE, REFIT/ REPLACE REAR BUMPER SENSOR	120.00	1 JOB	120.00 50	
39 TO REMOVE, REFIT END PANEL GARNISH TO FACILITATE REPAIRS	150.00	1 JOB	150.00 100	
			3,500.00	3,500.00
			Total 2900	S\$ 10,276.98
			Add GST @ 7%	719.39
			Total Amount Payable	S\$ 10,996.37

TOTAL: SINGAPORE DOLLAR TEN THOUSAND NINE HUNDRED NINETY SIX AND CENTS THIRTY SEVEN ONLY

For Progressive Car Care Pte Ltd

*Dear Lender - see from 065 005 -
 see check part by 10/1/2022*

mi

~~LKK Auto Consultants hence notify~~
AUTHORISED SIGNATURE

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

1-5096
 282
 3822
 S.N. 50
 1-2900
 6772

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
 3 Anson Road
 Springleaf Tower #16-00
 Singapore 079909
 TEL: 63896111 FAX: 6221033
 ATTN: Motor Claim Department \ CHINA


Estimate No: EST1508089
 Date: 09 Jun 2022
 Policy No: 5109583034-02
 Veh Reg No: SMK7838S
 Make/Model: TOYOTA TOYOTA
 COROLLA ALTIS 1.6L
 CVT
 Chassis No: MR053REH104535931
 Engine No: 1ZR521398
 Reg. Date: 30/06/2015

Your Ref No: TP 0422-6758
 Claim Type: Third Party
 Accident Date: 28/04/2022
 TP Veh Reg No: SMR1169S

Estimate Repair Cost to Vehicle No :SMK7838S

Description	U/Price	Quantity	Price S\$	Amount S\$
Supplementary Parts to Repair				
List Price				
1 REAR FENDER INNER TRIM - RH	393.20	1 PC	393.20 ✓	
2 REAR FLOOR PANEL TOP BOARD	282.80	1 PC	282.80 ✓	
3 REAR MUDFLAP - RH	65.90	1 PC	65.90 ✗	
			741.90	
		Less 25%	185.48	556.43
			Total	S\$ 556.43
			GST Amount	S\$ 38.95
			Total Amount Payable	S\$ 595.37

For Progressive Car Care Pte Ltd



AUTHORISED SIGNATURE

SUPP 556.43
 PARTS 335.00
 LAB 2900.00

 6771.43

1/3: 5400