

ASHER
FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

Not Authorised
HUI
5/5/22
2/5/22 3500/
4 days.

VEHICLE No: SJX 3092U

1PC	REAR BUMPER	904.00	0.5	\$1,315.10	✓
1PC	REAR BUMPER CENTRE BLACK GARNISH	466	0.5	\$488.90	✓
2PCS	REAR BUMPER SIDE INNER GARNISHS @\$285.10		1.1	\$570.20	X
2PCS	REAR BUMPER REFLECTORS @\$85.00	msnn	0.5	\$170.00	12C
2PCS	REAR BUMPER SIDE RETAINERS @\$65.00	msnn	0.5	\$130.00	12C
1PC	REAR BUMPER SPONGE	18x	0.5	\$199.80	✓
2PCS	REAR BUMPER PDC SENSORS @\$285.00		1.1	\$570.00	X
1PC	REAR END PANEL OUTER	715.50	0.5	\$899.10	✓
1PC	REAR END PANEL TOP GARNISH		1.1	\$468.90	X
2PCS	TAILLAMPS @\$1050.50 (white) 1020	msnn	0.5	\$2,101.00	12C
1PC	REAR EXHAUST		2	\$885.10	X
				\$7,798.10	

S.NETT

1SET	REAR BUMPER CLIPS	net	\$50.00	✓
1PC	REAR END PANEL SEALANT	net	\$50.00	✓

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REAR PDC SENSOR	\$80.00	50
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	\$100.00	80
TO DISMANTLE & REFIX REAR EXHAUST	1.1	\$100.00 X
TO SPRAY PROOFING	\$50.00	30
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$800.00	680
TO PUTTY & SPRAY PAINTING	\$1,000.00	850
TOTAL	\$10,078.10	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-3440.5
252
2580.37
1790
4390.37
202
3512