

ASS. REC. BY: Marcus

REF:

CS/AG122004149/49c

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1) 27/5/22

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format:

Lump Sum / I.B.I. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

) S + RS, SI

) Photos

) Others

TOTAL

24/5/22 4/5 @ 7400 insured Alan (Red \$ 25003.60, 772.7)

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

submit to us

not Authorized
5/5/22
4/5 @ 7400/
5 days.

VEHICLE No: SLU 8425C

1PC	REAR WINDSCREEN	11		\$1,488.10	X
1PC	REAR WINDSCREEN MOULDING	11	148.50	\$188.30	✓
1PC	TAILGATE	11	1365.10	\$1,685.10	✓
1PC	TAILGATE OUTER GARNISH	11		\$344.80	✓
1PC	TAILGATE REAR LOGO	11		\$168.50	✓
1PC	TAILGATE 'C-HR' EMBLEM	11		\$96.80	✓
1PC	TAILGATE 'HYBRID' EMBLEM	11		\$105.00	✓
2PCS	TAILGATE REFLECTORS @\$650.00	11		\$1,300.00	X
1PC	TAILGATE REAR WIPER ARM	11		\$188.90	X
1PC	TAILGATE REAR WIPER MOTOR	11		\$620.00	X
1PC	TAILGATE WEATHERSTRIP	11	392.10	\$488.90	✓
1PC	TAILGATE INNER LOCK	11	509.20	\$641.90	✓
1PC	TAILGATE LOCK STIRKER	11		\$60.00	X
1PC	TAILGATE INNER TRIM	11	605.10	\$811.60	✓
2PCS	TAILGATE INNER LOCK SENSOR @\$899.00	11		\$1,798.00	X
1PC	TAILGATE INNER HOLDER GARNISH	11		\$58.00	X
1PC	REAR BUMPER	11	545.10	\$1,215.10	✓
1PC	REAR BUMPER CENTRE BLACK GARNISH	11	425.10	\$488.90	✓
2PCS	REAR BUMPER SIDE REFLECTOR GARNISHS @\$285.10	11	1122.10	\$570.20	12C
2PCS	REAR BUMPER REFLECTORS @\$85.00	11		\$170.00	X
2PCS	REAR BUMPER SIDE RETAINERS @\$65.00	11		\$130.00	✓
1PC	REAR BUMPER SPONGE	11		\$199.80	X
2PCS	REAR BUMPER PDC SENSORS @\$285.00	11		\$570.00	✓
1PC	REAR END PANEL OUTER	11	680.10	\$899.10	✓
1PC	REAR END PANEL LOCK SENSOR	11		\$350.00	X
1PC	REAR END PANEL TOP GARNISH	11	392.50	\$468.90	✓
2PCS	TAILLAMPS @\$1050.50	11		\$2,101.00	X
2PCS	TAILLAMP HOUSING PANELS @\$650.30	11		\$1,300.60	X
1PC	REAR FENDER	11		\$1,205.10	X
2PCS	REAR FENDER INNER TRIM BOARDS @\$685.10	11		\$1,370.20	X
1PC	REAR FENDER OUTER PROTECTOR O/S	11		\$399.20	✓
1PC	REAR FLOOR PANEL	11		\$1,415.10	X
1PC	REAR FLOOR PANEL TOP BOARD	11	595.10	\$622.30	✓
2PCS	REAR FLOOR PANEL SIDE TOOL SPONGES @\$450.00	11		\$900.00	✓
1PC	REAR bumper Beam	11	420.10	\$520.80	✓
1PC	REAR EXHAUST	11		\$885.10	X
1PC	REAR EXHAUST HEAT SHIELD	11		\$188.30	✓
				\$26,013.60	

S.NETT

257

1SET	REAR BUMPER CLIPS	nee	\$50.00	✓
1PC	REAR WINDSCREEN SEALANT	nee	\$50.00	40
1PC	REAR WINDSCREEN INNER SEAL	nee	\$50.00	40
1PC	REAR END PANEL SEALANT	nee	\$50.00	✓
1SET	TAILGATE INNER TRIM CLIPS	nee	\$50.00	✓
1SET	REAR FLOOR PANEL INSULATOR	17	\$450.00	X
1SET	REAR FENDER INNER TRIM BOARD CLIPS	17	\$50.00	X
1SET	REAR REVERSE CAMERA	17	\$380.00	X

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REAR PDC SENSOR	\$80.00	50
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	120
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	\$100.00	50
TO DISMANTLE & REFIX REAR EXHAUST	17 \$100.00	X
TO TRANSFER TAILGATE MECHANISM	\$100.00	60
TO SPRAY PROOFING	\$180.00	60
TO MOUNT VEHICLE ON CAR O-LINER	17 \$380.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$2,000.00	800
TO PUTTY & SPRAY PAINTING	\$2,000.00	1000
TOTAL	\$32,403.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-9077.4
252
P-6808.05
S.N 230
1-2240

9278.05
202
7422