

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 04.05.2022

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : SMD434G
MODEL : HYUNDAI ELANTRA
DATE OF ACCIDENT : 02.05.2022
TIME OF ACCIDENT : 16:00HRS

KMH17841CMJ4717298

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dehd</i>	1	\$ 570.40	\$ 570.40
2	REAR BUMPER REFLECTOR LH <i>new</i>	1	\$ 32.50	\$ 32.50
3	REAR BUMPER LOWER LIP <i>Dehd</i>	1	\$ 250.10	\$ 250.10
4	REAR BUMPER RETAINER <i>LH Pangel</i>	2	\$ 44.30	\$ 88.60
5	REAR BUMPER INNER GRANISH LH <i>Dehd new</i>	1	\$ 137.50	\$ 137.50
6	BOOTLID LAMP LH <i>Cut</i>	1	\$ 298.80	\$ 298.80
7	BOOTLID WEATHER STRIP <i>new</i>	1	\$ 109.61	\$ 109.61
8	TAILLAMP LH <i>Crushed</i>	1	\$ 876.80	\$ 876.80
9	TAILLAMP PANEL LH <i>Dented</i>	1	\$ 197.40	\$ 197.40
10	REAR FENDER LH <i>Buckled</i>	1	\$ 1,890.50	\$ 1,890.50
11	REAR FENDER AIR VENT LH <i>Crushed</i>	1	\$ 107.40	\$ 107.40
12	REAR FENDER INNER COWLING LH <i>Alum torn</i>	1	\$ 146.80	\$ 146.80
13	REAR FENDER INNER TRIM LH <i>new</i>	1	\$ 279.80	\$ 279.80
14	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 186.30	\$ 186.30
15	REAR WHEEL RIM LH <i>new</i>	1	\$ 850.00	\$ 850.00

4214.60

3371.68

TOTAL PRICE \$ 6,022.51
LESS 20% \$ 1,204.50
SUB TOTAL PRICE \$ 4,818.01

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER INNER GRANISH CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
4	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
5	REAR FENDER RH SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00
6	REAR FENDER INNER COWLING RH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
7	REAR FENDER INNER TRIM RH CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SMD434G
 MODEL : HYUNDAI ELANTRA
 DATE OF ACCIDENT : 02.05.2022
 TIME OF ACCIDENT : 16:00HRS

8	REAR WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00
9	REAR WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00

TOTAL \$ 450.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	600
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	500
3	TUFF COAT	\$ 250.00	50
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x
8	REMOVE AND REFIX REAR FUEL TANK	\$ 120.00	80
9	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	✓
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	x

TOTAL \$5,130.00

ESTIMATE REPORT

TOTAL PARTS COST : \$
 TOTAL LABOUR COST : \$
 TOTAL REPAIR COST : \$

LKK51268 Consultants hence notify the Repairs of the following:

- To respray before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES Subject to final approval from Insurance Company

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

Acknowledged by

Signature

Date

Adrian L
 c/s 05/05/22.

05 Days.

Total: 5031.68.

H/S: AK.

1490

40 170
30