ASS. REC. BY: Steve CS/CT12	2004154/EVC
ASS	BIGNMENT
From: Date:	Veh No: SMK / /8 Cyr Regn: 18/11/18
Estimated Cost:	Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD TPIWS ITP RES I OD RES I EVA I INV I MV	Truck / Trailer or
To Inspect Vehicle No:	Make: PONSChe Panamera co 12995
at Workshop m/s	Colour RIGCK A/C: Insured / Std / NI / NA
of	Sp.Reading 51917 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: WP02224775LIMVS4
Claims No.	Gen. Cond: 6000 / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Ingrde / Jammed / Leaked / Burnit or
Make of Veh:	Modi: Nii / SKith / STD A/Rim or
1 Dex	Tyre Size: F: 3/5/35 LK LB
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA (MIC / OHTSU / PIR / SUMI /
Bal. or Market Value:	<i></i>
	Fron! Rear R/Bal. mm R/Bal. mm
DAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No	UBal. U mm UBal. U mm
	D.O.A. 22.11) 127 D.O.I. 5/5/27
Est Repairs: days Res.: Yes or No Lum Sum: % 3 Val.: Yes or No	Survey held at
	Des. of Damages (Frt Rear O/S N/S U/C Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN/	-
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
N/- 11/5 A	
6/5/22 Steve said my change to \$400	K
¥ .	
Date/Time, File Pass to? : Prell. Report	Days Of Repair:
	Resurvey No. of Trip: Survey Fee:
Date/Time, File Refum to?	Transportation:
	d Fee: : Sife Insp (\$)_s+Rs_si
. ————	: Interview (\$) Photos
Report Formet:	: Tech, Invs (\$) Others
Lump Sum / LP.f: (\$)	:Weelland (%)
	TOTAL
. · ·	
$t_{i} = k_{i} c_{i}$	



STUTTGART AUTO PTE LTD 27A TANJONG PENJURU, SINGAPORE 60904; (6) ELROKARS CPO!

ESTIMATE COST OF REPAIRS

CHINA	A TAIPING INSURANCE (SINGAPO	RE) (NAME :				-	WIP:		30035
3 Anso	on Road	ADDRESS:					EXCESS:		
16-00	Springleaf Tower						DATE:		4-May-22
	ore 079909								
ATTN.		TEL:							
FAX :								_	
VEH N	io: SMK778C	DATE IN :		CONTACT PERSON:			DEREK		63310683
CHASS	SIS NO: WPOZZZ97ZJL119034	MILEAGE :		TYPE OF CLAIM:			OWN DAMAGE		IAGE
MODE	EL: Panamera	DATE REG.:	18-Dec-18	POLICY NO. :					
			NATURE OF	WORKS					
s/no		Pai	ts Descriptio	<u>n</u>				_	
			QTY		1ST	SUPP	REVISED	_	PRICES
1	FRONT BUMPER / 00		1,	P971-898-010				\$	2,346.70
2	FRONT BUMPER LOWER SPOILER	c nat c	1	P971-807-541OK1				\$	754.50
3	FRONT GRILLE CENTER / (M)		1	P971-807-683OK1				\$	310.30
4	GRILLE LH	7	1	P971-807-681OK1				\$	135.40
5	GRILLE RH	?	1	P971-807-682OK1				\$	135.40
6	INSERT TRIM LH	"	1	P971-807-485OK1				\$	104.20
7	INSERT TRIM RH	7	1	P971-807-486OK1				\$	104.20
8	SUPPORT DISC LH	7	1	P971-807-985OK1				\$	99.10
9	SUPPORT DISC RH	1	1	P971-807-986OK1				\$	99.10
10	DISCLH - CUT		1	P971-807-877OK1		-		\$	133.90
11	DISC RH - CUT		1	P971-807-878OK1				\$	133.90
12	SENSOR		4	P5Q0-919-275-B -G2X	-			\$	1,056.80
13	SENSOR GASKET / N(22	4	P5Q0-919-1339B9		-		\$	13.20
14	NUMBER PLATE BRACKET	RK	1	P971-807-999OK1		-		\$	89.10
15	SPEED NUT / No		5	P9A7-007-380-00-		-		\$	14.00
16	FOAM PART LH		1	P971-807-251	_	\vdash		\$	59.20
17	FOAM PART RH		1	P971-807-252	-			\$	59.20
18	FRONT BUMPER REINFORCEMENT	•	1	P971-805-241-E -	_			\$	1,153.50 88.00
19	FRONT BUMPER SPONGE		1	P971-807-550	-	-		\$	794.20
20	ADDITIONAL READLAMIP LIT	'UT	1	P971-953-041-H -	-			5	2,563.30
21	REAR BUMPER / IT	00	1	P971-807-983- Y-	-			\$	1,107.60
22	REAR BUMPER LOWER SPOILER	- BR	1	P971-807-514- Y-	-	\vdash		5	173.10
23	EXHAUST TRIM LH		1	P971-807-951OK1	-			\$	173.10
24	EXHAUST TRIM RH / nee		1	P971-807-952OK1	1	-		5	528.40
25	SENSOR OUTER		2	P5Q0-919-275-B-G2X	1			5	528.40
-	SENSOR INNER		2	P5Q0-919-275-C -G2X	-	-		5	13.20
27	SENSOR GASKET / NC		4	P5Q0-919-1339B9	-	-		\$	9.20
	SPEED NUT / MC	4.10	4	PN -912-425-01-	+	-		5	325.10
29	REAR BUMPER SOUND ABSORBER LH	1 pec	1	P971-825-477		1		1,	525.10

NO	DESCRIPTION	30.7	QTY PARTS NO	1st Supp	REVISED		PRICES
		CHDD	TOTAL PARTS COST			\$	26,973.00
						\$	•
			TOTAL PARTS	\Box		\$	26,973.00
69		0	0			\$	
	LPIPERH / DT	1	P9A7-253-824-50-			\$	814.40
	S-HEAD SCREW	1	P9A7-008-019-00-			\$	3.40
	ED NUT	1	PN -903-425-02-			\$	2.40
	KAGON-HEAD BOLT	2	PN -909-210-02-			\$	4.60
	PPORT	1	P9A7-253-277-00-			\$	62.70
	(AGON-HEAD BOLT	2	PN -910-793-01-			\$	3.40
	UT BRACE	1	P9A7-253-521-00-			\$	43.20
	KAGON-HEAD BOLT	2	PN -910-793-01-			\$	3.40
	PPORT - A	1	P9A7-253-245-10-			\$	78.70
-	AR MUFFLER BH	1	P971-253-608- Y-			\$	3,183.70
	AMPING SLEEVE EXHAUŞT SYSTEM (WB43)	1	P958-111-220-00-			\$	102.90
	AT SHIELD RH	1	P971-804-170-E -			\$	165.40
	EED NUT / M	10	PN -912-475-01-			\$	19.00
	AR LIGHT REFLECTOR RH AR UNDERCOVER CENTER TI	1	P971-825-505			\$	500.10
	AR LIGHT REFLECTOR EN	1	P971-945-105-C - P971-945-106-C -			\$	82.80
	ENSE PLATE LIGHT	1	P958-631-620-11-			\$	82.80
51 CUI		10	P8X0-867-276-A -			\$	16.00
50 WA	ATER DRAIN STRIF	1	P971-854-327-A -			\$	63.80
	CORATIVE FILM BLACK ADHESIVE / //	1	P971-853-041-A -OK1			\$	45.40
	OND ABSORBER FIECE RIT	1	P971-827-786-A -			\$	13.20
47 500	UND ABSORBER PIECE LH / MC	1	P971-827-785-C -	-		\$	13.2
46 BUI	NGS / PC	6	PPAF-010-113	_		\$	12.0
45 GAS	SKET RH / NC	1	P971-827-460-C -			\$	233.2
44 GAS	SKET LH / M-	1	P971-827-459-C -			\$	233.2
43 GAS	SKET CENTER UPPER / MC	1	P971-827-594			\$	218.5
42 P00	00-043-305-51-/CAVITY PRESERVATION (AK //K	1	PV04-015-001-AG-			\$	72.4
41 STO	OPPER / NC	7	P9A7-007-983			\$	27.3
40 TAIL	LGATE / DD	1	P971-827-025-CY-GRV			\$	4,569.1
	AR BUMPER REINFORCEMENT	1	P971-803-184			\$	1,157.4
	ND RIVET / PL	15	P9A7-911-603-01-			\$	31.5
	L LIGHT BRACKET RH	1	P971-807-126-A -			\$	86.2
	L LIGHT BRACKET LH	1	P971-807-125			\$	86.2
_	PPORT BRACKET FOR UNDERCOVER RH	1	P971-825-200			\$	58.3
-	PORT BRACKET FOR UNDERCOVER LH	1	P971-807-332-C - P971-825-199		The second secon	\$	58.3
-	PORT BRACKET FOR BUMPER LH	1	P971-807-331-C -			5	574.7
	R BUMPER CENTER BRACKET	1	P971-807-863-A -			\$	574.7
-	R BUMPER SOUND ABSORBER RH MC	1	P971-825-478		Mathematical residence of the second of the second	\$	325.1 137.7

1		
		_
Labour Description		
	BODY 1569	\$ 3,120.00
1 TO REMOVE /REPLACE FRT BUMPER, REINFORCEMENT & ALL ACCIDENT DAMAGED	BODY 1503	3 3,120.00
PARTS ON THE FRONT PORTION. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	r,	
	3120	5 6,240.00
2 TO REMOVE / REPLACE TAILGATE, REAR BUMPER, REINFORCEMENT & ALL ACCIDEN		, , , , , , , , , , , , , , , , , , , ,
DAMAGED BODY PARTS ON REAR PORTION. TO REPAIR REAR END PANEL & ALL ARI	EAS	
AFFECTED BY THE ACCIDENT.		
1797 (187)	3709	\$ 5,500.00
3 TO RESPRAY FRT BUMPER, TAILGATE, REAR BUMPER, REAR END PANEL.	3705	7
THE POPULATION OF THE POPULATION	150	\$ 250.00
4 TO CARRY-OUT BODY CAVITY PRESERVATION.	100	
5 TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE	(Ohol) 399	\$ 500.00
	4')	
REPAIR ON THE REAR SECTION.		
6 TO SUPPLY FRONT & REAR LICENCE PLATE WITH CASING (SPECIAL)	NETT	\$ 300.00
6 TO SUPPLY FRONT & REAR LICENCE PLATE WITH CASING (SPECIAL)		
7 TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	NETT	\$ 1,560.00
7 TO REMOVE & RELEASE THE RESIL ENGINEERS.		
8 TO TRANSFER THE TAILGATE MECHANISM.	NETT	\$ 780.00,
6 TO THAT IS THE THE STATE OF T		
9 TO REMOVE & REFIT THE REAR WINDSCREEN GLASS.	NETT	\$ 560.00
10 TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.	NETT	\$ 195.00
	700	
11 TO TRANSFER THE FRONT & REAR SENSORS. 150 X2	700	\$ 500.00
	000	
12 TO TRANSFER THE REVERSE CAMERA.	200	\$ 300.00
13 TO INSTALL THE BODY WRAP STICKER (PRICE TO BE ADVISE)	NETT	
14 TO APPLY SPECIAL CERAMIC COATING. (PRICE TO BE ADVISE)	NETT	
		\$ 250.00
TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		3 230.00
	NETT	\$ 600.00
16 TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT	3 000.00
	NETT	s 250 300.00
17 TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	- NETT	7 70 555.55
	NETT	\$ 0 - 50.00
18 SUNDRIES.	- REII	\$ 29 50.00

GRAND TOTAL	\$	\$ 51,336.46
GST 7%	\$	\$ 3,358.46
TOTAL AFTER EXCESS	\$	\$ 47,978.00
LESS EXCESS	\$	\$
TOTAL	\$	\$ 47,978.00
TOTAL PARTS	\$	\$ 26,973.00
TOTAL LABOUR	\$	\$ 21,005.00

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Steve CLKK)

Steve CLKK)

EXCE, 5-?

P/P

Modely

8 45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: