

ASS. REC. BY:

Steve

CS/CT/22004154/EVC

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. DMPCSNA00248302101Claims No. SNM22D202812/C01/TANKLSum Insured: \_\_\_\_\_ Excess: 2500

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Bel. or Market Value: \_\_\_\_\_

DAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SMK 778C Yr Regn: 18/12/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Porsche Panamera c.c. 2995Colour: Black A/C: Insured / Std / NI / NASp. Reading: 51947 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WP 02229775L119034

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 315/35ZR20R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal. 4 mm R/Bal. 4 mmL/Bal. 4 mm L/Bal. 4 mmD.O.A. 22/12/22 D.O.I. 5/5/22Survey held at StuttgartDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

M/K #75K \$400k28/9/22 Steve informed final fig \$54,334.40 (Red 13,416.80, 20%)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

2) 30/9/22-typistReport Format: MerimenLump Sum / I.C.F. (\$) \$54,334.40Days Of Repair: 13Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS \$ \_\_\_\_\_

Photos

Others

TOTAL





STUTTGART AUTO PTE LTD  
27A TANJONG PENJURU, SINGAPORE 60904; EUROKARS  
ESTIMATE COST OF REPAIRS

PORSCHE

<b>CHINA TAIPING INSURANCE (SINGAPORE)</b>		<b>NAME :</b>		<b>WIP :</b> 30035	
3 Anson Road		<b>ADDRESS :</b>		<b>EXCESS :</b>	
#16-00 Springleaf Tower				<b>DATE:</b> 4-May-22	
Singapore 079909		<b>TEL :</b>			
<b>ATTN. :</b> MOTOR CLAIMS					
<b>FAX :</b>					
<b>VEH NO :</b>	SMK778C	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>	DEREK 63310683
<b>CHASSIS NO :</b>	WP0ZZZ97JL119034	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>	OWN DAMAGE
<b>MODEL :</b>	Panamera	<b>DATE REG.:</b>	18-Dec-18	<b>POLICY NO. :</b>	
<b>NATURE OF WORKS</b>					
<b>S/NO</b>	<b>Parts Description</b>			<b>1ST</b>	<b>SUPP</b>
	<b>QTY</b>			<b>REVISED</b>	<b>PRICES</b>
1	FRONT BUMPER / <i>OD</i>	1	P971-898-010- -		\$ 2,346.70
2	FRONT BUMPER LOWER SPOILER <i>X</i> <i>MM (info)</i>	1	P971-807-541- -OK1		\$ 754.50
3	FRONT GRILLE CENTER <i>- CUT</i>	1	P971-807-683- -OK1		\$ 310.30
4	GRILLE LH <i>?</i>	1	P971-807-681- -OK1		\$ 135.40
5	GRILLE RH <i>?</i>	1	P971-807-682- -OK1		\$ 135.40
6	INSERT TRIM LH <i>?</i>	1	P971-807-485- -OK1		\$ 104.20
7	INSERT TRIM RH <i>?</i>	1	P971-807-486- -OK1		\$ 104.20
8	SUPPORT DISC LH <i>?</i>	1	P971-807-985- -OK1		\$ 99.10
9	SUPPORT DISC RH <i>?</i>	1	P971-807-986- -OK1		\$ 99.10
10	DISC LH <i>- CUT</i>	1	P971-807-877- -OK1		\$ 133.90
11	DISC RH <i>- CUT</i>	1	P971-807-878- -OK1		\$ 133.90
12	SENSOR <i>?</i>	4	P5Q0-919-275-B -G2X		\$ 1,056.80
13	SENSOR GASKET <i>- MC</i>	4	P5Q0-919-133- -9B9		\$ 13.20
14	NUMBER PLATE BRACKET <i>- BR</i>	1	P971-807-999- -OK1		\$ 89.10
15	SPEED NUT <i>- MC</i>	5	P9A7-007-380-00-		\$ 14.00
16	FOAM PART LH <i>- MC</i>	1	P971-807-251- -		\$ 59.20
17	FOAM PART RH <i>- MC</i>	1	P971-807-252- -		\$ 59.20
18	FRONT BUMPER REINFORCEMENT <i>?</i>	1	P971-805-241-E -		\$ 1,153.50
19	FRONT BUMPER SPONGE <i>?</i>	1	P971-807-550- -		\$ 88.00
20	ADDITIONAL HEADLAMP LH <i>- CUT</i>	1	P971-953-041-H -		\$ 794.20
21	REAR BUMPER <i>- BR</i>	1	P971-807-983- Y-		\$ 2,563.30
22	REAR BUMPER LOWER SPOILER <i>- BR</i>	1	P971-807-514- Y-		\$ 1,107.60
23	EXHAUST TRIM LH <i>- MC</i>	1	P971-807-951- -OK1		\$ 173.10
24	EXHAUST TRIM RH <i>- MC</i>	1	P971-807-952- -OK1		\$ 173.10
25	SENSOR OUTER <i>?</i>	2	P5Q0-919-275-B -G2X		\$ 528.40
26	SENSOR INNER <i>?</i>	2	P5Q0-919-275-C -G2X		\$ 528.40
27	SENSOR GASKET <i>- MC</i>	4	P5Q0-919-133- -9B9		\$ 13.20
28	SPEED NUT <i>- MC</i>	4	PN -912-425-01-		\$ 9.20
29	REAR BUMPER SOUND ABSORBER LH <i>- MC</i>	1	P971-825-477- -		\$ 325.10



30	REAR BUMPER SOUND ABSORBER RH	1	P971-825-478- -			\$	325.10
31	REAR BUMPER CENTER BRACKET	1	P971-807-863-A -			\$	137.70
32	SUPPORT BRACKET FOR BUMPER LH	1	P971-807-331-C -			\$	574.70
33	SUPPORT BRACKET FOR BUMPER RH	1	P971-807-332-C -			\$	574.70
34	SUPPORT BRACKET FOR UNDERCOVER LH	1	P971-825-199- -			\$	58.30
35	SUPPORT BRACKET FOR UNDERCOVER RH	1	P971-825-200- -			\$	58.30
36	TAIL LIGHT BRACKET LH	1	P971-807-125- -			\$	86.20
37	TAIL LIGHT BRACKET RH	1	P971-807-126-A -			\$	86.20
38	BLIND RIVET	15	P9A7-911-603-01-			\$	31.50
39	REAR BUMPER REINFORCEMENT	1	P971-803-184- -			\$	1,157.40
40	TAILGATE	1	P971-827-025-CY-GRV			\$	4,569.10
41	STOPPER	7	P9A7-007-983- -			\$	27.30
42	P000-043-305-51-/CAVITY PRESERVATION (AK	1	PV04-015-001-AG-			\$	72.40
43	GASKET CENTER UPPER	1	P971-827-594- -			\$	218.50
44	GASKET LH	1	P971-827-459-C -			\$	233.20
45	GASKET RH	1	P971-827-460-C -			\$	233.20
46	BUNGS	6	PPAF-010-113- -			\$	12.00
47	SOUND ABSORBER PIECE LH	1	P971-827-785-C -			\$	13.20
48	SOUND ABSORBER PIECE RH	1	P971-827-786-A -			\$	13.20
49	DECORATIVE FILM BLACK ADHESIVE	1	P971-853-041-A-OK1			\$	45.40
50	WATER DRAIN STRIP	1	P971-854-327-A -			\$	63.80
51	CLIP	10	P8X0-867-276-A -			\$	16.00
52	LICENSE PLATE LIGHT	1	P958-631-620-11-			\$	107.40
53	REAR LIGHT REFLECTOR LH	1	P971-945-105-C -			\$	82.80
54	REAR LIGHT REFLECTOR RH	1	P971-945-106-C -			\$	82.80
55	REAR UNDERCOVER CENTER	1	P971-825-505- -			\$	500.10
56	SPEED NUT	10	PN -912-475-01-			\$	19.00
57	HEAT SHIELD RH	1	P971-804-170-E -			\$	165.40
58	CLAMPING SLEEVE EXHAUST SYSTEM (WB43)	1	P958-111-220-00-			\$	102.90
59	REAR MUFFLER RH	1	P971-253-608-Y-			\$	3,183.70
60	SUPPORT	1	P9A7-253-245-10-			\$	78.70
61	HEXAGON-HEAD BOLT	2	PN -910-793-01-			\$	3.40
62	STRUT BRACE	1	P9A7-253-521-00-			\$	43.20
63	HEXAGON-HEAD BOLT	2	PN -910-793-01-			\$	3.40
64	SUPPORT	1	P9A7-253-277-00-			\$	62.70
65	HEXAGON-HEAD BOLT	2	PN -909-210-02-			\$	4.60
66	SPEED NUT	1	PN -903-425-02-			\$	2.40
67	LENS-HEAD SCREW	1	P9A7-008-019-00-			\$	3.40
68	TAIL PIPE RH	1	P9A7-253-824-50-			\$	814.40
69		0	0			\$	-
TOTAL PARTS						\$	26,973.00
						\$	-
TOTAL PARTS COST						\$	26,973.00
SUPPLEMENTARY							
NO	DESCRIPTION	QTY	PARTS NO	1st	Supp	REVISED	PRICES







TOTAL LABOUR		\$ -	\$ 21,005.00
TOTAL PARTS		\$ -	\$ 26,973.00
TOTAL		\$ -	\$ 47,978.00
LESS EXCESS		\$ -	\$ -
TOTAL AFTER EXCESS		\$ -	\$ 47,978.00
GST 7%		\$ -	\$ 3,358.46
GRAND TOTAL		\$ -	\$ 51,336.46

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Steve (LKK)  
5/5/22 4.00pm

OD-MH  
EXCESS?  
P/P  
My Policy  
8 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: