



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22004159/Kqcn2	
			Date: 17/06/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBL 1760X	Veh. Inspected	SLX 2675X
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2201530/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	05/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	GP71120454	Colour	METALLIC BLACK
	Odometer	205853 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/65 R16	DUNLOP	8 mm
	L/H Front Tyre	185/65 R16	DUNLOP	8 mm
	R/H Rear Tyre	185/65 R16	DUNLOP	8 mm
	L/H Rear Tyre	185/65 R16	DUNLOP	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/05/2022	Inspection Date	09/05/2022
	Survey held at	SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	