

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 64517420

ESTIMATE

LEE AN, EDWARD
c/o 46 Lenton Plain
Singapore 786548

*Not Authorised
11 Days @ 3600ph
Painting After Rain
4 days*

Date: 7/5/2022

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: HONDA SHUTTLE / SLX 2675 X		
1 pc	rear bumper <i>936.50</i>	<i>Am</i> 958.30 ✓
2 pcs	rear bumper reflector @ 137.60	<i>Sm</i> 275.20 X
2 pcs	rear bumper reflector garnish @ 216.70	<i>Sm</i> 433.40 X
1 pc	rear bumper tow cover	<i>Sm</i> 65.80 X
1 pc	rear boot lid <i>1193</i>	<i>R</i> 1,643.10 ✓
1 pc	rear boot chrome outer garnish <i>288.50</i>	<i>scr</i> 347.10 ✓
1 pc	rear boot emblem "SHUTTLE" <i>55</i>	<i>am</i> 87.60 ✓
1 pc	rear boot emblem "HYBRID" <i>45</i>	<i>am</i> 75.10 ✓
1 pc	rear boot emblem logo H <i>38</i>	<i>am</i> 66.40 ✓
1 pc	rear boot inner trim <i>320.40</i>	<i>mgms</i> 443.70 ✓
1 pc	rear boot lock	<i>R</i> 221.50 X
1 pc	rear boot lock catch	<i>R</i> 76.50 X
1 pc	rear end panel	<i>R</i> 598.40 X
1 pc	rear end panel top garnish <i>204.30</i>	<i>mg ori</i> 269.60 ✓
1 pc	rear windscreen glass moulding <i>116</i>	<i>am</i> 195.00 ✓
Sub-Total		5,756.70
less 20%		1,151.34
sub-total		4,605.36
1 set	reverse sensor s.nett	<i>phot</i> 220.00 <i>2005m</i>
1 pc	number plate s.nett	<i>Sm</i> 55.00 X
1 pc	number plate casing - carbon fiber s.nett	<i>Sm</i> 60.00 X
1 pc	boot rubber strip s.nett	<i>Sm</i> 35.00 X
2 tubes	windscreen glass sealant s.nett @ 60.00	<i>am</i> 120.00 <i>405m</i>
To remove and replace the parts mentioned above, panel beat and align the necessary affected areas.		1,000.00 <i>500</i>
To apply putty and spray painting on affected areas.		950.00 <i>600</i>
sub-total		7,045.36

0001 02 on 4159/ke |

balance brought forwards.

7,045.36

To check wiring system.

50.00 20

To apply rust proofing on affected areas.

150.00 301

To apply waterproof sealant on affected areas.

150.00 301

To apply putty and spray painting on affected areas.

Repair 110.00 X

To install reverse sensors.

80.00 50

To remove / refit rear windscreen glasses to enable repair.

150.00 1201

To remove / refit carpet, trimming and seats to enable repair.

100.00 501

Total

7,835.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

EE AN, EDWARD
46 Lenton Plain
Singapore 786548

Date: 11/5/2022

QUANTITY	PARTICULARS	AMOUNT (\$)
	<u>RE: HONDA SHUTTLE / SLX 2675 X/SUPPLEMENTARY</u>	
cc	Rear Boot Lamp LH <i>1-2 398</i>	<i>Sen</i> 764.30 ✓
	Sub-total	764.30
	Less 20%	152.86
	Total:	611.44