

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST-M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAY LING FONG
110 SELETAR GREEN VIEW

SINGAPORE 805089

ATTN:

Your Ref No: SCY6968B
Claim Type: Third Party → *Aliman*
Accident Date: 25/04/2022
TP Veh Reg No: SLT6038E

Estimate No: MC1902640
Date: 27 Apr 2022
Policy No: MT/00970642
Veh Reg No: SCY6968B
Make/Model: TOYOTA CAMRY 2.0
AUTO

*LKIC
3-330pm*

*Not Notarise
Recovery After Pain*

@ 1088.70

2 day

Estimate Repair Cost to Vehicle No :SCY6968B

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 REAR DOOR RH	1 PC	1,597.40	X
2 REAR DOOR RUBBER (AT DOOR) RH	1 PC	217.30	X
3 REAR DOOR RUBBER (AT DOOR) BTM RH	1 PC	79.50	X
4 REAR DOOR RUBBER (AT BODY) RH	1 PC	310.60	X
5 REAR DOOR LOCK RH	1 PC	595.70	X
6 SIDE SKIRT RH	1 PC	633.30	X
7 SIDE SKIRT CLIPS	7 PC	80.50	X
8 REAR FENDER RH	1 PC	1,137.00	X
9 REAR FENDER COWLING RH	1 PC	202.20	X
10 REAR FENDER COWLING CLIPS	8 PC	36.00	X
11 REAR WINDSCREEN MLDG	1 PC	967.20	X
12 REAR WINDSCREEN MLDG BTM - CHECK PRICE	1 PC	0.00	X
13 REAR BUMPER	1 PC	695.80	✓
14 REAR BUMPER REFLECTOR RH	1 PC	63.40	X
15 REAR BUMPER SIDE RETAINER RH	1 PC	117.40	✓
16 REAR BUMPER CLIPS	8 PC	38.40	✓
17 REAR BUMPER REINFORCEMENT	1 PC	423.90	X
18 REAR AIR VENT RH	1 PC	144.90	X
		7,340.50	
	Less 25%	1,835.13	5,505.38
Special Nett			
19 INNER SEAL	1 PC	20.00	X
20 WINDSCREEN SEALANT	1 PC	40.00	✓
21 PARKIGN SENSOR 4-IN-1 SET	1 PC	400.00	X
		460.00	460.00
LABOUR			
22 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	X
23 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	X
24 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.	1 PC	120.00	X
25 TO REMOVE AND REINSTALL/REPLACE QUARTER GLASS.	1 PC	60.00	X
26 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	180.00	X

Zila
Ah Lim Motor Company

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAY LING FONG
110 SELETAR GREEN VIEW

SINGAPORE 805089

ATTN:

Estimate No: MC1902640
Date: 27 Apr 2022
Policy No: MT/00970642
Veh Reg No: SCY6968B
Make/Model: TOYOTA CAMRY 2.0
AUTO

Your Ref No: SCY6968B
Claim Type: Third Party
Accident Date: 25/04/2022
TP Veh Reg No: SLT6038E

Estimate Repair Cost to Vehicle No :SCY6968B

Description	Quantity	List Price	Amount
		SS	SS
27 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	501
28 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	X
29 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR FENDER RH.TO KNOCK & REPAIR REAR WHEELHOUSE PANEL RH,REAR END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	2001
30 TO SPRAY REAR DOOR RH,SIDE SKIRT RH,REAR FENDER RH,REAR BUMPER,REAR END PANEL.	1 PC	1,000.00	2001
		2,480.00	2,480.00
		Total	SS 8,445.38
		Add GST @ 7%	591.18
		Total Amount Payable	SS 9,036.56

TOTAL: SINGAPORE DOLLAR NINE THOUSAND THIRTY SIX AND CENTS FIFTY SIX ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Zila
Ah Lim Motor Company

AUTHORISED SIGNATURE