

Date : 4 MAY 2022

**ALLIANZ Insurance Singapore Pte Ltd**  
 Attn: Motor Claims Department

Vehicle number : **SLZ 746 C**  
 Make and model : I30 1.4 GLS 5DR DCT TURBO  
 Registration Date : 23/04/2018  
 Chassis number : TMAH3513VJJ064981  
 Engine number : G4LDHD120582

Job No. :  
 Owner name : Tan Jing Felix  
 Date of Acc : 29/04/2022  
 Policy number : SP2001255858-01  
 Claim Type : **OD-Excess TBC**

Items :	Estimate
1 BUMPER CLIP X10	86595-2T500 \$ 12.00
2 UPPER GRILLE CLIP X6	14206-08250B \$ 3.60
3 GRILLE-RADIATOR	86351-G4010 \$ 480.20
4 CR PIECE 1-RADIATOR GRILLE	86355-G4100 \$ 255.90
5 STRIP ASSY-FR BUMPER UPR	86357-G4000 \$ 64.89
6 EMBLEM-SYMBOL MARK	86300-G4100 \$ 26.10
7 COVER-RADIATOR GRILLE,UPR	86362-G4000 \$ 150.44
8 COVER-FR BUMPER	86511-G4000 \$ 836.64
9 GRILLE-FRONT BUMPER	86561-G4000 \$ 123.41
10 BRACKET-FR BUMPER SIDE,LH	86513-G4000 \$ 74.93
11 BRACKET-FR BUMPER SIDE,RH	86514-G4000 \$ 74.93
12 MOULDING-FRT BPR LICENSE PLATE	86519-G4000 \$ 41.83
13 ABSORBER-FRONT BUMPER ENERGY	86520-G4050 \$ 224.91
14 COVER-FR BUMPER FOG LAMP,LH	86563-G4040 \$ 88.99
15 COVER-FR BUMPER FOG LAMP,RH	86564-G4040 \$ 88.99
16 BRACKET-FRT BUMPER MOUNTING,LH	86553-G4000 \$ 44.75
17 BRACKET ASSY-FR BUMPER UPR SUP X2	86556-F2000 \$ 16.80
18 BRACKET-FRT BUMPER MOUNTING,RH	86554-G4000 \$ 44.75
19 PIECE-RADIATOR GRILLE NO.2	86353-G4000 \$ 158.30
20 PIECE-RADIATOR GRILLE NO.3	86354-G4000 \$ 112.86
21 GARNISH-RADIATOR GRILLE,UPR	86356-G4000 \$ 73.90
22 DUCT ASSY-AIR CURTAIN,LH	86567-G4030 \$ 47.68
23 DUCT ASSY-AIR CURTAIN,RH	86568-G4030 \$ 47.68
24 STIFFNER-FR BPR LWR	86571-G4000 \$ 174.25
25 CAP ASSY-FR BPR	86588-G4000 \$ 24.84
26 LIP ASSY-FRONT BUMPER	86591-G4000 \$ 161.80
27 LAMP ASSY-FRONT FOG,LH	92201-G4000 \$ 265.10
28 LAMP ASSY-FRONT FOG,RH	92202-G4000 \$ 265.10
29 LAMP ASSY-DAY RUNNING LIGHT,LH	92207-G4100 \$ 642.50
30 LAMP ASSY-DAY RUNNING LIGHT,RH	92208-G4100 \$ 642.50

Vehicle number : **SLZ 746 C**  
 Make and model : I30 1.4 GLS 5DR DCT TURBO  
 Registration Date : 23/04/2018  
 Chassis number : TMAH3513VJJ064981  
 Engine number : G4LDHD120582

Job No. :  
 Owner name : Tan Jing Felix  
 Date of Acc : 29/04/2022  
 Policy number : SP2001255858-01  
 Claim Type : **OD-Excess TBC**

Items :		Estimate
31	LAMP ASSY-HEAD,LH	92101-G4030 \$ 1,686.80
32	LAMP ASSY-HEAD,RH	92102-G4030 \$ 1,686.80
33	BEAM COMPLETE-FR BUMPER	64900-G4000 \$ 636.40
34	CARRIER ASSY-FRONT END MODULE	64101-G4000 \$ 1,332.76
35	HORN ASSY-LOW PITCH	96610-G3000 \$ 73.50
36	PANEL ASSY-HOOD	66400-G4000 \$ 1,502.54
37	HINGE ASSY-HOOD,LH	79110-G3000 \$ 49.50
38	HINGE ASSY-HOOD,RH	79120-G3000 \$ 49.50
39	PAD-HOOD INSULATING	81125-G4000 \$ 419.30
40	LATCH ASSY-HOOD	81130-G3900 \$ 114.80
41	CABLE ASSY-HOOD LATCH RELEASE	81190-G3800 \$ 12.40
42	SIDE BUMPER-HOOD OVERSLAM X2	17372-09520B \$ 2.00
43	FRT BUMPER-HOOD OVERSLAM X2	17377-22036B \$ 7.60
44	COVER ASSY-COWL TOP SIDE,LH	86152-G4000 \$ 73.04
45	COVER ASSY-COWL TOP SIDE,RH	86153-G4000 \$ 136.55
46	COVER ASSY-COWL TOP	86150-G4900 \$ 683.22
47	RETAINER-COWL TOP COVER MTG X4	86155-2H100 \$ 5.60
48	PANEL ASSY-FENDER,LH	66310-G3000 \$ 1,061.90
49	PANEL ASSY-FENDER,RH	66320-G3000 \$ 1,061.90
50	FILLER NECK ASSY-RADIATOR	25329-F3300 \$ 28.80
51	BLOWER ASSY	25380-F3300 \$ 567.50
52	HOSE-RADIATOR INLET	25411-F2250 \$ 48.10
53	HOSE ASSY-RADIATOR,UPR	25414-F3300 \$ 42.40
54	HOSE ASSY-RADAATOR,LWR	25415-F3300 \$ 59.10
55	GUARD-AIR,LH	29136-G4200 \$ 73.04
56	GUARD-AIR,RH	29134-G4200 \$ 73.04
57	CONDENSER ASSY-COOLER	97606-F2200 \$ 745.10
58	RADIATOR ASSY	25310-G4300 \$ 1,009.69
59	ANTIFREEZER	99H94-AQ710H \$ 95.60
60	AIR GUIDE-INTERCOOLER	28272-2A690 \$ 31.00
61	COOLER ASSY-INTER	28270-03110 \$ 915.40
62	DUCT ASSY-EXTENSION	28220-G3000 \$ 143.20
63	DUCT-EXTENSION	28212-G3000 \$ 3.50
64	SHIELD-AIR INTAKE	28213-G3000 \$ 8.60
65	DUCT-AIR "B"	28210-G3000 \$ 96.80
66	RETAINER-COWL TOP COVER MTG X2	86155-2H100 \$ 2.80
67	WIRING ASSY-BATTERY	91850-G4490 \$ 1,239.41
68	WIRING ASSY-FEM	91870-G4060 \$ 236.16
69	WIRING ASSY-FRT	91228-G4631 \$ 7,187.25
70	WIRING ASSY-CONTROL	91420-G4010 \$ 3,738.61
		\$ 32,211.78
	<i>Less 20% Discount</i>	\$ 6,442.36
	<b>Material total</b>	<b>\$ 25,769.42</b>

Vehicle number : **SLZ 746 C**  
Make and model : I30 1.4 GLS 5DR DCT TURBO  
Registration Date : 23/04/2018  
Chassis number : TMAH3513VJJ064981  
Engine number : G4LDHD120582

Job No. :  
Owner name : Tan Jing Felix  
Date of Acc : 29/04/2022  
Policy number : SP2001255858-01  
Claim Type : **OD-Excess TBC**

**Body,Paint & Labour Items :**

**Estimate**

1	To carry out accident body repair	\$	3,040.00
2	Complete putty and spray paint all affected areas	\$	2,040.00

**Labour Charges:**

**Estimate**

3	TO REFOCUS BOTH FRT HEAD LAMP (S.NETT)	\$	40.00
4	TO SUPPLY BONNET SEALANT (S.NETT)	\$	100.00
5	TO VACUUM & TOP UP AIRCON GAS (S.NETT)	\$	140.00
6	TO SUPPLY & INSTALL FRT NUMBER PLATE (S.NETT)	\$	40.00
7	TO REPAIR CHASSIS MEMBER (S.NETT)	\$	320.00
8	TO PUT ON CHASSIS BENCH ALIGNER	\$	320.00
9	TO R&I DASHBOARD ASSY TO FACILITATE REPAIR (S.NETT)	\$	570.00
10	TO RENEW FRT WIRING ASSY & REPROGRAM (S.NETT)	\$	570.00
11	TO RENEW CONTROL WIRING ASSY & REPROGRAM (S.NETT)	\$	570.00
12	TO RENEW BATTERY / FEM WIRING & REPROGRAM (S.NETT)	\$	380.00
	Total	\$	<u>33,899.42</u>
	Excess		
	Add GST 7%		

**Grand Total**

\*\*\* *Estimation are base on visual inspection, should there be furthur damages found during process of repair, you will be inform prior before carry out\*\*\**