



KOMODO MOTORS PTE. LTD.
 251 Alexandra Road #01-01, Singapore 119936
 TEL: 6547232888 FAX: 6547231613 www.komodomotors.com.sg
 SINGAPORE 119999338

(GST REGISTRATION NO: MR-8500364-4)

Date : 4 MAY 2022

ALLIANZ Insurance Singapore Pte Ltd

Attn: Motor Claims Department

Finalise

Vehicle number : **SLZ 746 C**
 Make and model : I30 1.4 GLS 5DR DCT TURBO
 Registration Date : 23/04/2018
 Chassis number : TMAH3513VJJ064981
 Engine number : G4LDHD120582

Job No. : 2022010701
 Owner name : Tan Jing Felix
 Date of Acc : 29/04/2022
 Policy number : SP2001255858-01
 Claim Type : **OD-Excess \$700**

Items :		Estimate	Revised
1 BUMPER CLIP X10	86595-2T500	\$ 12.00	\$ 12.00
2 UPPER GRILLE CLIP X6	14206-08250B	\$ 3.60	\$ 3.60
3 GRILLE-RADIATOR	86351-G4010	\$ 480.20	\$ 480.20
4 CR PIECE 1-RADIATOR GRILLE	86355-G4100	\$ 255.90	\$ 255.90
5 STRIP ASSY-FR BUMPER UPR	86357-G4000	\$ 68.30	\$ 68.30
6 EMBLEM-SYMBOL MARK	86300-G4100	\$ 26.10	\$ 26.10
7 COVER-RADIATOR GRILLE,UPR	86362-G4000	\$ 158.60	\$ 158.60
8 COVER-FR BUMPER	86511-G4000	\$ 939.20	\$ 939.20
9 GRILLE-FRONT BUMPER	86561-G4000	\$ 123.41	\$ 123.41
10 BRACKET-FR BUMPER SIDE,LH	86513-G4000	\$ 78.80	\$ 78.80
11 BRACKET-FR BUMPER SIDE,RH	86514-G4000	\$ 78.80	Refit
12 MOULDING-FRT BPR LICENSE PLATE	86519-G4000	\$ 44.20	\$ 44.20
13 ABSORBER-FRONT BUMPER ENERGY	86520-G4050	\$ 224.91	\$ 224.91
14 COVER-FR BUMPER FOG LAMP,LH	86563-G4040	\$ 88.99	\$ 93.60
15 COVER-FR BUMPER FOG LAMP,RH	86564-G4040	\$ 88.99	Refit
16 BRACKET-FRT BUMPER MOUNTING,LH	86553-G4000	\$ 47.20	\$ 47.20
17 BRACKET ASSY-FR BUMPER UPR SUP	86556-F2000	\$ 16.80	\$ 8.40
18 BRACKET-FRT BUMPER MOUNTING,RH	86554-G4000	\$ 47.20	Refit
19 PIECE-RADIATOR GRILLE NO.2	86353-G4000	\$ 162.90	\$ 162.90
20 PIECE-RADIATOR GRILLE NO.3	86354-G4000	\$ 112.86	Refit
21 GARNISH-RADIATOR GRILLE,UPR	86356-G4000	\$ 73.90	\$ 77.80
22 DUCT ASSY-AIR CURTAIN,LH	86567-G4030	\$ 47.68	Refit
23 DUCT ASSY-AIR CURTAIN,RH	86568-G4030	\$ 47.68	Refit
24 STIFFNER-FR BPR LWR	86571-G4000	\$ 174.25	Refit
25 CAP ASSY-FR BPR	86588-G4000	\$ 24.84	Refit
26 LIP ASSY-FRONT BUMPER	86591-G4000	\$ 161.80	Refit
27 LAMP ASSY-FRONT FOG,LH	92201-G4000	\$ 265.10	Refit
28 LAMP ASSY-FRONT FOG,RH	92202-G4000	\$ 265.10	Refit
29 LAMP ASSY-DAY RUNNING LIGHT,LH	92207-G4100	\$ 642.50	Refit
30 LAMP ASSY-DAY RUNNING LIGHT,RH	92208-G4100	\$ 642.50	Refit

Vehicle number : **SLZ 746 C**
 Make and model : I30 1.4 GLS 5DR DCT TURBO
 Registration Date : 23/04/2018
 Chassis number : TMAH3513VJJ064981
 Engine number : G4LDHD120582

Job No. : 2022010701
 Owner name : Tan Jing Felix
 Date of Acc : 29/04/2022
 Policy number : SP2001255858-01
 Claim Type : **OD-Excess \$700**

<i>Items :</i>		<i>Estimate</i>	<i>Revised</i>
31	LAMP ASSY-HEAD,LH	\$ 1,686.80	\$ 1,686.80
32	LAMP ASSY-HEAD,RH	\$ 1,686.80	Refit
33	BEAM COMPLETE-FR BUMPER	\$ 636.40	\$ 636.40
34	CARRIER ASSY-FRONT END MODULE	\$ 1,332.76	\$ 1,332.76
35	HORN ASSY-LOW PITCH	\$ 73.50	Refit
36	PANEL ASSY-HOOD	\$ 1,502.54	\$ 1,502.54
37	HINGE ASSY-HOOD,LH	\$ 49.50	\$ 49.50
38	HINGE ASSY-HOOD,RH	\$ 49.50	\$ 49.50
39	PAD-HOOD INSULATING	\$ 422.70	\$ 422.70
40	LATCH ASSY-HOOD	\$ 114.80	\$ 114.80
41	CABLE ASSY-HOOD LATCH RELEASE	\$ 12.40	Refit
42	SIDE BUMPER-HOOD OVERSLAM X2	\$ 2.00	Refit
43	FRT BUMPER-HOOD OVERSLAM X2	\$ 7.60	Refit
44	COVER ASSY-COWL TOP SIDE,LH	\$ 76.80	\$ 76.80
45	COVER ASSY-COWL TOP SIDE,RH	\$ 136.55	\$ 140.40
46	COVER ASSY-COWL TOP	\$ 683.22	Refit
47	RETAINER-COWL TOP COVER MTG X4	\$ 5.60	\$ 5.60
48	PANEL ASSY-FENDER,LH	\$ 1,061.90	\$ 1,061.90
49	PANEL ASSY-FENDER,RH	\$ 1,061.90	Refit
50	FILLER NECK ASSY-RADIATOR	\$ 28.80	Refit
51	BLOWER ASSY	\$ 567.50	Refit
52	HOSE-RADIATOR INLET	\$ 48.10	Refit
53	HOSE ASSY-RADIATOR,UPR	\$ 42.40	Refit
54	HOSE ASSY-RADAATOR,LWR	\$ 59.10	Refit
55	GUARD-AIR,LH	\$ 76.80	\$ 76.80
56	GUARD-AIR,RH	\$ 76.80	\$ 76.80
57	CONDENSER ASSY-COOLER	\$ 745.10	\$ 745.10
58	RADIATOR ASSY	\$ 1,009.69	\$ 1,009.69
59	ANTIFREEZER	\$ 95.60	\$ 95.60
60	AIR GUIDE-INTERCOOLER	\$ 31.00	Refit
61	COOLER ASSY-INTER	\$ 915.40	Refit
62	DUCT ASSY-EXTENSION	\$ 143.20	Refit
63	DUCT-EXTENSION	\$ 3.50	Refit
64	SHIELD-AIR INTAKE	\$ 8.60	Refit
65	DUCT-AIR "B"	\$ 96.80	Refit
66	RETAINER-COWL TOP COVER MTG X2	\$ 2.80	\$ 2.80
67	WIRING ASSY-BATTERY	\$ 1,239.41	Refit
68	WIRING ASSY-FEM	\$ 236.16	Refit
69	WIRING ASSY-FRT	\$ 7,187.25	Refit
70	WIRING ASSY-CONTROL	\$ 3,738.61	Refit
		\$ 32,360.20	\$ 11,891.61
<i>Less 20% Discount</i>		\$ 6,472.04	\$ 2,378.32
Material total		\$ 25,888.16	\$ 9,513.29

Vehicle number : **SLZ 746 C**
 Make and model : I30 1.4 GLS 5DR DCT TURBO
 Registration Date : 23/04/2018
 Chassis number : TMAH3513VJJ064981
 Engine number : G4LDHD120582

Job No. : 2022010701
 Owner name : Tan Jing Felix
 Date of Acc : 29/04/2022
 Policy number : SP2001255858-01
 Claim Type : **OD-Excess \$700**

Body,Paint & Labour Items :		Estimate	Revised
1	To carry out accident body repair	\$ 3,040.00	\$ 1,520.00
2	Complete putty and spray paint all affected areas	\$ 2,040.00	\$ 1,360.00
Labour Charges:		Estimate	Revised
3	TO REFOCUS BOTH FRT HEAD LAMP (S.NETT)	\$ 40.00	\$ 40.00
4	TO SUPPLY BONNET SEALANT (S.NETT)	\$ 100.00	\$ 100.00
5	TO VACUUM & TOP UP AIRCON GAS (S.NETT)	\$ 140.00	\$ 140.00
6	TO SUPPLY & INSTALL FRT NUMBER PLATE (S.NETT)	\$ 40.00	\$ 40.00
7	TO REPAIR CHASSIS MEMBER (S.NETT)	\$ 320.00	\$ 320.00
8	TO PUT ON CHASSIS BENCH ALIGNER	\$ 320.00	None
9	TO R&I DASHBOARD ASSY TO FACILITATE REPAIR (S.NETT)	\$ 570.00	None
10	TO RENEW FRT WIRING ASSY & REPROGRAM (S.NETT)	\$ 570.00	None
11	TO RENEW CONTROL WIRING ASSY & REPROGRAM (S.NETT)	\$ 570.00	None
12	TO RENEW BATTERY / FEM WIRING & REPROGRAM (S.NETT)	\$ 380.00	None
	Total	\$ 34,018.16	\$ 13,033.29
	Excess	\$ 700.00	\$ 700.00
		\$ 33,318.16	\$ 12,333.29
	Add GST 7%	\$ 2,332.27	\$ 863.33
	Grand Total	\$ 35,650.43	\$ 13,196.62

*** *Estimation are base on visual inspection, should there be furthur damages found during process of repair, you will be inform prior before carry out****