



6	"Mercedes" Sticker	new	\$	30.00	✓
7	3.0 Di" Sticker	new	\$	30.00	✓
8	Rear Boot Reflective Striped Decal	new	\$	280.00	100
9	Rear Fender Reflective Striped Decal	new	\$	640.00	150
10	Rear Number Plate	new	\$	35.00	X
11	Windscreen Sealant	new	\$	60.00	40
12	Reverse Sensor * 2 pes 1 set	Tom	\$	323.40	200
			<b>Amount :</b>	<b>\$ 1,438.40</b>	

Labour	Amount (\$)	
To conduct wheel alignment	\$ 60.00	✓
To check front & rear electrical wiring and focus headlamps etc	\$ 120.00	30
To remove & reinstall reverse sensors	\$ 80.00	50
To transfer rear boot components from old boot to new boot	\$ 200.00	60
To remove & install interior trims and garnishes etc to facilitate repair	\$ 150.00	11 X
To remove & reinstall windscreen glass	\$ 180.00	100
To remove & install undercarriages <i>front</i>	\$ 450.00	250
To remove & install spare tyre	\$ 80.00	X
To spray anti-rusting coating on new and affected panels	\$ 200.00	100
Labour to remove, cut, change & panel beating	\$ 1,300.00	1200
To putty and respray affected areas	\$ 1,400.00	1100
<b>Labour Total :</b>		<b>\$ 4,220.00</b>
<b>Total (Parts &amp; Labour)</b>		<b>\$ 15,498.11</b>

PARF Eligibility Expiry Date: 27 Mar 2025  
 PARF Rebate Amount: \$0.00  
 Intended COE Rebate Details  
 COE Expiry Date: 27 Mar 2025  
 COE Category: C - Good  
 COE Period (Years): 5  
 PQP Paid: \$12,194.00  
 COE Rebate Amount: \$7,047.00  
 Total Rebate Amount: \$7,047.00

LKK Auto Consultants hence notify the Repairer of the following:
 

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

 Acknowledged by Repairer  
 Signature:  
 Date:

P-10347-45  
 102  
 9312-70  
 570  
 2950  
 128327