

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd  
64 Cecil Street  
#04-00 IOB Building  
Singapore 049711

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 06 May 2022

**Preliminary Advice**

Vehicle No	: SJR5067L	Accident Date	: 21/04/2022
Make	: HYUNDAI AD AVANTE	Policy No.	: D18MPC0002588
Assignment Date	: 06/05/2022	Excess	: S\$0.00
Date of Inspection	: 25/04/2022	Est. Duration of Repair	: 4
Inspection At	: HUP MOTOR TRADING & SERVICE (HQ) BLK 9004 TAMPINES STREET 93, #01-120 SINGAPORE 528838		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,657.20
Revised Amount	:S\$	2,139.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,139.60

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	40,000.00
COE / PARF Rebate	:S\$	19,420.00

Salvage Value	:S\$
Margin for Repair	:S\$ 20,580.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
  
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
  
- ( X ) Other comments : The vehicle repair on Lump Sum basis.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject o part prices and labour cost check.