

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0359/2022/JT
DATE : 05-May-22
WIP : 22640

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 11/5/22

YOUR INSURED VEH NO : SJX 5620 H

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Rasul,

4 days - ok - Jy - 11 Aug 22

OWNER'S NAME : MR JIANG SHUAI
ADDRESS : 220 DEPOT ROAD
#15-76
SINGAPORE 109704
TELEPHONE : HP +65 93397470
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : PER/AIS/2021/0000260
VEHICLE NO : **SNA 5904 M**
MODEL CODE : AUDI Q8 3.0 TFSI QU
MODEL YEAR : 28/01/2019
ENGINE NO : DCB 051886
CHASSIS NO : WAUZZZF13KD011200
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 01-May-22
PLACE OF ACCIDENT : THE SLIP ROAD OF HENDERSON ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 5904 M

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	\$	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,800.00	\$	600.00
3	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER, BOT HREAR WHEEL ARCH TRIMS AND REAR END PANELLING.	\$	4,000.00	\$	1,700.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 6,352.00	\$	2,852.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 5904 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER - UPPER	1	\$ 1,451.00	\$ 1,160.80
2	REAR BUMPER - LOWER	1	\$ 2,201.00	\$ 1,760.80
3	REAR BUMPER FIXING PARTS	1	\$ 177.00	
4	REAR BUMPER SPOILER	1	\$ 1,407.00	\$ 1,125.60
5	REAR BUMPER CLOSING ELEMENT - RH	1	\$ 108.00	
6	REAR BUMPER TRIM - RH	1	\$ 273.00	\$ 218.00
7	REAR BUMPER TRIM - CENTER	1	\$ 271.00	\$ 216.40
8	BOOT LID CONTROL UNIT	1	\$ 454.00	
9	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,506.00	
10	REAR BUMPER SEAL - LH / RH	2	\$ 32.00	
11	REAR BUMPER HOLDING STRAP	1	\$ 206.00	
12	REAR BUMPER GUIDE SECTION - CENTER	1	\$ 159.00	
13	REAR BUMPER GUIDE SECTION - RH	1	\$ 75.00	
14	REAR PARKING AID SENSOR	2	TBC	
15	REAR PARKING AID SEAL RING	4	\$ 10.00	
16	REAR WHEEL ARCH COVER - LH / RH	2	\$ 794.00	\$ 635.20
17	REAR FOG LIGHT - RH	1	\$ 257.00	\$ 205.60
18	SUNDRIES		\$ 350.00	
TOTAL SPARE PARTS			\$ 9,731.00	\$ 5,322.40
TOTAL LABOUR CHARGES			\$ 6,352.00	\$ 2,852.00
GRAND TOTAL			\$ 16,083.00	\$ 8,174.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-02/-8/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LABOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT