

Not Authorized

THIAM HENG HUAT PTE LTD
176 SIN MING DR #05-14
SINGAPORE 575721
ATT: STEVEN HP 82636295

11 Bmp @ 145 dp
Rebody After Paint
3 days

VEH NO: SDM 9955U
MODEL: 2016 TOYOTA ALTIS 1.6 AUTO
CHASSIS: MR053REH104535227

1PC REAR BUMPER ASSY	573.30	Bmp	\$ 581.20	✓
1PC REAR BUMPER REINFORCEMENT	373.20	Bp	\$ 398.70	✓
2PC REAR BUMPER BRACKETS		R	\$ 131.60	X
2PC REAR BUMPER SIDE RETAINERS		Sm	\$ 124.80	X
1PC REAR BUMPER SENSORS		Shur	\$ 300.00	✓
1SET REAR BUMPER CLIPS		M	\$ 50.00	✓
1PC REAR BUMPER REFLECTORS		Pm	\$ 181.20	X
2PC TAIL LAMPS		Sm	\$ 689.00	X
2PC TAIL LAMP LOWER BRACKETS		Sm	\$ 160.40	X
1PC REAR END PANEL		R	\$ 708.00	X
1PC REAR END PANEL GARNISH		Sm	\$ 146.00	X
1SET REAR END PANEL GRANISH CLIPS		nm	\$ 30.00	X
1PC SPARE TYRE TOP BOARD		Sm	\$ 388.20	X
1PC KEYLESS ENTRY SENSOR		Sm	\$ 160.00	X
1PC REAR EXHAUST PIPE		\$M	\$ 720.50	X
2PC REAR EXHAUST PIPE MOUNTINGS		\$Sm	\$ 90.00	X
1PC REAR BOOT ASSY		\$R	\$ 781.20	X
1PC REAR BOOT LOGO		\$nm	\$ 80.00	X
1PC REAR BOOT RUBBER		\$Sm	\$ 157.00	X
1PC REAR BOOT LOCK		\$R	\$ 124.00	X
1PC REAR BOOT LATCH		\$R	\$ 87.00	X
1PC REAR EMBLEM " ALTIS "		\$nm	\$ 65.80	X
1PC REAR EMBLEM " COROLLA "		\$nm	\$ 58.60	X
2PC REAR BOOT LAMPS		Pm	\$ 560.40	X
1PC REAR BOOT CHROME HANDLE		Pm	\$ 265.00	X
Total			\$ 7,038.60	
Less 25%			\$ 5,278.95	

1SET REAR NUMBER PLATE	S/N	Sm	\$ 100.00	X
PANEL SEALANT		nm	\$ 100.00	X

Labour				
R & R REVERSE SENSOR; REPLACE ,RESET AND RE-ALIGN THE SAME	\$	100.00	50l	
PANEL BEATING	\$	1,000.00	400l	
PAINTING	\$	1,000.00	400l	
RUSTPROOFING	nm	\$ 100.00	X	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____