



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2300641

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 02/02/2023
Reference CC6/CTI22004172/Dpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 3099K
Insured Veh. SKD 9444S
Claim No. SNM22D203090/C02
Policy No. DMPCSNW00225562100
Accident Date 04/05/2022
Inspection Date 06/05/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22004172/Dpa3q2 Date: 02/02/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKD 9444S	Veh. Inspected	SHC 3099K
	Policy No.	DMPCSNW00225562100	Coverage (\$)	0.00
	Claim No.	SNM22D203090/C02	Excess (\$)	0.00
	Assign From		Assign Date	06/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI IONIQ	c.c	1580
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	KMHC851CVLU189103	Colour	BLUE
	Odometer	143800 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	WEST LAKE	5 mm
	L/H Front Tyre	195/65 R15	WEST LAKE	5 mm
	R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
	L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/05/2022	Inspection Date	06/05/2022
	Survey held at	Blk 9 Sector C #01-42, Sin Ming Industrial Estate		
	Repairer	BIFROST AUTO PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3099K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	BENT / DENTED	2,253.80	2,253.80
1	BONNET LOCK	NOT NECESSARY	127.30	-
1	RADIATOR GRILLE NEW MODEL	CRACKED / CUT	1,568.60	1,568.60
2	FLAP ASSY ACTIVE AIR UPPER (LH/RH) @\$824.60	MTG CRACKED	1,649.20	1,649.20
1	FLAP ASSY ACTIVE WIRE	NOT NECESSARY	765.30	-
1	FRONT NUMBER PLATE GARNISH	DEFORMED	188.00	188.00
1	FRONT BUMPER COVER	CUT	481.10	481.10
1	FRONT BUMPER TOP COVER	NOT NECESSARY	476.30	-
1	FRONT BUMPER SPONGE	TORN	186.90	186.90
1	FRONT BUMPER REINFORCEMENT	BENT	1,136.70	1,136.70
2	FRONT BUMPER REINFORCEMENT ABSORBER (LH/RH) @\$186.50	NOT NECESSARY	373.00	-
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	29.00	-
1	FRONT BUMPER MOULDING CENTRE UPPER	CUT	368.50	368.50
1	FRONT BUMPER MOULDING	NOT NECESSARY	93.60	-
1	FRONT BUMPER LOWER STIFFNER	NOT NECESSARY	285.10	-
1	FRONT BUMPER LOWER GRILLE	CUT / DEFORMED	365.30	365.30
1	FRONT BUMPER LOWER GRILLE MOULDING	BROKEN	127.60	127.60
1	FRONT BUMPER LIP	NOT NECESSARY	35.10	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$85.00	NOT NECESSARY	170.00	-
2	FRONT BUMPER BRACKET (LH/RH) @\$75.00	NOT NECESSARY	150.00	-
2	FRONT BUMPER RETAINER MOUNTING (LH/RH) @\$95.00	NOT NECESSARY	190.00	-
10	FRONT BUMPER CLIPS	NECESSARY	45.00	45.00
1	FRONT BUMPER GRILLE (RH)	CUT	186.90	186.90
1	FRONT BUMPER AIR DUCT (RH)	NOT NECESSARY	153.80	-
1	DAY LIGHT ,RH	NOT NECESSARY	642.50	-
1	DAY LIGHT WIRE	NOT NECESSARY	585.50	-
1	HEADLAMP SUPPORT PANEL ASSY	CRACKED	1,139.30	1,139.30
2	HEADLAMP (LH/RH) @\$3987.30	CRACKED	7,974.60	4,220.60
2	HORN UNIT (LH/RH) @\$72.80	NOT NECESSARY	145.60	-
1	HORN WIRE	NOT NECESSARY	386.70	-

Report Ref No. CC6/CTI22004172/Dpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR INVERTER	BENT	884.80	884.80
1	RADIATOR	NOT NECESSARY	710.50	-
2	RADIATOR AIR GUARD (LH/RH) 76.40	NOT NECESSARY	152.80	-
2	RADIATOR AIR GUARD UPR (LH/RH) @\$127.50	NOT NECESSARY	255.00	-
1	AIR DUCT	NOT NECESSARY	156.80	-
1	AIR DUCT HOSE	NOT NECESSARY	86.40	-
1	AIRCON CONDENSER	BENT	663.60	663.60
1	SPEAKER ASSY -VESS (ADDITIONAL)	MTG BROKEN	554.40	554.40
	LESS 20% DISCOUNT		-5,148.92	-3,204.06
			20,595.68	12,816.24
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN) }	BROKEN	25.00	45.00
1	FRONT NO PLATE TRIM COVER (SN)}	BROKEN	30.00	-
1	COOLANT (SN)	NOT NECESSARY	45.00	-
			100.00	45.00
	<u>LABOUR</u>			
	PANEL BEATING.		1,600.00	600.00
	SPRAY PAINTING CHARGE .		1,400.00	400.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		100.00	20.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE/REFIX RADIATOR.		90.00	50.00
	REMOVE/REFIX AIRCON & REFILL GAS .		130.00	80.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.		550.00	150.00
			4,050.00	1,330.00
GRAND TOTAL			24,745.68	14,191.24

RECOMMENDED COST OF REPAIRS			14,191.24
------------------------------------	--	--	------------------

Report Ref No. CC6/CTI22004172/Dpa3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 3099K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 3099K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 3099K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

