



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 7177D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOTLID (NPA)(CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	BOOTLID CENTER LOGO (CONSISTENT)	NOT NECESSARY	120.00	-
1	BOOTLID E220D (CONSISTENT)	NOT NECESSARY	98.00	-
1	TAILLAMP LH (CONSISTENT)	SERVICEABLE	980.50	-
1	TAILLAMP LOWER BRACKET LH (CONSISTENT)	SERVICEABLE	228.00	-
1	TAILLAMP PANEL LH (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	END PANEL (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	REAR BUMPER (CONSISTENT)	BUCKLED	1,685.50	1,670.00
1	REAR BUMPER SPONGE (CONSISTENT)	SERVICEABLE	485.00	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	685.00	-
1	REAR BUMPER LOWER GARNISH (CONSISTENT)	SCRATCHED	785.00	478.00
1	REAR BUMPER OUTER CHROME (CONSISTENT)	CRACKED	620.00	388.00
1	REAR BUMPER EXHAUST END LH (CONSISTENT)	DENTED	598.00	345.00
1	REAR BUMPER EXHAUST END HOLDER LH (CONSISTENT)	SERVICEABLE	332.00	-
1	REAR BUMPER REFLECTOR LH (CONSISTENT)	SERVICEABLE	323.00	-
1	REAR BUMPER SENSORS (CONSISTENT)	SHORTED	680.00	255.00
1	REAR BUMPER BRACKETS/HOLDERS (CONSISTENT)	SERVICEABLE	280.00	-
1	REAR BUMPER SIDE RETAINER LH (CONSISTENT)	SERVICEABLE	224.00	-
1	REAR BUMPER BRACKET (CONSISTENT)	SERVICEABLE	232.00	-
	LESS 10% DISCOUNT		-835.60	-313.60
			7,520.40	2,822.40
<u>SPECIAL NETT ITEMS</u>				
10	REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	55.00	55.00
15	REAR BUMPER RIVETS (SN) (CONSISTENT)	NOT NECESSARY	75.00	-
			130.00	55.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	LABOUR CHARGES,TO REPAIR,REPLACE ALIGN ADJUST,REMOVE REFIX ACCIDENT AFFECTED AREA.INCLUSIVE OF THE REPAIR OF BOOTLID,TAILLAMP PANEL LH,END PANEL AND REAR BUMPER REINFORCEMENT .		1,000.00	250.00
	REMOVE REFIX,GARNISH,SIDE TRIM ETC FOR ACCIDENT REPAIR.	NOT NECESSARY	150.00	-
	TO CHECK LAMP WIRING SYSTEM.		90.00	15.00
	TO DO ANTI RUST.	NOT NECESSARY	90.00	-
	TO DO SPRAY PAINTING ON ACCIDENT AFFECTED AREA.		800.00	250.00
	TO DO DIAGNOSE,DELETE FAULT CODE,SETTLING AFTER REPAIR.	NOT NECESSARY	250.00	-
			2,380.00	515.00
	GRAND TOTAL		10,030.40	3,392.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,650.00

Report Ref No. CC4/ASM22004174/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.