

ASS. REC. BY:

REF:

AGZ/ 22004181/K943

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

04/30

Person Contacted:

Vehicle: IN / OUT

Veh No:

EU

S64 63364

Yr Regn:

09, 92

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(n)

Make:

BMW 320i

C.C.

1991

Colour

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading

158 416

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBABF 22010-JA 72058

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/40R17

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
TOYO/YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

7

mm

L/Bal.

6

mm

L/Bal.

7

mm

D.O.A.

28/4/22

D.O.I.

6/5/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Acc

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

/ GIA & EH not ready

11/5 11:15 AM 8/11501 Control (Red 7304.10, 862.)

Date/Time, File Pass to?



: Prell. Report

1) 05/7 11:15 AM



: Final Report

Date/Time, File Return to?

Days Of Repair:

3

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Report Format :

TP

Lump Sum / I.B.T. (\$

1150

Repair Estimate

Not Authorized
11 Sep @ 1150h
Penny After Point

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

3 days

Make/Model: BMW 320i E36

Engine/Chassis No.: WBABF22010JA72058


Date of accident:

Damaged area: N/S

Date: 06/05/2022

Claim Type: TP

VRN: EU6336Y



List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear fender n/s	1	\$ 1,078.00	\$ 1,078.00
2	Rear fender inner shield n/s	1	\$ 228.00	\$ 228.00
3	Rear roll over strut n/s	1	\$ 475.00	\$ 475.00
4	Rear shock absorber n/s	1	\$ 589.00	\$ 589.00
5	Rear shock absorber mounting n/s	1	\$ 167.00	\$ 167.00
6	Rear lower arm n/s	1	\$ 487.00	\$ 487.00
7	Rear wheel knuckle n/s	1	\$ 594.00	\$ 594.00
8	Rear wheel knuckle bearing n/s	1	\$ 396.00	\$ 396.00
9	Rear wheel hub n/s	1	\$ 445.00	\$ 445.00
10	Rear windscreen moulding	1	\$ 319.00	\$ 319.00
Subtotal				\$ 4,778.00
List discount				5.00%
Total				\$ 4,539.10

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear alloy wheel "BBS" n/s	1	\$ 950.00	\$ 950.00
2	Rear tyre n/s	1	\$ 280.00	\$ 280.00
3	Rear windscreen sealant	1	\$ 100.00	\$ 100.00
4	Rear fender sealant n/s	1	\$ 80.00	\$ 80.00
5	Rear fender inner shield clips n/s	10	\$ 5.50	\$ 55.00
6	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 1,515.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	5	\$ 1,000.00

300/

Repair Estimate

2	Supply spray paint materials and necessary items to respray affected area / panel.	4	\$	800.00
3	To rust proof all affected portions after repair.	0.5	\$	nn 100.00
4	To disconnect wire harnesses of electrical components to facilitate repairs, reconnect and check functions.	0.25	\$	nn 50.00
5	To remove and refit interior upholstery, inner trim, inner garnish, mouldings to facilitate repair.	0.5	\$	100.00
6	To remove and refit n/s rear undercarriage for replacement of parts.	0.5	\$	nn 100.00
7	To conduct computerized wheel alignment.	0.5	\$	100.00
8	To remove and refit rear windscreen to facilitate repair work.	0.75	\$	nn 150.00
Total labour			\$	2,400.00

2501

X

X

601

X

601

X

Estimate Grand Total	\$	8,454.10
----------------------	----	----------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: