

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/198R GS1 Reg. No. 19-900/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	ef:	CS/AGI22004181/Kqy3e2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	08/07/2022	
			C	ode:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJE 5841L	Veh. Inspected		EU 6336Y	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10015028/CD	Excess (\$)		0.00	
	Assign From	Shafawati Md Rabu	Assign Date		06/05/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	B.M.W. 320I (M)	c.c		1991	
	Engine No.	HIDDEN	Year of Reg.		1992	
	Chassis No.	WBABF22010JA72058	Colour		METALLIC GREY	
	Odometer	158416 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.						
		Size	Make		Balance	
	R/H Front Tyre	235/40 R17	BRIDGESTONE		6 mm	
	L/H Front Tyre	235/40 R17	BRIDGESTONE		6 mm	
	R/H Rear Tyre	235/40 R17	BRIDGESTONE		7 mm	
	L/H Rear Tyre	235/40 R17	BRIDGESTONE		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	28/04/2022	Inspection Date		06/05/2022	
	Survey held at	THIAM HENG HUAT PTE LTD				
		176 SIN MING DRIVE #05-14 SINGAPORE 575721				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: