

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI22004183/VQCM4**Date:** 12/08/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000206		
<b>Claimant Vehicle No :</b>	SH8046Z	<b>Insured Vehicle No :</b>	SLP176A		
Date of Loss:	28/04/2022	Nature of Claim:	TP	Claim No:	M2202156

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SH8046Z</b>	Engine No:	G4LEJU192047
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 DCT (A)	Chassis No:	KMHC851CVKU141553
Reg. Date:	02/04/2019 (Man. Year: 2018)	Odometer:	256947 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,301.84	756.72	3,545.12	82.41
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,140.00	1,510.00	630.00	29.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,452.84</b>	<b>2,277.72</b>	<b>4,175.12</b>	<b>64.70</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,800.00</b>		
<b>(S\$)</b>	6,452.84	1,800.00	4,652.84	72.11
<b>+ GST 7.00/7.00% (S\$)</b>	451.70	126.00	325.70	72.11
<b>Nett Amount (S\$)</b>	<b>6,904.54</b>	<b>1,926.00</b>	<b>4,978.54</b>	<b>72.11</b>

INSPECTION

Date of Assignment:	05/05/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	06/05/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Aug 2022)
Parts:	143	HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH8046Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	459.40 FL	*- FL
2	1		*REAR BUMPER SIDE BRKT LH	Repair	55.80 FL	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*REAR FENDER LH	Repair	1,768.30 FL	*- FL
5	1		*REAR WHEEL CAP LH	Scratched	346.40 FL	*346.40 FL
6	1		*REAR DOOR LH	Repair	2,147.90 FL	*- FL
7	1		*REAR FENDER (PETROL ONLY) LH	Necessary	40.00 FL	*40.00 FL
8	1		*REAR DOOR APPS LH	Necessary	80.00 F	*80.00 F
9	1		*REAR DOOR ADVERTISEMENT STICKER LH	Necessary	100.00 F	*100.00 F
10	1		*REAR BUMPER ADVERTISEMENT STICKER	Necessary	50.00 F	*50.00 F
11	2		*REAR FENDER ADVERTISEMENT STICKER RH / LH	Necessary	200.00 F	*200.00 F
						F=Franchise part. L=ListItemDisc.
Sub Total (\$\$)					5,269.80	838.40
- List Item Discount on L Items 20.00/20.00% (\$\$)					967.96	81.68
Total Parts (\$\$)					4,301.84	756.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	700.00
2	SPRAY PAINTING	New	900.00	750.00
3	TUFF KOTE	New	80.00	30.00
4	WHEEL ALIGNMENT	New	120.00	0.00
5	R/I REVERSE SENSORS	New	120.00	30.00
6	TRANSFER OF DOOR	New	120.00	0.00
Gross Labour Cost (\$\$)			2,140.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >