

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/CTI22004187/VVY3E2

**Date:** 15/08/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00080292201  
Claimant Vehicle No: SMA4439H Insured Vehicle No: SMK2100U  
Date of Loss: 21/04/2022 Nature of Claim: TP Claim No: SNM22D202817/C02/THAMYL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA4439H**  
Make & Model: TOYOTA C-HR, 1.2 (A) Engine No: 2ZR8431654  
Reg. Date: 07/06/2018 (Man. Year: 2018) Chassis No: ZYX102118735  
Colour: Red Odometer: 218347 km  
Engine Capacity: 1797 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17  
Front Left Side: West Lake 7 mm Rear Left Side: West Lake 7 mm  
Front Right Side: West Lake 7 mm Rear Right Side: West Lake 7 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 2,392.80          | 1,372.10          | 1,020.70          | 42.66         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 1,680.00          | 890.00            | 790.00            | 47.02         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>4,072.80</b>   | <b>2,262.10</b>   | <b>1,810.70</b>   | <b>44.46</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>1,800.00</b>   |                   |               |
| <b>(S\$)</b>                             | 4,072.80          | 1,800.00          | 2,272.80          | 55.80         |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 285.10            | 126.00            | 159.10            | 55.80         |
| <b>Nett Amount (S\$)</b>                 | <b>4,357.90</b>   | <b>1,926.00</b>   | <b>2,431.90</b>   | <b>55.80</b>  |

### INSPECTION

Date of Assignment: 09/05/2022  
Date Inspected: 06/05/2022 Inspected At: 8 Kaki Bukit Ave 4, Premier@Kaki Bukit #06-31  
Repaired By: Rico 60 Auto Services Pte Ltd  
Estimated Period of Repair: 3.0 days

**Adjuster:** Thevan Thomas Karthikesavan

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

|                            |  |
|----------------------------|--|
| <b>Part Source:</b> MRM-SG | Version: 1.0 (Last Synchronised: 15 Aug 2022)  |
| <b>Parts:</b> M1-SUV       | TOYOTA C-HR 1.2 (A) (Catalogue:Merimen Singapore 1.0)  |
| <b>Labour:</b> Repairer's  | (Price-denominated Standard List)  |
| <b>Print Code:</b>         | (Unsubmitted, no print-code for SMA4439H)  |
| <b>Validity:</b>           | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>       | Items/values not in reference catalogue are prefixed with an asterisk *.   |

## Recommended Parts

| No. | Qty | Part No. | Particulars                     | Condition   | Repairer's | Amount     |
|-----|-----|----------|---------------------------------|-------------|------------|------------|
| 1   | 1   |          | *FRONT BUMPER                   | Deformed    | 794.20 F   | *794.20 FL |
| 2   | 1   |          | *FRONT BUMPER LOWER EXTENSION   | Scratched   | 359.40 F   | *359.40 FL |
| 3   | 1   |          | *FRONT BUMPER L/H SIDE RETAINER | Necessary   | 87.10 F    | *87.10 FL  |
| 4   | 1   |          | *FRONT BUMPER R/H SIDE RETAINER | Necessary   | 87.10 F    | *87.10 FL  |
| 5   | 1   |          | *SET FRONT BUMPER CLIPS         | Necessary   | 35.00 F    | *35.00 FL  |
| 6   | 1   |          | *R/H FRONT SPORT RIM            | Distorted   | 670.00 FS  | *350.00 FS |
| 7   | 1   |          | *R/H FRONT TYRE                 | Serviceable | 360.00 FS  | *- FS      |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|   |                 |                 |
|---|-----------------|-----------------|
| <b>Sub Total (\$)</b>                                   | <b>2,392.80</b> | <b>1,712.80</b> |
| <b>- List Item Discount on L Items 0.00/25.00% (\$)</b> | 0.00            | 340.70          |
| <b>Total Parts (\$)</b>                                 | <b>2,392.80</b> | <b>1,372.10</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                  | Particulars   | Lab.Type | Repairer's                    | Amount        |
|---------------------|---|----------|-------------------------------|---------------|
| <b>Labour Items</b> |   |          |                               |               |
| 1                   | TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS | New      | 900.00                        | 400.00        |
| 2                   | TO CHECK WIRING AND REWIRE                                    | New      | 60.00                         | 30.00         |
| 3                   | TO PERFORM 4 WHEEL ALIGNMENT                                  | New      | 120.00                        | 60.00         |
| 4                   | TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS                    | New      | 600.00                        | 400.00        |
|                     |   |          | <b>Gross Labour Cost (\$)</b> | <b>890.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >