



**K A A S**  
kelvin automotive appraising services

6 tampines st 73, #01-03, singapore 528825  
tel: 6746 2118 fax: 6746 1148  
reg no: 53058468m

Claim Reference : -  
Insured Vehicle No. : -  
Thirty Party Veh No. : -  
Officer-In-Charge : -

Our Reference : KAAS/TA/6380/4439/TP/04.22  
Date : 31 May 2022

To: Hua Hong Pte Ltd  
c/o 8 Kaki Bukit Ave 4  
#06-31, Premier @ Kaki Bukit  
Singapore 415875

### VEHICLE APPRAISAL REPORT

Name of Workshop : Oohray Rental Pte Ltd  
Place of inspection : 8 Kaki Bukit Ave 4 #06-31, Premier @ Kaki Bukit, Singapore 415875  
Date of Assignment : 05 May 2022  
Date of Accident : 21 April 2022  
Date of Inspection : 05 May 2022

#### **PARTICULARS OF INSPECTED VEHICLE**

Registration No.	: SMA 4439H	Chassis Frame No.	: ZYX10-2118735
Make / Model	: Toyota C-HR Hybrid 1.8S CVT	Engine No. ( Logcard )	: 2ZR8431654
Year of Manufacture/Reg	: 2018	Odometer Reading	: 218,337 KM
Colour	: Red		
Class / Type	: SUV		

#### **CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)**

General Condition : Very Good  
Paintwork : Very Good  
Market Value : -  
Scrap Value : -

#### **CONDITION OF TYRES ON VEHICLE**

	<u>Make/Size</u>	<u>Thread Balance</u>
Front L	WESTLAKE 215 / 60 R17	7 mm
Front R	WESTLAKE 215 / 60 R17	7 mm
Rear L	WESTLAKE 215 / 60 R17	7 mm
Rear R	WESTLAKE 215 / 60 R17	7 mm

\*The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.



**KAAS**  
 Calvin Automotive Appraising Services

6 Tampines St 73, #01-03, Singapore 528825  
 tel: 6746 2118 fax: 6746 1148  
 web: www.kaas.com.sg

Our Reference : KAAS/TA/6380/4439/TP/04.22  
 Vehicle Number : SMA 4439H

### APPRAISEMENT SCHEDULE


S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
LIST ITEMS:-					
1	1 pc	front bumper	deformed	\$ 794.20	\$ 794.20
2	1 pc	front bumper lower extension	scratched	\$ 359.40	\$ 359.40
3	1 pc	front bumper l/h side retainer	necessary	\$ 87.10	\$ 87.10
4	1 pc	front bumper r/h side retainer	necessary	\$ 87.10	\$ 87.10
5	1 set	front bumper clips	necessary	\$ 35.00	\$ 35.00
				\$ 1,362.80	\$ 1,362.80
Less 25%					\$ 340.70
				\$ 1,362.80	\$ 1,022.10
SPECIAL NETT ITEMS:-					
6	1 pc	r/h front sports rim	distorted	\$ 670.00	\$ 670.00
7	1 pc	r/h front tyre @50% depreciation	scratched	\$ 360.00	\$ 180.00
				\$ 1,030.00	\$ 850.00
<b>Sub - Total</b>				<b>\$ 2,392.80</b>	<b>\$ 1,872.10</b>

350  
 XGC



**ASSESSMENT SUMMARY**

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered **Diagonally to the RH Side from rear to front; right to left;** portion of the vehicle.



The general area of damages is at the **RH Side portion**  
( Please refer to the parts list and photographs as attached for more information )

**ASSESSOR'S RECOMMENDATIONS**

The estimated repair costs submitted by Messrs **Oohray Rental Pte Ltd** is \$ **4,072.80**.  
We have adjusted the cost to \$ **3,022.10** and the repairer has agreed to undertake the repairs at a **Contract Lump Sum of \$ 2,400.00** to a acceptable quality and standards. **1860**  
However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of **3** working days.

**15** photographs were taken at the time of static inspection.

This report is strictly done in a **Without Prejudice Basis**.

We are reverting the matter to you a decision.

We enclose herewith our Invoice No. **6380** for our services rendered and we thank you for engaging our services.

**KELVIN AUTOMOTIVE APPRAISING SERVICES**



**KELVIN TEO**  
Licensed Automotive Appraiser  
Niltec In Automotive Technology  
Cert. Crash Investigation & Reconstruction  
Dip MS  
MSAAA, AM SAE-A

**NOTE :** This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company within Seven (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.