

### SERVICE ESTIMATE

##### - C00001      SL: SERVICE SALES - PC

Ms Alexia Ho Wen Tsi  
522 East Coast Road #17-01

Singapore 458966

Closed by .... : Juan Paulo Bongon Ba  
Svc Consultant :  
Remarks ..... : Ms Alexia Ho Wen Tsi

GST Reg.No:M28920628X  
Inv.No. . : B&P            0    Page 1  
Inv.date. : 05/05/2022  
WIP No. . : 23674  
Veh.In/Out:  
\*Tel.No. . : Mobile: 98164184  
Reg.No. . : SBV68R  
Reg.date . : 30/10/2020  
Mileage .. : 0  
Chassis No: SADCA2AXXKA616467

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR TOW HOOK COVER, REINFORCEMENT, ETC	0	1500.00	0		1,500.00	S
800	TO SPRAY REAR BUMPER, REINFORC ETC	0	1800.00	0		1,800.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	621.00	0		621.00	S
	COVER-BUMPER REAR	1.0 EA	1957.80			1,957.80	S
	MOUNTING-BRACKET CTR	1.0 EA	234.30			234.30	S
	BUMPER NUT XF	10.0 EA	5.30			53.00	S
	COVER-TWNG HK OPNG	1.0 EA	33.40			33.40	S
	PANEL VALANCE	1.0 EA	257.30			257.30	S
	BUMPER BEAM REAR XE	1.0 EA	714.30			714.30	S
	SENSOR	4.0 EA	428.10			1,712.40	S
	LAMP-FOG LH	1.0 EA	340.80			340.80	S
	ANTENNA	1.0 EA	43.80			43.80	S

**SERVICE ESTIMATE**

##### - C00001 SL: SERVICE SALES - PC  
 Ms Alexia Ho Wen Tsi  
 522 East Coast Road #17-01

Singapore 458966

Closed by .... : Juan Paulo Bongon Ba  
 Svc Consultant :  
 Remarks ..... : Ms Alexia Ho Wen Tsi

GST Reg.No:M28920628X  
 Inv.No. . : B&P 0 Page 2  
 Inv.date. : 05/05/2022  
 WIP No. . : 23674  
 Veh.In/Out:  
 \*Tel.No. . : Mobile: 98164184  
 Reg.No. . : SBV68R  
 Reg.date . : 30/10/2020  
 Mileage .. : 0  
 Chassis No: SADCA2AXXKA616467

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	HEATSHIELD LH	1.0 EA	81.50			81.50	S
	HEATSHIELD LH	1.0 EA	62.80			62.80	S

			Gross Total.	9,412.40
<b>Labour Total</b>	3,921.00		Net.....	9,412.40
<b>Parts Total</b>	5,491.40		GST @ 7.0%	658.87
<b>Package Total</b>	0.00		Total.....	10,071.25
			Paid.....	0.00
			Please Pay..	10,071.25

GST: S=StdRated; O=OutOfScope; Z=ZeroRated