




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWER SINGAPORE 048623			Ref: CS3/SMO22004192/Avce2 Date: 12/05/2022 Code: SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SLT 3359Z	Veh. Inspected	GBE 6748L
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2201456/GPL	Excess (\$)	0.00
	Assign From	MELVIN YE	Assign Date	06/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	2494
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	KDH2000065732	Colour	SILVER
	Odometer	377880 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	MAXMILER	6 mm
	L/H Front Tyre	195 R15C	MAXMILER	6 mm
	R/H Rear Tyre	195 R15C	MAXMILER	6 mm
	L/H Rear Tyre	195 R15C	MAXMILER	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information				
	Accident Date	28/04/2022	Inspect Date / Time	06/05/2022 (12:41 PM)
	Survey held at	MK VEHICLE ENTERPRISE 48 TOH GUAN ROAD EAST #04-124 SINGAPORE 608586		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000-\$9,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days

Report Ref No. CS3/SMO22004192/Avce2

Inspected By

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.