



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22004200/Eqy3n2	
			Date: 06/06/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMB 1598X	Veh. Inspected	SMH 8887J	
Policy No.		Coverage (\$)	0.00	
Claim No.	BUS/05/22/5002	Excess (\$)	0.00	
Assign From	ASHLENE LEE	Assign Date	06/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA HRV	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JHMRU1830JX201510	Colour	WHITE	
Odometer	107573 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	MICHELIN	4 mm	
L/H Front Tyre	215/60 R16	MICHELIN	4 mm	
R/H Rear Tyre	215/60 R16	MICHELIN	4 mm	
L/H Rear Tyre	215/60 R16	MICHELIN	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/05/2022	Inspection Date	23/05/2022	
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	