

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

*Not Notwithstanding
BTR Policy B4pant*

5 days

M/S: LONPAC INSURANCE BERHAD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
TEL: 62507388 FAX: 62963767
ATTN: Motor Claim Department

Claim No: ES2290446
Estimate No: ES2290446/YISHUN
Date: 06 May 2022
Policy No: Z21VP05029819
Veh Reg No: SFB6883Y
Make/Model: MERCEDES MERC
BENZ E200 EXCLUSIVE
(R18 LED)
Chassis No: WDD2130422A027556
Engine No: 27492030690197
Reg. Date: 15/09/2016

WS Ref: OD/LONPAC
Claim Type: Own Damage
Accident Date: 02/05/2022

Estimate Repair Cost to Vehicle No : SFB6883Y

Description	U/Price	Quantity	Cost	Amount
Cost Plus			SS	SS
1 FRONT BUMPER	810.00	1 PC	810.00	✓
2 FRONT BUMPER REINFORCEMENT	280.00	1 PC	280.00	7✓
3 FRONT BUMPER SPONGE <i>fog lamp</i>	95.00	1 PC	95.00	7✓
4 FRONT BUMPER LH HEADLAMP COVER	55.00	1 PC	55.00	✓
5 FRONT BUMPER LH FOG LAMP COVER CHROME	45.00	1 PC	45.00	✓
6 FRONT BUMPER LH OUTER PDC SENSOR	115.00	1 PC	115.00	7X
7 FRONT BUMPER LH CORNAL PARKING SENSOR	115.00	1 PC	115.00	✓
8 FRONT BUMPER LH SIDE INNER FRAME	55.00	1 PC	55.00	7✓
9 FRONT BUMPER RIVET PIN	5.00	12 PC	60.00	✓
10 FRONT BUMPER PDC SENSOR WIRE HARNESS	275.00	1 SET	275.00	7X
11 FRONT GRILLE ASSY	520.00	1 PC	520.00	✓
12 BONNET	1,350.00	1 PC	1,350.00	✓
13 BONNET LH UPPER LATCH	50.00	1 PC	50.00	7✓
14 BONNET LH INNER LOCK	60.00	1 PC	60.00	7X
15 BONNET SPRING ELEMENT	24.00	2 PC	48.00	✓
16 FRONT LH FENDER	590.00	1 PC	590.00	✓
17 FRONT LH FENDER EXPANSION RIVETS	4.00	4 PC	16.00	✓
18 FRT SUPPORT PANEL	520.00	1 PC	520.00	7✓
19 FRONT MOUNTING CONSOLE	140.00	1 PC	140.00	7✓
20 HEADLAMP LH	1,720.00	1 PC	1,720.00	✓
21 HEADLAMP LH CONTROL UNIT	410.00	1 PC	410.00	7X
Add 15%			6479	7,329.00
			971.85	1,099.35
				8,428.35
				7450.85
Labour				
22 REMOVE & REFIX FRT BUMPER & ATTACHMENTS, GRILLE, BONNET & ATTACHMENTS, HEADLAMP, FRT LH FENDER, FRT SUPPORT PANEL & REALIGN THE SAME	800.00	1 LA	800.00	500
23 PUTTY & RESPRAY FRT BUMPER & PARKING SENSORS, BONNET, FRT LH FENDER & ALL AFFECTED AREAS	700.00	1 LA	700.00	600
24 REMOVE & REFIX PARKING SENSORS, CHECK RESET THE SAME	80.00	1 LA	80.00	601
25 REMOVE & REFIX HEADLAMP CONTROL UNIT, REPROGRAMME & RESET THE SAME	180.00	1 LA	180.00	1201
				1280

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST: 201001158E RCB NO: 201001158E

M/S: LONPAC INSURANCE BERHAD

300 BEACH ROAD

#17-04/07 THE CONCOURSE

SINGAPORE 199555

TEL: 62507388

FAX: 62963767

ATTN: Motor Claim Department

Claim No: ES2290446

Estimate No: ES2290446/YISHUN

Date: 06 May 2022

Policy No: Z21VP05029819

Veh Reg No: SFB6883Y

Make/Model: MERCEDES MERC
BENZ E200 EXCLUSIVE
(R18 LED)

Chassis No: WDD2130422A027556

Engine No: 27492030690197

Reg. Date: 15/09/2016

WS Ref: OD/LONPAC

Claim Type: Own Damage

Accident Date: 02/05/2022

Estimate Repair Cost to Vehicle No : SFB6883Y

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
				1,760.00

Total S\$ 10,188.35

Add GST @ 7% 713.18

Total Amount payable S\$ 10,901.53

PART: 7450.85

L: 1280

8730.85

P/P: 8730.85/2

PLS CHECK & CONFIRM

For Cheng Hoe Motor Pte Ltd

Dorlyn LA

AUTHORISED SIGNATURE