

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

*Not Authorized
BtR Recovery B4point*

M/S : LONPAC INSURANCE BERHAD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

TEL: 62507388 FAX: 62963767
ATTN: Motor Claim Department

Claim No: ES2290446
Estimate No: ES2290446/YISHUN
Date: 06 May 2022
Policy No: Z21VP05029819
Veh Reg No: SFB6883Y
Make/Model: MERCEDES MERC
BENZ E200 EXCLUSIVE
(R18 LED)

WS Ref: OD/LONPAC
Claim Type: Own Damage
Accident Date: 02/05/2022

Chassis No: WDD2130422A027556
Engine No: 27492030690197
Reg. Date: 15/09/2016

Estimate Repair Cost to Vehicle No : SFB6883Y

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Cost Plus				
1 FRONT BUMPER	810.00	1 PC	810.00	✓
2 FRONT BUMPER REINFORCEMENT	280.00	1 PC	280.00	✓
3 FRONT BUMPER SPONGE	95.00	1 PC	95.00	✓
4 FRONT BUMPER LH HEADLAMP COVER	55.00	1 PC	55.00	✓
5 FRONT BUMPER LH FOG LAMP COVER CHROME	45.00	1 PC	45.00	✓
6 FRONT BUMPER LH OUTER PDC SENSOR	115.00	1 PC	115.00	✓
7 FRONT BUMPER LH CORNAL PARKING SENSOR	115.00	1 PC	115.00	✓
8 FRONT BUMPER LH SIDE INNER FRAME	55.00	1 PC	55.00	✓
9 FRONT BUMPER RIVET PIN	5.00	12 PC	60.00	✓
10 FRONT BUMPER PDC SENSOR WIRE HARNESS	275.00	1 SET	275.00	✓
11 FRONT GRILLE ASSY	520.00	1 PC	520.00	✓
12 BONNET	1,350.00	1 PC	1,350.00	✓
13 BONNET LH UPPER LATCH	50.00	1 PC	50.00	✓
14 BONNET LH INNER LOCK	60.00	1 PC	60.00	✓
15 BONNET SPRING ELEMENT	24.00	2 PC	48.00	✓
16 FRONT LH FENDER	590.00	1 PC	590.00	✓
17 FRONT LH FENDER EXPANSION RIVETS	4.00	4 PC	16.00	✓
18 FRT SUPPORT PANEL	520.00	1 PC	520.00	✓
19 FRONT MOUNTING CONSOLE	140.00	1 PC	140.00	✓
20 HEADLAMP LH	1,720.00	1 PC	1,720.00	✓
21 HEADLAMP LH CONTROL UNIT	410.00	1 PC	410.00	✓
			7,329.00	
			1,099.35	8,428.35
Labour				
22 REMOVE & REFIX FRT BUMPER & ATTACHMENTS, GRILLE, BONNET & REALIGN THE SAME	800.00	1 LA	800.00	500
23 PUTTY & RESPRAY FRT BUMPER & PARKING SENSORS, BONNET, FRT LH FENDER & ALL AFFECTED AREAS	700.00	1 LA	700.00	600
24 REMOVE & REFIX PARKING SENSORS, CHECK RESET THE SAME	80.00	1 LA	80.00	60
25 REMOVE & REFIX HEADLAMP CONTROL UNIT, REPROGRAMME & RESET THE SAME	180.00	1 LA	180.00	120

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10,188.35