



Front View



Rear View



Side View



Side View



Damage Photos



Sats Vehicle Rear



Sats Vehicle Front






POH KIAN GUAN (ERIC)  
461A  
9115 4794  
YP 9899A


# Sats Driver's Particulars

Annex A

## SUPPORTING SKETCHES




Schematic Diagram Pt. 1



Schematic Diagram Pt. 2

SUPPORTING SKETCHES



Schematic Diagram Pt. 3



**SINGAPORE  
POLICE FORCE**



T/20220428/7027

1 of 4

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20220428/7027

#### REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/04/2022 18:03		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: THANARAJOO RETHINAM			Address: [REDACTED]		
ID Type / ID No.: NRIC NO / [REDACTED] 819J			Contact No.: Home/Office: [REDACTED] Mobile: [REDACTED]		
Nationality: SINGAPORE CITIZEN			Email: [REDACTED]		
Sex: Male	Age: 64	Date of Birth: 13/01/1958	Type of Informant: Owner of the SAF vehicle		
Race: Indian			Language: English		Institution / School Name:
Occupation: Defence Executive Officer			Driving Licence Information: Class: [REDACTED] Date of Expiry: [REDACTED]		

<b>General Information of the Accident</b>				
Type of Accident:	Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 10/04/2022 17:15	Type of Location: Gradient
Location: Gombak Dr				
Weather:		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of
34268MID	Operations Utility Vehicle	FORD	Everest	Green	Slightly Damaged	0
YP9599A	Delivery Tailgate Truck					0

Police Report Pt. 1



**SINGAPORE  
POLICE FORCE**



Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 4  
Report No. T/20220426/7027

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	ERIC POH	ID No.	NIL
Related Vehicle	YP9599A (Delivery Tailgate Truck)	Contact No.	NIL
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	10/04/2022	Date	10/04/2022
No. of Days granted Medical Leave	04	Degree of	Slight
<b>Owner of the SAF vehicle</b>			
Name	THANARAJOO RETHINAM	ID No.	819J
Related Vehicle	NIL	Contact No.	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry	Class: NIL Date of Expiry: NIL
Date	NIL	Date	NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL

**Brief Details.**

I, [REDACTED] 819J, DX9 Thanarajoo from 1 SAF TPT BN, LTC, wish to write this accident report on behalf of Gombak Base involving an Operations Utility Vehicle (OUV), plate number: 34286MID, belonging to my company LTC. The OUV was loaned to Gombak Base for self drive purpose.

On 10/04/2022 at about 1715hrs, a Singapore Food Industry (SFI) driver Mr Eric Poh drove his delivery tailgate vehicle, plate number: YP9599A, to deliver packet rations to Gombak Base personnel at Blk 319 Gombak Pass Office.

He stopped his delivery tailgate vehicle along a road behind Blk 319 Gombak Pass Office. After stopping the delivery tailgate vehicle near a stationary parked OUV (34286MID), he proceeded to deliver the rations to a building nearby.

While returning toward his delivery tailgate Vehicle, he noticed that it was slowly rolling down the slope towards the stationary parked OUV. He immediately ran towards the delivery tailgate vehicle in an attempt to stop the vehicle and was slightly injured in the process. But it was too late and the delivery tailgate vehicle had already grazed both doors on the left hand side of the OUV and hit the antenna bracket before coming to a halt. The damages sustained by the OUV includes scratches on both doors on the left hand side and bending of the left antenna bracket.

Police Report Pt. 2



**SINGAPORE  
POLICE FORCE**



T/20220426/7027

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 4

Report No. T/20220426/7027

CONTINUATION OF REPORT

Police Report Pt. 3



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000



T/20220426/7027

4 of 4

Report No. T/20220426/7027

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 26/04/2022 16:03
Officer In Charge Of Case: TP / TPB / TAN JEOK LENG Contact No.: 65476151	Classification Of Case:

NP168

Police Report Pt. 4

## FINAL COST OF REPAIR

(To be completed for only one type of item)

To:  CPT JOHN HO, S4/OC HQ, TPTBN1  <div style="border-bottom: 1px solid black; width: 100%; text-align: center;">1 TPT BN/ TPT HUB NORTH/ KRANJI NODE</div> <div style="text-align: center;">Unit</div>		From:  <div style="display: flex; justify-content: space-between;"> <div> <b>SHI ZHANGSONG</b>  <div style="border-bottom: 1px solid black; width: 100%;"></div>         Base/LEO Area Office       </div> <div style="font-size: 0.8em;">         Digitally signed by SHI ZHANGSONG          Date: 2022.07.25 15:01:24 +08'00'          9AMB/92FMD/MOS       </div> </div>	
Description of Item:		OPS UTILITY VEH FORD EVEREST FFR 0.7T	
Part/Reg No:	MID34266	Original Value:	\$66,635
Quantity:	01	CE/Non CE:	Non CE
Description of Damages and Costs of Repairs:		SAF 1222:	BB71(1TPTBN)/D/LTC/012/22
		Date:	10/4/2022
		SAF 1204/SAF 1351:	8202753033
		Date:	25.07.2022
		Workshop Job No:	8202753033
		Date:	05.05.2022
<u>MATERIAL COST</u>			
DESCRIPTION	Qty	Unit Price	Total Price
DOOR STICKER, REAR LH (UR93-50-8W4)	1	\$ 11.50	<b>\$11.50</b>
REAR BUMPER (B7A10242A)	1	\$ 950.00	<b>\$950.00</b>
REAR ANTENNA MOUNTING LH (B7A10188A)	1	\$ 200.00	<b>\$200.00</b>
REAR CORNER GARNISH LH (UBYK-50-241B)	1	\$ 59.52	<b>\$59.52</b>
DOOR, REAR LH (UA6G-73-020D)	1	\$ 620.00	<b>\$620.00</b>
REAR CORNER GARNISH RH (UBYK-50-231B)	1	\$ 91.94	<b>\$91.94</b>
P3 GREEN PAINT	2	\$ 26.00	<b>\$52.00</b>
<u>LABOUR COST</u>			
		Rate	<b>\$79.81</b>
LH REAR DOOR DAMAGED	12		<b>\$957.72</b>
REAR BUMPER DAMAGED	12		<b>\$957.72</b>
BODY, UNDERCARRIAGE NEAR CROSSMEMBER, BUMPER MOUNTING PORTION DENTED	4		<b>\$319.24</b>
SPRAY PAINT ON ALL ABOVE ACCIDENT REPAIRED AREA	6		<b>\$478.86</b>
<u>Assessment Fee</u>			
DF-Equip charged under basic		\$ 638.47	<b>\$638.47</b>
<u>General Services</u>			
Tow Svc Wheeled (< 3 Ton)	2	\$ 132.62	<b>\$265.24</b>
<b>Base/LEO Area Office's Assessment of Damages</b>			
Labour Charges @	\$79.81	per hour x 34	hrs = \$2,713.54
		per hour x	hrs =
Total Cost of Parts / Materials Used		=	\$1,984.96
Sub-contractor		=	
Assessment Fee		=	\$638.47
Towing Service		=	\$265.24
7% GST			N/A
Grand Total			<b>\$5,602.21</b>
Estimated Time for Repair:		25 day	

\*Delete whichever is not applicable