## ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3 #01-80 SINGAPORE 159723 TEL:62715133: 62717433 FAX:62745715

ESTIMATE REPAIR

China Taiping Insurance (Singapore) Pte Ltd

Date: 23.5.2022

Owner's Name: Tan Qiu Yan

Vehicle No: SNA3090Z

Vehicle Make & Model : Mercedes Benz C180

Registration Date: 17 Jun 2021 (YOM 2021) COE Expiry Date 16 Jun 2031

Claim Type: Third Party Claim

Chassis No: W1K2050762R635441

Pg1

DOA: 3.5.2022

0	As the same		Description	LI FREE		Unit		List (\$)	white of any state of the state of
The second second	R BOOT	×	R			1	\$		2,895.00
			TH MOULDING	X	NN	1	\$		1,833.40
+	-								
-									
							-		
_									
+					AND DESCRIPTION OF STREET CAPTURE				
+									
							+-		
-									
+									
							-		
-									
							-		
						Total (A	): \$		4,728.4
	Less 10%							945.6	

Total: \$

3,782.72

## ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3 #01-80 SINGAPORE 159723 IEL:62715133: 62717433 FAX:62745715

## ESTIMATE REPAIR

China Taiping Insurance (Singapore) Pte Ltd

Date: 23.5.2022

Owner's Name: Tan Qiu Yan

Vehicle No: SNA3090Z

Vehicle Make & Model: Mercedes Benz C180

Registration Date: 17 Jun 2021 (YOM 2021) COE Expiry Date 16 Jun 2031

Claim Type: Third Party Claim

Chassis No: W1K2050762R635441

Pg2

DOA: 3.5.2022

lo	Description	Unit	N P	List (\$	)	
	Special Nett					
1	CAR PLATE NUMBER WITH HOLDER X NN	SET	\$			50.00
_	REAR WINDSCREEN SEALANT Y NN	1	\$		_	80.00
	Labour	1	\$	250		300.00
_	Spray Painting to All Affected Areas	1	\$			600.0
2	Labour Remove / Refix Accident Damages parts to knock, jack, cut weld and realign accident affected area			100		
3	To Remove/Replace Rear Windscreen	1	\$		Ϋ́	150.0
4	Anti Rust Treatment	1	\$		X	100.0
	Sten (LKK) M 30/5/72, 1900c	PIP		P/P = (	350	
	A	JA C	1			
-		2 4/5				
+			_			
+						
		Total (B):	¢			1,280.0